


Quality Leadership System

## **CRAIOVA Plant** \*BX726 WINDOW WASHER PUMP wo CAL

Generated: 04:31:57 13 May 2025 **Printed:** 04:47:12 13 May 2025

By: RAZVAN CIRJU



	CY		Month					Week Starting					Day							
Actual Unit Concern /1000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sample Size	165545	50705	13621	9955	10749	14285	11078	4708	3508	3732	2761	1764	3969	699	655	776	769	762	362	604
Actual Unit Concern /1000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
FTT Not-OK Units Count	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
First Run %	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100
Actual Unit Concern Count	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Undefined Unit Concern /1000	0	1.005	0	0	0	0	0	10.83	0	0	0	0	0.503	70.1	1.526	0	0	1.312	0	67.88

	Actual Unit Concern,/1000											
CY	Month		Week Starting		Day							
			30 6 13 27	4 11	6 7 8 9	10 <b>12</b>						
2024 2025	Dec Jan Feb Mar	Apr May	Mar Apr Apr Apr	May May	May May May May	May <b>May</b>						

Pareto Population Percent