


Quality Leadership System

CRAIOVA Plant *V769 TAIL LAMP CONDENSATION

Generated : 04:28:51 13 May 2025 **Printed :** 05:04:41 13 May 2025

By: RAZVAN CIRJU

G_S



		CY			Мо	nth					Week S	Starting					D	ay		1
Actual Unit Concern /1000	0.012	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sample Size	82693	33649	6991	7153	8643	9113	6551	2369	2064	2091	1738	1107	2002	334	371	390	391	393	115	303
Actual Unit Concern /1000	0.012	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
FTT Not-OK Units Count	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
First Run %	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100
Actual Unit Concern Count	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Undefined Unit Concern /1000	0	0.029	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

	Actual Unit Concern,/1000										
	CY	Month	Week Starting	Day							
			30 6 13 27 4 11	6 7 8 9 10	12						
	2024 2025	Dec Jan Feb Mar Apr May	Mar Apr Apr May May	May May May May May N	May						
TailLamp CONDENSATION	0.012 0	0 0 0 0 0	0 0 0 0 0	0 0 0 0 0	0						
RIGHT	0.012 0	0 0 0 0 0	0 0 0 0 0	0 0 0 0 0	0						

Pareto Population Percent 0%