


Quality Leadership System

CRAIOVA Plant *BX726 TIRE BALANCE - OUT OF BALANCE

Generated : 04:41:51 13 May 2025 **Printed :** 04:56:15 13 May 2025

By: RAZVAN CIRJU



	C	Υ	Month					Week Starting					Day							
Actual Unit Concern /1000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sample Size	165545	50710	13621	9955	10749	14285	11078	4713	3508	3732	2761	1764	3969	704	655	776	769	762	362	609
Actual Unit Concern /1000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
FTT Not-OK Units Count	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
First Run %	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100
Actual Unit Concern Count	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Undefined Unit Concern /1000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

	Actual Unit Concern,/1000											
CY	Month		Week Starting		Day							
			30 6 13 27	4 11	6 7 8 9	10 12						
2024 2025	Dec Jan Feb Mar	Apr May	Mar Apr Apr Apr	May May	May May May May	May May						

Pareto Population Percent 0%