


Quality Leadership System

## **CRAIOVA Plant** \*BX726 SEAT BELT BUCKLE DEFECTIVE wo CAL


Generated: 04:34:31 13 May 2025 **Printed:** 04:47:56 13 May 2025

By: RAZVAN CIRJU



021P2190.CON

021P0069.TEM



		CY	Month					Week Starting					Day							
Actual Unit Concern /1000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sample Size	165545	50707	13621	9955	10749	14285	11078	4710	3508	3732	2761	1764	3969	701	655	776	769	762	362	606
Actual Unit Concern /1000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
FTT Not-OK Units Count	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
First Run %	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100
Actual Unit Concern Count	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Undefined Unit Concern /1000	0	1.025	0	0	0	0	0	11.04	0	0	0	0	0.755	69.9	1.526	1.288	0	1.312	0	67.65

	Actual Unit Concern,/1000											
CY		Month			Week Starting		Day					
				30 6	13 27	4 11	6 7	8 9	10 <b>12</b>			
2024 2025	Dec Jan	Feb Mar	Apr May	Mar Apr	Apr Apr	May May	May May	May May	May May			

Pareto Population Percent

0%