


Quality Leadership System

ty
dership
\*BX726 AIR DEFLECTOR

**Generated:** 04:13:31 13 May 2025 **Printed:** 04:47:40 13 May 2025

By: RAZVAN CIRJU

## BX726 AIR DEFLECTOR PIP: CAL BUY OFF 021P2033.CON 021P0078.TEM



	Model Year Month								Week Starting							Day							
Actual Unit Concern /1000	0.102	0.643	1.101	0.2	0.651	0.49	0.722	0.212	0.855	1.071	0.362	0	0.252	0	0	0	1.288	0	0	0	0		
Sample Size	97781	118118	13621	9955	10749	14285	11078	4700	3508	3732	2761	1764	3969	691	643	655	776	769	762	362	596		
Actual Unit Concern Count	10	76	15	2	7	7	8	1	3	4	1	0	1	0	0	0	1	0	0	0	0		
FTT Not-OK Units Count	10	75	15	2	6	7	8	1	3	4	1	0	1	0	0	0	1	0	0	0	0		
FTT %	99.99	99.94	99.89	99.98	99.94	99.95	99.93	99.98	99.91	99.89	99.96	100	99.97	100	100	100	99.87	100	100	100	100		
Undefined Unit Concern Count	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
Actual Unit Concern /1000	0.102	0.643	1.101	0.2	0.651	0.49	0.722	0.212	0.855	1.071	0.362	0	0.252	0	0	0	1.288	0	0	0	0		

								Actual I Init	Concern,/1000									——
	Model Year	Month						/totaai Oilii	Day									
			Ī			1		30 6	Week Startin 13 27	4	11	5	6	7	8	9	10	12
TOP 20	2024 2025	Dec	Jan	Feb	Mar	Apr	May	Mar Apr	Apr Apı	· May	May	May	May	May	May	May	May	May
AirDeflector LOOSE	0.01 0.11	0.073	0.1	0.093	0.07	0.722	0.212	0.855 1.07	0.362 0	0.252	0	0	0	1.288	0	0	0	0
AirDeflector NOT SEATED	0.092 0.46	0.734	0.1	0.558	0.35	0	0	0 0	0 0	0	0	0	0	0	0	0	0	0
AirDeflector IMPROPER ASSEMBLY	0 0.00	0	0	0	0.07	0	0	0 0	0 0	0	0	0	0	0	0	0	0	0
AirDeflector DAMAGED	0 0.02	0.22	0	0	0	0	0	0 0	0 0	0	0	0	0	0	0	0	0	0
AirDeflector LEAK	0 0.00	0.073	0	0	0	0	0	0 0	0 0	0	0	0	0	0	0	0	0	0
AirDeflector IMPROPER ALIGNMENT	0 0.01	0	0	0	0	0	0	0 0	0 0	0	0	0	0	0	0	0	0	0

Pareto Population Percent 100%

	Actual Unit Concern,/1000																			
	Mode	el Year	Month								Week Starting			Day						
							į		30	6	13 27	4	11	5	6 7	8	9	10	12	
TOP 20	2024	2025	Dec	Jan	Feb	Mar	Apr	May	Mar	Apr	Apr Apr	May	May	May	May May	May	May	May	May	
AirDeflector LOOSE	0.01	0.118	0.073	0.1	0.093	0.07	0.722	0.212	0.855	1.071	0.362 0	0.252	0	0	0 1.288	0	0	0	0	
AirDeflector NOT SEATED	0.092	0.465	0.734	0.1	0.558	0.35	0	0	0	0	0 0	0	0	0	0 0	0	0	0	0	
AirDeflector IMPROPER ASSEMBLY	0	0.008	0	0	0	0.07	0	0	0	0	0 0	0	0	0	0 0	0	0	0	0	
AirDeflector DAMAGED	0	0.025	0.22	0	0	0	0	0	0	0	0 0	0	0	0	0 0	0	0	0	0	
AirDeflector LEAK	0	0.008	0.073	0	0	0	0	0	0	0	0 0	0	0	0	0 0	0	0	0	0	
AirDeflector IMPROPER ALIGNMENT	0	0.016	0	0	0	0	0	0	0	0	0 0	0	0	0	0 0	0	0	0	0	