


Quality CRAIOVA Plant
Leadership \*V769 LIFT GATE LIFT ASSEMBLY

q<sub>s</sub>

Generated: 04:30:23 13 May 2025
Printed: 05:05:45 13 May 2025
By: RAZVAN CIRJU



		CY	Month						Week Starting						Day					
Actual Unit Concern /1000	0.036	0.029	0	0.139	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sample Size	82693	33649	6991	7153	8643	9113	6551	2369	2064	2091	1738	1107	2002	334	371	390	391	393	115	303
Actual Unit Concern /1000	0.036	0.029	0	0.139	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
FTT Not-OK Units Count	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
First Run %	100	100	100	99.99	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100
Actual Unit Concern Count	3	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Undefined Unit Concern /1000	0	0.029	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

	Actual Unit Concern./1000															
	C	Υ	Month								Starting					
										6 13	27	4 11	6 7	8	9 10	12
	2024	2025	Dec	Jan	Feb	Mar	Apr	May	Mar	Apr Apr	Apr	May May	May May	May	May May	May
LiftGateLiftAsmbly POPS	0	0.029	0	0.139	0	0	0	0	0	0 0	0	0 0	0 0	0	0 0	0
BOTH LR	0	0.029	0	0.139	0	0	0	0	0	0 0	0	0 0	0 0	0	0 0	0
LiftGateLiftAsmbly NOISY	0.024	0	0	0	0	0	0	0	0	0 0	0	0 0	0 0	0	0 0	0
LEFT REAR	0.024	0	0	0	0	0	0	0	0	0 0	0	0 0	0 0	0	0 0	0
LiftGateLiftAsmbly IMPROPER FUNCTION	0.012	0	0	0	0	0	0	0	0	0 0	0	0 0	0 0	0	0 0	0
ALL	0.012	0	0	0	0	0	0	0	0	0 0	0	0 0	0 0	0	0 0	0

Pareto Population Percent 0%