


Quality **CRAIOVA Plant** Leadership *V769 WINDSHIELD System

G_S Generated: 04:29:15 13 May 2025 **Printed:** 05:05:02 13 May 2025

By: RAZVAN CIRJU



	CY		Month					Week Starting					Day							
Actual Unit Concern /1000	3.918	3.298	1.43	7.689	6.363	2.304	0.61	0.422	0	0.956	0	0.903	0.499	0	2.695	0	0	0	0	0
Sample Size	82693	33649	6991	7153	8643	9113	6551	2369	2064	2091	1738	1107	2002	334	371	390	391	393	115	303
Actual Unit Concern /1000	3.918	3.298	1.43	7.689	6.363	2.304	0.61	0.422	0	0.956	0	0.903	0.499	0	2.695	0	0	0	0	0
FTT Not-OK Units Count	237	93	9	38	54	21	4	1	0	2	0	1	1	0	1	0	0	0	0	0
First Run %	99.64	99.67	99.86	99.25	99.36	99.77	99.94	99.96	100	99.9	100	99.91	99.95	100	99.73	100	100	100	100	100
Actual Unit Concern Count	324	111	10	55	55	21	4	1	0	2	0	1	1	0	1	0	0	0	0	0
Undefined Unit Concern /1000	0	0.029	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

	CV			Actual Unit Concern,/1000												
	CY	Mo	nth	Week Starting	Day											
				30 6 13 27 4 11	6 7 8 9 10	12										
29	2024 2025	Dec Jan Feb	Mar Apr May	Mar Apr Apr May May	May May May May May	May										
Windshield LEAK - WATER 3.	3.918 3.298	1.43 7.689 6.363	2.304 0.61 0.422	0 0.956 0 0.903 0.499 0	2.695 0 0 0 0	0										
A1 1.	1.947 0.505	0.143 1.677 0.925	0.219 0 0.422	0 0 0 0 0.499 0	2.695 0 0 0 0	0										

Pareto Population Percent