


Quality Leadership System

**CRAIOVA Plant** \*BX726 LIFT GATE HANDLE **Generated:** 04:03:52 13 May 2025 Printed: 04:46:11 13 May 2025

By: RAZVAN CIRJU



	C	Υ	Month					Week Starting				Day								
Actual Unit Concern /1000	0.012	0.019	0	0.1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sample Size	165545	50697	13621	9955	10749	14285	11078	4700	3508	3732	2761	1764	3969	691	655	776	769	762	362	596
Actual Unit Concern /1000	0.012	0.019	0	0.1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
FTT Not-OK Units Count	2	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
First Run %	100	100	100	99.99	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100
Actual Unit Concern Count	2	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Undefined Unit Concern /1000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

	Actual Unit Concern,/1000											
	CY	Month	Week Starting	Day								
			30 6 13 27 4 11	6 7 8 9 10	12							
	2024 2025	Dec Jan Feb Mar Apr M	ay Mar Apr Apr Apr May May	May May May May May	May							
LiftGateHandle LOOSE	0.012 0.019	0 0.1 0 0 0	0 0 0 0 0 0	0 0 0 0 0	0							

Pareto Population Percent 0%