


Quality Leadership System

CRAIOVA Plant *BX726 LIFT GATE TRIM PANEL

Generated: 04:19:35 13 May 2025 Printed: 04:49:32 13 May 2025

By: RAZVAN CIRJU



	CY		Month					Week Starting				Day								
Actual Unit Concern /1000	0.253	0.138	0.146	0.1	0.372	0.14	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sample Size	165545	50697	13621	9955	10749	14285	11078	4700	3508	3732	2761	1764	3969	691	655	776	769	762	362	596
Actual Unit Concern /1000	0.253	0.138	0.146	0.1	0.372	0.14	0	0	0	0	0	0	0	0	0	0	0	0	0	0
FTT Not-OK Units Count	18	4	0	1	2	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
First Run %	99.98	99.99	99.99	99.99	99.96	99.99	100	100	100	100	100	100	100	100	100	100	100	100	100	100
Actual Unit Concern Count	42	7	2	1	4	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Undefined Unit Concern /1000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

	Actual Unit Concern,/1000												
	CY	Month		Wee	k Starting	Day							
				30 6 13	27 4 11	6 7 8 9	10 12						
	2024 2025	Dec Jan Feb Mar	Apr May	Mar Apr Apr	Apr May May	May May May May I	May May						
LiftGatePanel RATTLES	0.253 0.138	0.146 0.1 0.372 0.14	0 0	0 0 0	0 0 0	0 0 0 0	0 0						

Pareto Population Percent 0%