Date 26 / 1 / 26 Loco No. R1004 Cab No 1 Facing Andoom Shift Driver/s Glen Ross (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 1
Loco Comp Oil: (OK) Not OK Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car N		Comp Car J	Comp Car P		Comp Car O	Comp Car K		Comp Car M	Radiator Water added(mm s/glass)
Rake 1 0550	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 2 0810	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 3 0340	Comp Hrs	34967	15465	15373	32753		7156		17282	Loco Hrs 22598
	Next Service	35000	15500	16000	33500		7601		18137	Cab Cleaned COVID
Locomotive 0355	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	Running in Auto / ~~Manual~~ Not Running		~~Running in Auto / Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	Loco Km's Travelled 458748
Fuel added to comp cars / Loco	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	2650 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0346		0425	0535			3		
2	0610		0645	0737			1		MC RR.
3	0812		0840	0933			2		MC JS.
4	1008		1035	1128			3		MC JS.
5	1203		1236	1326			1		
6	1402		1449	1513			2	Fuel loco 2650L	
7	1549						3		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Fuelled loco 7. 1005 Litres		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 26/1/26 Loco No. 5 Cab No 1 Facing Andoom Shift Driver/s Steve/Pete Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 / Rake 2 / Rake 3
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken

			Rake1		Rake2		Rake3		Locomotive
			Lead	2nd	Lead	2nd	Lead	2nd	
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Radiator Water added(mm s/glass) Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs
		Next Service							Cab Cleaned COVID
Locomotive			Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	1502 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1549		1625	1657			3		
2	1832		1905	1848			1	MC R3	RR
3	1923		1955	2037			2		SH
4	2112		2142	2220			3		SH
5	2255		2342	0007			1		
6	0042		0119	0247			2		
7	0322						3	Andoom Slow fuelled loco 1502 Ltrs	
8							1		
9							2		
10							3		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....