Date 22 6 26 Loco No. R007 Cab No 2 Facing Andoom Shift Driver/s Pete/Steve Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	OK Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3

Loco Comp Oil	OK	Not OK	Topped Up

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(min a/glass)
Rake 1	Engine Oil: Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Comp Oil: Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Hrs									Loco Hrs
	Next Service									Cab Cleaned COVID
Locomotive	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Litre

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1445		1605	1607	Y		3		
2	1642		1732	1739	N		1	m/c	PH BF
3	1815		1850	1900	N		2	m/c	PH BF
4	1935		2010	2016	N		3	m/c	PH BF
5	2050		2126	2136	N		1		
6	2210		2245	2347	N		2		
7	0022		0100	0103	N		3		
8	0138		—	0220	N		1		
9	0255		0325	0330			2		
10	0411						3	slow dumping	
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....