Date 7/5/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Glen Rob Day / Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 5 Rake 2 0 Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car J	Comp Car O		Comp Car P	Comp Car N		Comp Car K	Comp Car T		Radiator Water added(mm s/glass)

Record time comp car/loco hrs taken			Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 1	0340	Engine Oil							
Rake 2	0520	Comp Oil							
Rake 3	0740	Comp Hrs	16192	32952	16322	35697	8059	10849	Loco Hrs 24413
		Next Service	16500	33500	17057	36052	8100	11000	Cab Cleaned COVID
Locomotive	0355		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ ~~Not Running~~	Loco Km's Travelled 49263
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	1500 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0338		0420	0500			1		
2	0535		0605	0705			2		MC RR
3	0740		0810	0900			3		MC RR
4	0935		1005	1058			1		
5	1153		1216	1325			2		
6	1401		1442	1539			3	Fuel loco 1500L	
7	1615						1		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 17/5/26 Loco No. 5 Cab No 2 Facing Andoom Shift Driver/s Nev / Adam Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil (OK) Not OK Topped Up

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3										Loco Hrs 24426
										Cab Cleaned COVID
Locomotive 1635	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 492298
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1700 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1615		1658	1737	N		1	MCR1	RR
2	1812		1852	1938	N		2	RK3 Not working comp I not in R2	
3	2013		2050	2158	N		3	Dump R3	
4	2233		2313	0014	N		1		
5	0049		0121	0229	N		2		
6	0304						3	1700L Fuel	
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
1820	R3 Manual Dump FOR m Dump Comp I in Transit		
2200	R3 Manual Load AtDoom		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....