Date 20/2/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s ROB GLEN Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	OK Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car J	Comp Car K		Comp Car P	Comp Car O		Comp Car T	Comp Car M		Radiator Water added(mm s/glass)
Rake 1 0400	Engine Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0550	Comp Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 0835	Comp Hrs 15513	7401		15711	32817		10241	17437		Loco Hrs 29999
	Next Service 16500	8100		16000	33500		11000	18137		Cab Cleaned COVID
Locomotive 0415	Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		Running in Auto / Manual ~~Not Running~~	Running in Auto / Manual ~~Not Running~~		Loco Km's Travelled 469893
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0410	0420	~~0445~~	0525			1		MC SM TL
2	0600		0735	0758			2		MC SM RR
3	0833	1055	1120	1230			3	tailings. Flush Shunt R3	MC AM CW
4	1305		1333	1412			1		
5	1448		1527	1600			2	Fuel loco 1100 L	
6	1636						3		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 20/2/26 Loco No. 5 Cab No 1 Facing Andoom Shift Driver/s Nev / Gary Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up ↓100	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3										Loco Hrs 23018
										Cab Cleaned COVID
Locomotive 2330	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 470227
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1893 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1636		1709	1748	NO		3		
2	1823		1858	1944	NO		1	M/C R1	
3	2019	2029	2101	2127	NO		2	R2	
4	2203		2240	2349	NO		3	R3	
5	0022		0055	0145	NO		1		
6	0218		0304	0320	NO		2	Fuel loco	
7	0353								
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....