Date 07/2/26 Loco No. 2005 Cab No. 2 Facing Andoom Shift Drivers ADAM - TRUDI Day / Night Shift

The following checks are to be performed at shift handover or close as practical

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| Yes / No | Ok / Not OK / Topped up | OK / Not Ok / Topped Up | Rake 1 Y / N Rake 2 Y / N Rake 3 Y / N | Rake 1 0 Rake 2 0 Rake 3 0 |
| Loco Comp Oil | OK / Not OK / Topped Up | | | |

| Record time comp car/loco hrs taken | | | Lead | Rake1 | 2nd | Lead | Rake2 | 2nd | Lead | Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Rake 1 | 0529 | Engine Oil | Comp Car J | | Comp Car K | Comp Car P | | Comp Car N | Comp Car | | Comp Car M | Radiator Water added(mm e/glass) |
| Rake 2 | 0713 | Comp Oil | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added |
| Rake 3 | 0845 | Comp Hrs | 15629 | | 7529 | 15926 | | 35097 | 10372 | | 17546 | Loco Hrs |
| | | Next Service | 16500 | | 8100 | 16000 | | 36000 | 11000 | | 18137 | Cab Cleaned (COVID) |
| Locomotive | 0944 | | Running In Auto / Manual Not Running | | Running In Auto / Manual Not Running | Running In Auto / Manual Not Running | | Running In Auto / Manual Not Running | Running In Auto / Manual Not Running | | Running In Auto / Manual Not Running | Loco Km's Travelled 474372 |
| Fuel added to comp cars / loco? | | | Ltr's | | Ltr's | Ltr's | | Ltr's | Ltr's | | Ltr's | 1700 Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0307 | | 0415 | 0445 | N | | 3 | | |
| 2 | 0520 | | 0600 | 0640 | N | | 1 | | AT |
| 3 | 0715 | | 0753 | 0832 | N | | 2 | | AT |
| 4 | 0907 | | 0945 | 1022 | N | | 3 | | AT |
| 5 | 1057 | | 1134 | 1213 | N | | 1 | | AT |
| 6 | 1247 | | 1319 | 1413 | N | | 2 | | |
| 7 | 1447 | | | | | | 3 | fuel loco | |
| 8 | | | | | | | 1 | | |
| 9 | | | | | | | 2 | | |
| 10 | | | | | | | 3 | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*