Date 12/7/26 Loco No. 7 Cab No 2 Facing Andoom Shift Driver/s Allen / Rob (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) (Not OK) Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car I	Comp Car N		Comp Car P	Comp Car K		Comp Car J	Comp Car M		Radiator Water added(mm s/glass)

Record time comp car/loco hrs taken			Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added 235
Rake 1	0715	Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2	0450	Comp Oil							
Rake 3	0605	Comp Hrs	11204	35824	16883	6262	16543	18337	Loco Hrs 7204
		Next Service	12000	36800	17057	9100	17500	19000	Cab Cleaned COVID
Locomotive	03401		~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ ~~Not Running~~	Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running	Loco Km's Travelled 51331
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	3578 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0321	0338	0405	0413			1		
2	0443		0525	0543			2		MC RR
3	0618		0655	0705			3		MC RR
4	0740		0815	0827			1		MC RR
5	0902		0935	0942			2		
6	1017	1030	1149	1150			3	Topped up oil Fuelled Loco 3578Ltrs.	
7	1226		1258	1321			1		
8	1357		1428	1449			2		
9	1525		1556				3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 12/7/26 Loco No. 5 Cab No 1 Facing Andoom Shift Driver/s Neu/Adam Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 3 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Radiator Water added(mm s/glass) / Amt Added
Rake 2		Comp Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Amt Added
Rake 3		Comp Hrs				Loco Hrs 25151
		Next Service				Cab Cleaned COVID
Locomotive	1610		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 507251
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	2300 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1525		1605	1625	N		3		
2	1700		1736	1806	N		1	M/C R1	
3	1841		1917	1931	N		2	R2	
4	2006		2039	2057	N		3	R3	
5	2132		2219	2220	N		1		
6	2255		2330	2340	N		2		
7	0015		0048	0100	N		3		
8	0135		0206	0220	N		1		
9	0255	300					2	2300L Fuel	
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....