Date 21/2/26 Loco No. 5 Cab No 1 Facing Andoom Shift Driver/s Glen/Rob (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car J	Comp Car K		Comp Car P	Comp Car O		Comp Car F	Comp Car M		Radiator Water added(mm s/glass)
Rake 1 0525	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0730	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 0350	15531	7406		15729	32817		10241	17448		Loco Hrs 23022
	16500	8100		16000	33500		11000	18137		Cab Cleaned COVID
Locomotive 0355	Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running In Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running In Auto / Manual~~ Not Running		~~Running In Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ ~~Not Running~~		Loco Km's Travelled 470325
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0353		0425	0508			3		
2	0543		0620	0708			1		ML RL
3	0743		0815	0852			2		MK RL
4	0927		1000	1100			3		MC RL
5	1135		1225	1307			1		
6	1343		1422	1525			2	Fuel loco 1000L	
7	1601						3		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Engine oil ~~low~~		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 21/2/26 Loco No. 5 Cab No 1 Facing Andoom Shift Driver/s Gary/Nev Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up 100	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1 / Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 / Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 / Comp Hrs										Loco Hrs
Next Service										Cab Cleaned COVID
Locomotive	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		935 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1601		~~1633~~	1612	NO		5		
2	1645		1920	2028	NO				
3	2101		2300	2316				Andoom down - Fuel loco	
4	2351		0024	0251					
5	0326								
6									
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....