Date 7/8/26 Loco No. 7 Cab No 2 Facing Andoom Shift Driver/s Adam / Ilter Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	OK Not OK Topped Up	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
1											

Record time comp car/loco hrs taken			Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Locomotive
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs
		Next Service							Cab Cleaned (COVID)
Locomotive	1646		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled 519131.6
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1607		1647	1659	N		2	MC R2	BR AK
2	1734		1820	1826	N		3		
3	1901		1941	1949	N		1		
4	2024		2101	2112	N		2		
5	2147		2225	2237	N		3		
6	2312		2347	0005	N		1		
7	0040		0114	0130	N		2	LP Down C1	
8	0205	0235	0312	0315	N		3		
9	0350						1		
10							2		
11							3		
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....