Date 8 / 6 / 26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s STEVE JBD Day ~~Night~~ Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓95	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up	Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive

Record time comp car/loco hrs taken			Comp Car J	Comp Car O	Comp Car P	Comp Car K	Comp Car M	Comp Car I	Radiator Water added(mm s/gless)
Rake 1	0826	Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2	1001	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	0533	Comp Hrs	16311	33101	16472	8120	18093	10985	Loco Hrs
		Next Service	16500	33500	17057	9100	19000	11000	Cab Cleaned COVID
Locomotive			Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running	Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual (Not Running)	Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	2300 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0355		0425	0500			1		SSM SK
2	0535		0605	0756			2		SSM SK
3	0830		0980	0937			3		SSM SK
4	1012		1044	1120	No		1		
5	1155		1222	1301	No		2		
6	1336		1415	1450	No		3		
7	1525						1		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....