Date 6.9.26 Loco No. 21007 Cab No 2 Facing Andoom Shift Driver/s Glen – Rob (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 Rake 3 0
Loco Comp Oil (OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1	0615.	Engine Oil	Comp Car P Amt Added / Comp Car J Amt Added	Comp Car O Amt Added / Comp Car K Amt Added	Comp Car I Amt Added / Comp Car M Amt Added	Radiator Water added(mm s/glass) Amt Added
Rake 2	[illegible]	Comp Oil	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added
Rake 3	0450	Comp Hrs	17311 / 17001	33783 / 8566	11528 / 18782	Loco Hrs 74482
		Next Service	18137 / 17500	34800 / 9100	12000 / 19000	Cab Cleaned COVID
Locomotive	0455		~~Running in Auto / Manual~~ Not Running / Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ ~~Not Running~~ / ~~Running in Auto / Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running / Running In Auto / ~~Manual~~ ~~Not Running~~	Loco Km's Travelled 528149
Fuel added to comp cars / Loco			Ltr's / Ltr's	Ltr's / Ltr's	Ltr's / Ltr's	901 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0445		0520	0556.			3		
2	0632		0705	0737			1	Loco 5 Enelled 901 Litres	MK RR
3	0812		0845	0858			2		MK RR
4	0933		1005	1023			3		MK RR
5	1058		1153	1154	Y		1	AC Fault	
6	1230		1313				2		
7							3		
8							1		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 6/9/26 Loco No. 7 Cab No 2 Facing Andoom Shift Driver/s Nev / Adam Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 / Rake 2 / Rake 3
Loco Comp Oil 7	OK Not OK Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Comp Car	Comp Car / Comp Car	Comp Car / Comp Car	Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added
Rake 3		Comp Hrs				Amt Added
		Next Service				Loco Hrs
Locomotive	1840		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Cab Cleaned COVID
Fuel added to comp cars / Loco			Ltr's / Ltr's	Ltr's / Ltr's	Ltr's / Ltr's	Loco Km's Travelled 528569.4
						1600 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1230		1313				2		
2	1715		1755	1757	Y		3		
3	1832		1912	1925	N		1	M/c R3	
4	2000		2041	2047	N		2	R1	
5	2123		2158	2225	N		3	R2	
6	2300		2339	2352	N		1		
7	0027		0118	0137	N		2		
8	0212		0259	0305	N		3		
9	0340						3	1600L FUEL	
10							1		
11							2		
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....