Date 7/5/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Glenn / Rob / Molly Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 Rake 3 6
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0525	Engine Oil	Comp Car J	Comp Car O		Comp Car P	Comp Car N		Comp Car K	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	0715	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0400	Comp Hrs	16047	32936		16264	35600		7955	17978		Amt Added
		Next Service	16500	33500		17057	36052		8100	18137		Loco Hrs 24198
Locomotive	0420		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		Cab Cleaned COVID
Fuel added to comp cars / Loco			273 Ltr's	Ltr's		209 Ltr's	Ltr's		95 Ltr's	172 Ltr's		Loco Km's Travelled 488515
												1250 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0403		0445	0527			3		
2	0603		0640	0734	No.		1	Fuelled Comp J	MC RR
3	0809		0845	0937	No.		2	fuelled Comp P	MC RR
4	1012		1050	1137			3	fuelled comps K + M	MC RR
5	1212		1302	1335			1		
6	1411						2	Fuel loco 1250L Andoom Down	
7							3		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 7/5/26 Loco No. 5 Cab No 2 Facing Andoom Shift Driver/s New / Adam Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Amt Added
Rake 3		Comp Hrs	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Amt Added
		Next Service				Loco Hrs 24216
Locomotive	2000		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Cab Cleaned COVID
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Loco Km's Travelled 488830
						1400 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1411	1600	1633	1717	N		2		
2	1752		1830	1920	N		3		
3	1955		2032	2120	N		1	M/C	
4	2155		2245	0021	N		2	"	
5	0056		0136	0219	N		3	"	
6	0254						1	1400L FUEL	
7							2		
8							3		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....