Date 01/8/27 Loco No. R005 Cab No | Facing Andoom Shift Driver/s Ted Steve (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up 80 ↓	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil: (OK) Not OK Topped Up

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
	Comp Car I	Comp Car N		Comp Car P	Comp Car K		Comp Car J	Comp Car M		Radiator Water added(mm s/gless)
Rake 1 0551 / Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0728 / Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 0850 / Comp Hrs	11349	35984		17118	8340		16718	18481		Loco Hrs 25511
Next Service	12000	36800		17057	9100		17500	19000		Cab Cleaned COVID
Locomotive 0559	(Running in Auto / Manual) Not Running	Running in Auto / Manual (Not Running)		(Running in Auto / Manual) Not Running	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	(Running in Auto / Manual) Not Running		Loco Km's Travelled 516066
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1525 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0433		0505	0523	No		3		
2	0558		0630	0655	No		1		✓
3	0730		0802	0818	No		2		✓
4	0853		0921	0939	No		3		✓
5	1014		1045	1100	No		1		
6	1135		1204	1220	N.		2		
7	1255		1334	1358			3	REFUEL. LOCO.	
8	1413		1443	1458			1		
9	1533						2		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 1/8/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s ROB GLEN ~~Day~~ Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Amt Added	Amt Added	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Amt Added	Amt Added	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3			Comp Hrs							Loco Hrs 25521
			Next Service							Cab Cleaned COVID
Locomotive 1547	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 516341
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1533		1612	1617			2	inc R2	RB GR
2	1653		1725	1734			3	inc R3	RB GR
3	1810		1843	1859			1	inc R1	RB GM
4	1935		2004	2018			2		
5	2054		2124	2135			3		
6	2214		2340	2302			1		
7	2327		0005	0018			2		
8	0053	0055	0120	0138			3		
9	0213		0243	0305			1		
10	0340						2		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....