Date 15/2/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s Jed Pete Steve Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational			Rake Leakage Check kPa		
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up		Rake 1 Y N	Rake 2 Y N	Rake 3 Y N	Rake 1	Rake 2	Rake 3

Loco Comp Oil	OK Not OK Topped Up	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive

Record time comp car/loco hrs taken			Comp Car J	Comp Car K	Comp Car P	Comp Car O	Comp Car I	Comp Car M	Radiator Water added(mm s/glass)
Rake 1	1245	Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2	0824	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	1000	Comp Hrs	15500	7345	15648	32800	15648	32800	Loco Hrs 22885
		Next Service	16500	8100	16000	33500	16000	33500	Cab Cleaned COVID
Locomotive	1045		~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / ~~Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running	Loco Km's Travelled 468106
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	1763 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0428		0458	0600	No		3	M/C	PH
2	0635		0707	0744	No		1	M/C	PH
3	0819		0900	0925	No		2	M/C	PH
4	1000		1040	1125	N		3		
5	1200		1235	1318	N		1	LOCO FUEL 1763L	
6	1352		1443	1538	N		2		
7	1613						1		
8							2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....