Date 18.5.26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s GLEN - ROB (Day) Night Shift

The following checks are to be performed at shift handover/or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 2 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car V	Comp Car O		Comp Car P	Comp Car N		Comp Car K	Comp Car I		Radiator Water added(mm e/glass)
Rake 1 0510	Engine Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added 70 Gal
Rake 2 0720	Comp Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 0840	Comp Hrs 16210	32952		16340	35697		8059	10862		Loco Hrs 24437
	Next Service 16500	33000		17057	36052		8100	11000		Cab Cleaned COVID
Locomotive 6345	Running In Auto / ~~Manual~~ ~~Not Running~~	~~Running In Auto / Manual~~ Not Running		Running In Auto / ~~Manual~~ ~~Not Running~~	~~Running In Auto / Manual~~ Not Running		~~Running In Auto / Manual~~ Not Running	Running In Auto / ~~Manual~~ ~~Not Running~~		Loco Km's Travelled 492494
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1405 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0304		0410	0435			3	MC	RR CW
2	0510		0545	0634			1	MC	RR
3	0710		0809	0842			2	MC	RR.
4	0918		0958	1053			3		
5	1129		1229	1252			1		
6	1328		1432	1458			2	Fuel & Eng oil loco	
7	1534						3		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.

Date 18/5/26 Loco No. 5 Cab No 2 Facing Andoom Shift Driver/s Steve/Pete/Jed, Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Amt Added	Comp Car / Amt Added		Comp Car / Amt Added	Comp Car / Amt Added		Comp Car / Amt Added	Comp Car / Amt Added		Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Loco Hrs
		Next Service										Cab Cleaned COVID
Locomotive			Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1534		1620	1706			3	MCRJ	RA. SJW SJW
2	1741		1815	1906			1		
3	1941		2015	2116			2		
4	2151		2230	2305	No		3		
5	2340		0009	0147	No		1		
6	0222		0250	0334	No		2		
7	0409						3		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....