Date 16.9.26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Pete/Steve/Jed (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0945	Engine Oil	Comp Car P	Comp Car J		Comp Car O	Comp Car K		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	0615	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0737	Comp Hrs	17357	17121		[illegible]	[illegible]		[illegible]	18547		Amt Added
		Next Service	18137	17500		[illegible]	9100		120[illegible]	19000		Loco Hrs
Locomotive	1055		~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Cab Cleaned COVID
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Loco Km's Travelled 533555
												2600 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0320		0403	0407	N		3		
2	0453		0540		N		1	m/c	PA SL
3	0615		0635	0704	N		2	m/c	PA SL
4	0753		0[illegible]	0[illegible]	N		3	m/c	PA SL
5	0900		0940	1005	N		1		
6	1040		1120	1128	No		2	Loco fuel 1500L	
7	1203		1245	1255	No		3		
8	1330		1403	1420	No		1	Loco fuel 1500L	
9	1455		1530	1549	No		2		
10	1624						3		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 16/9/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Glen Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational			Rake Leakage Check kPa		
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N	Rake 2 (Y) N	Rake 3 (Y) N	Rake 1	Rake 2	Rake 3
Loco Comp Oil	(OK) Not OK Topped Up								0

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Radiator Water added(mm s/glass) Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Loco Hrs 7585
		Next Service										Cab Cleaned COVID
Locomotive	1630		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 533715
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1624		1700	1715			3		
2	1750		1825	1839			1		
3	1914		1945	2003			2		
4	2038	2115	2145	2145			3	Meal Break.	
5	2220		2245	2340			1		
6	0015		0045	0102			2		
7	0137		0205	0223			3		
8	0303						1		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....