Date 6 / 4 / 26 Loco No. R1007 Cab No | Facing Andoom Shift Driver/s GARY - NEV Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up ✓	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken										
Rake 1	Engine Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added		Comp Car / Amt Added	Comp Car / Amt Added		Radiator Water added(mm s/glass)
Rake 2	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Hrs	Amt Added	Amt Added	Amt Added	Amt Added		Amt Added	Amt Added		Loco Hrs
	Next Service									Cab Cleaned COVID
Locomotive		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco		Ltr's	Ltr's	Ltr's	Ltr's		Ltr's	Ltr's		4000 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1535		1608	1721	NO		3	red over white 21 switch	
2	1754		1826	1936	NO		1		
3	2009		2040	2149	NO		2		
4	2222		2255	0003	NO		3		
5	0036		0114	0230	NO		1		
6	0305						2		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....