Date 12/3/26 Loco No. 2005 Cab No 2 Facing Andoom Shift Driver/s Allen / Rob (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil: (OK) Not OK Topped Up				

	Record time comp car/loco hrs taken		Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	1444	Engine Oil	Comp Car J	Comp Car K		Comp Car P	Comp Car N		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	0510	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	1245.	Comp Hrs	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
		Next Service	15650	7599		15926	35174		10415	17588		Loco Hrs 3362
Locomotive	0340.		16500	8100		16000	36000		11000	18137		Cab Cleaned COVID
			Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		~~Running in Auto / Manual~~ Not Running	~~Running in Auto / Manual~~ ~~Not Running~~ RA		Loco Km's Travelled 476398
Fuel added to comp cars / Loco			61 Ltr's	133 Ltr's		Ltr's	269 Ltr's		119 Ltr's	121 Ltr's		2055 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0320	0340.	0405	0455			1		
2	0530	0540	0605	1214			2	Fuelled Comp N.	MC RR
3	1249		1338	1439.			3	Fuelled Comps I + M	MC RR
4	1515						1	" of J & K.	MC RR GM
5							2		
6							3		
7							1		
8							2		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Repair "O" Ring comp I R3.		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 12/3/26 Loco No. 5 Cab No 2 Facing Andoom Shift Driver/s Nev / Gary Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓60	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 ○ Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Amt Added
Rake 3		Comp Hrs				Amt Added
		Next Service				Loco Hrs 23375
Locomotive	1615		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Cab Cleaned COVID
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Loco Km's Travelled 476535
						1500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1515	1550	1613	1706	N		1	MC R1	RR ~~~~
2	1741		1819	1920	N		2	R2	~~~~ GH
3	1955		2028	2148	N		3	R3	~~~~ GH
4	2223		2255	~~00~~ 50	NO		1		
5	0023		0200	0300	NO		2	Fuel loco	
6	0333								
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....