
Metro incidents and service disruptions

A primary-source record of flooding, derailment, signalling faults, fires and earthquake disruptions, with unresolved counts and dates left visible.

The page is a chronology of what the cited primary records establish, with the live operator log treated as a dated snapshot rather than a permanent archive. ^[11]

Flooding: Typhoon Nari

The primary records agree on the scale of the September 2001 disaster: DORTS technical material records flooding at 16 underground stations, one depot and one high-capacity control centre, followed by three months of repairs and full service on 15 December. ^[5] Another DORTS volume says the control centre flooded to approximately 4.7 metres and that its train-control computers were badly damaged. ^[4]

DORTS names the Taipei [\[/rail/thsr/stations/taipei/\]](/rail/thsr/stations/taipei/) Main Station–Taiwan Railways shared underground area, the Zhongxiao Dunhua–department-store interface and Kunyang [\[/rail/metro/stations/bl21/\]](/rail/metro/stations/bl21/) station entrances as examples of openings through which water entered. ^[2] The same engineering volume records later flood gates, watertight doors and removable barriers, including a design criterion based on the recorded Nari water level plus 20 centimetres. ^[3]

The Control Yuan's correction adds an accountability record: it found flood preparation and drills deficient and identified defects in the Zhongxiao Fuxing station Y-shaped ventilation-shaft partition and the shared Taipei Main Station underground interfaces involving DORTS, TRTC [\[/rail/operators/trtc/\]](/rail/operators/trtc/) and Taiwan Railways. ^[6]

Derailment: Xiaonanmen

At 04:00 on 13 September 2016, an engineering vehicle at the Xiaonanmen [\[/rail/metro/stations/g11/\]](/rail/metro/stations/g11/) station platform toward Songshan [\[/rail/metro/stations/g19/\]](/rail/metro/stations/g19/) had a wheel leave the rail and could not move.^[7] The response ran the Xiaonanmen–Zhongshan section single-track in both directions for 11 hours 39 minutes and used shuttle buses for the interrupted sections.^[7] The fetched primary does not establish the exact restoration clock, the vehicle type or the mechanical cause, so those details remain TBC.

Signals, smoke and fire

TRTC records a 2025 Wenhua Line signalling anomaly between Zhongshan Junior High School and Wende [\[/rail/metro/stations/br18/\]](/rail/metro/stations/br18/).^[8] The line continued operating, with longer waits; the release attributes the immediate recovery to restarting a delayed signalling-network transmission system and says the detailed cause was still to be clarified with the original manufacturer.^[8]

On 11 March 2022, sparks and smoke appeared in the track between Chiang Kai-shek Memorial Hall and NTU Hospital [\[/rail/metro/stations/r09/\]](/rail/metro/stations/r09/).^[9] Trains passed slowly, a driver went down to extinguish the fire, and TRTC later replaced the failed insulation-baseplate assembly and embedded sleeve.^[9]

On 28 December 2025, a fire alarm at the main substation outside Zhongxiao Fuxing was traced to an abnormal main transformer.^[10] Power transfer restored train operation, nobody was injured, and some nearby lifts and escalators were temporarily affected.^[10]

TRTC's live operations table, fetched on 17 August 2026, also records a [BR10](#) signalling fault, an [007](#) signalling fault, passenger power-bank smoke/fire at [011](#), third-rail cable smoke at [BL07](#) and platform-door automatic-opening failure at [BL15](#).^[11] The table gives the local response and service effect for each row; its live nature means these entries should be re-fetched before being treated as a historical register.^[11]

The DORTS Wenhua project record supplies an older primary description without a station or exact date: during 1993 system testing, the Muzha Line had a tyre- ignition accident.^[1] The station, unit, time and relationship to the two fires described in secondary histories remain TBC.^[1]

Earthquake: Circular and Ankeng lines

The 3 April 2024 earthquake displaced eleven Circular Line girder locations and is covered in the focused 0403 earthquake investigation [\[/rail/history/circular-line-0403-earthquake/\]](/rail/history/circular-line-0403-earthquake/). closed the damaged section.^[12] ^[13] The Control Yuan investigation attributes the failure to construction and inspection problems around the bearing assembly, while New Taipei DORTS records seven severe displacements of 20–92 centimetres and four smaller displacements.^[12] ^[13]

NTMC [/rail/operators/ntmc/] recorded full Circular Line suspension on the day, followed by single-track bidirectional operation between Banqiao and New Taipei Industrial Park [/rail/metro/stations/y20/] from 17:00.^[14] Full service resumed at noon on 12 December 2024; the operator's repair inventory says nine steel-box-girder spans were repositioned, alongside track-baseplate, cable and equipment replacement.^[15]

The same earthquake temporarily changed Ankeng LRT service: NTMC recorded K09—K06 single-track bidirectional working and K06—K01 partial operation, followed by normal service at 16:30 with a 15-minute headway.^[16] ^[14]

Conflicts and gaps

DORTS technical-book no. 29 p. 87 labels Nari 「民國90年9月6日」, while DORTS technical journal no. 46 p. 214 gives 「民國90年9月17日」.^[2] ^[5] Both dates are published here; no fetched primary reconciles them.^[2] ^[5]

The Control Yuan and New Taipei DORTS count eleven Circular Line displacement locations, while NTMC's reopening release counts nine spans repositioned. The sources appear to count different things, but no fetched primary explicitly maps eleven locations to nine spans, so this page does not choose between them.^[12] ^[13] ^[15]

The complete station-by-station identity of the 16 flooded stations is **TBC**; the fetched DORTS pages name only examples. The exact station, date and vehicle details of the 1993 Wenhua testing incident remain TBC, as do the formal investigations behind the incoming lead-only events whose full primary pages could not be fetched.

See also: Wenhua Line [/rail/metro/lines/wenhua-line/], Songshan–Xindian Line [/rail/metro/lines/songshan-xindian-line/], Tamsui–Xinyi Line [/rail/metro/lines/tamsui-xinyi-line/], Bannan Line [/rail/metro/lines/bannan-line/], Zhonghe–Xinlu Line [/rail/metro/lines/zhonghe-xinlu-line/], Circular Line [/rail/metro/lines/circular-line/], and Ankeng LRT [/rail/metro/lines/ankeng-lrt/].

References

16 of 16 sources on this page are primary — published by the operator, the builder or government.

- 1 Wenshan—Neihu Line [https://www.dorts.gov.taipei/cp.aspx?n=DBAC040496EFAB94]
文山內湖線
PRIMARY Taipei City Department of Rapid Transit Systems (臺北市政府捷運工程局)
accessed 2026-08-17
Full DORTS project record stating that the Muzha Line had a tyre-ignition accident during system testing in 1993; it does not name a station, date or vehicle.

- 2 Practical water, environmental-control and fire-safety engineering, p. 87 [https://ebook.dorts.gov.taipei/ebook/no29/files/basic-html/page87.html]

捷運工程叢書精進版－29 捷運系統水電、環控與消防工程實務

PRIMARY Taipei City Department of Rapid Transit Systems (臺北市政府捷運工程局)

accessed 2026-08-17

Full DORTS technical-book page describing Nari flood entry through openings and naming Taipei Main Station, Zhongxiao Dunhua and Kunyang as examples; it labels the typhoon date 90年9月6日.

- 3 **Practical water, environmental-control and fire-safety engineering, p. 88** [<http://ebook.dorts.gov.taipei/ebook/no29/files/basic-html/page88.html>]

捷運工程叢書精進版－29 捷運系統水電、環控與消防工程實務

PRIMARY Taipei City Department of Rapid Transit Systems (臺北市政府捷運工程局)

accessed 2026-08-17

Full DORTS technical-book page recording flood-level design and the post-Nari flood gates, watertight doors and removable barriers.

- 4 **Practical civil engineering, p. 182** [<https://ebook.dorts.gov.taipei/ebook/no4/files/basic-html/page182.html>]

捷運工程叢書精進版－4 土木工程實務

PRIMARY Taipei City Department of Rapid Transit Systems (臺北市政府捷運工程局)

accessed 2026-08-17

Full DORTS technical-book page stating that Nari flooded 16 underground stations and the control centre to about 4.7 metres, damaging train-control computers.

- 5 **Remote control of full-section flood isolation compartments, p. 214** [<https://ebook.dorts.gov.taipei/JRTST/ebook/no46/files/basic-html/page214.html>]

捷運防水隔艙遠端控制之探討

PRIMARY Taipei City Department of Rapid Transit Systems (臺北市政府捷運工程局)

accessed 2026-08-17

Full DORTS technical-journal page stating the 17 September 2001 date, 16 flooded stations, one depot, one high-capacity control centre, three months of repairs and 15 December full reopening.

- 6 **Control Yuan correction case 091內正0009** [<https://www.cy.gov.tw/CyBsBoxContent.aspx?n=134&s=5250>]

監察院糾正案文 091內正0009

PRIMARY Control Yuan of the Republic of China (監察院) accessed 2026-08-17

Full official correction page recording deficiencies in flood preparation, the Zhongxiao Fuxing Y-shaped ventilation-shaft partition, and shared Taipei Main Station underground interfaces.

- 7 **Technical journal no. 52, p. 15** [<https://ebook.dorts.gov.taipei/JRTST/ebook/no52/files/basic-html/page15.html>]

捷運技術 第52期

PRIMARY Taipei City Department of Rapid Transit Systems (臺北市政府捷運工程局)

accessed 2026-08-17

Full DORTS technical-journal page recording the 13 September 2016 Xiaonanmen engineering-vehicle wheel derailment, the single-track response and 11 hours 39 minutes of single-track bidirectional operation.

- 8 Wenhu Line signalling anomaly cleared and normal operation restored [https://www.metro.taipei/News_Content.aspx?n=30CCEFD2A45592BF&s=9CF946E985FD0EA1&sms=72544237BBE4C5F6]

8日晚間文湖線號誌異常已排除 本(9)日恢復正常營運 維修人員檢修為號誌傳輸網路異常 詳細原因將洽原廠協助釐清

PRIMARY Taipei Rapid Transit Corporation (臺北大眾捷運股份有限公司) accessed 2026-08-17
Full TRTC release for the 8 February 2025 signalling anomaly between Zhongshan Junior High School and Wende, including the service effect and network-transmission diagnosis.

- 9 Sparks and smoke between NTU Hospital and Chiang Kai-shek Memorial Hall stations [https://www.metro.taipei/News_Content.aspx?n=30CCEFD2A45592BF&s=E5AF23FD3A33772D]

臺大醫院站站間軌道火花冒煙事件

PRIMARY Taipei Rapid Transit Corporation (臺北大眾捷運股份有限公司) accessed 2026-08-17
Full TRTC release for the 11 March 2022 track sparks/smoke event and the replacement of the failed insulation-baseplate assembly and embedded sleeve.

- 10 Abnormal equipment at the Xinfu-Jie main substation outside Zhongxiao Fuxing station [https://www.gov.taipei/News_Content.aspx?n=F0DDAF49B89E9413&s=F85C992AFFE655D3&sms=72544237BBE4C5F6]

忠孝復興站外新復捷主變電站設備異常 未影響系統營運

PRIMARY Taipei Rapid Transit Corporation (臺北大眾捷運股份有限公司), published by Taipei City Government accessed 2026-08-17
Full official release for the 28 December 2025 substation fire alarm, abnormal main transformer, no injuries and temporary lift/escalator effects without train-service interruption.

- 11 Taipei Metro operational information [<https://ssl.metro.taipei/metrooperation/>]
臺北捷運營運資訊

PRIMARY Taipei Rapid Transit Corporation (臺北大眾捷運股份有限公司) accessed 2026-08-17
Full live TRTC operational table fetched on 17 August 2026; it records current incident rows including **BR10** and **007** signalling faults, **011** passenger power-bank smoke/fire, **BL07** third-rail cable smoke and **BL15** platform-door failure.

- 12 Control Yuan investigation report, case 114交調0005 [<https://www.cy.gov.tw/CyBsBoxContent.aspx?s=49082>]

監察院調查報告 114交調0005

PRIMARY Control Yuan of the Republic of China (監察院) accessed 2026-08-17
Full official investigation report on the 3 April 2024 Circular Line earthquake damage, including the eleven displacement locations and construction findings.

- 13 Initial explanation of Circular Line earthquake damage [<https://www.dorts.ntpc.gov.tw/news/indexInfo/1A1dprRBmLK7>]

環狀線震損初步說明

PRIMARY New Taipei City Department of Rapid Transit Systems (新北市政府捷運工程局)

accessed 2026-08-17

Full New Taipei DORTS announcement recording the seven severe and four less-severe displacement ranges and the initial recovery estimate.

14 New Taipei's two light rail lines resume operation; the Circular Line runs single-track bidirectional [<https://www.ntmetro.com.tw/basic/?mode=detail&node=719>]

新北捷運兩線輕軌恢復正常營運 環狀線採部份區段單線雙向營運

PRIMARY New Taipei Metro Corporation (新北大眾捷運股份有限公司) accessed 2026-08-17

Full operator release for 3 April 2024, covering Circular Line suspension and partial single-track operation plus Ankeng LRT's 16:30 return to normal service.

15 Circular Line ready; full service resumes at noon [<https://www.ntmetro.com.tw/basic/?mode=detail&node=754>]

新北環狀線準備好了!確認安全無虞12:00 全線復駛

PRIMARY New Taipei Metro Corporation (新北大眾捷運股份有限公司) accessed 2026-08-17

Full operator reopening release for 12 December 2024, including nine repositioned spans and the published repair inventory.

16 3 April earthquake statement [<https://www.ntmetro.com.tw/basic/?mode=detail&node=716>]

新北捷運公司 - 0403 地震說明

PRIMARY New Taipei Metro Corporation (新北大眾捷運股份有限公司) accessed 2026-08-17

Full operator release recording Ankeng LRT **K09**—**K06** single-track bidirectional operation and **K06**—**K01** partial operation immediately after the earthquake.

Last updated: 2026-08-17

An independent, non-commercial reference site. Not affiliated with any transit operator or government body in Taiwan. Line colours are the official values published by each operator through Taiwan MOTC's open data platform. [About this site.](#)

Station names, codes and sequence from TDX Transport Data eXchange, Ministry of Transportation and Communications, operators TRTC, NTMC, TYMC, and TMRT. Government open data. Retrieved 2026-08-24; source last updated 2016-11-23. The 12 Sanying station records absent from TDX are sourced directly to New Taipei Metro and government publications on their pages. Provenance.