VCS VERIFICATION REPORT

QINGDAO LONGXIN WIND POWER PROJECT PHASE I

Document Prepared By

China Quality Certification Centre

Project Title	Qingdao Longxin Wind Power Project Phase I
Version	02
Report ID	CDM-VCS-2022-0008

Report Title	VCS Verification Report of Qingdao Longxin Wind Power Project Phase I
Client	Juno Carbon Investment & Environmental Technology (Beijing) Co., Ltd.
Pages	30
Date of Issue	16/09/2022

Prepared By	China Quality Certification Centre
Contact	Address: No.9, No.188 South 4th Ring Road West, Fengtai District, Beijing,China Tel: +86 10 83886382 Email: zhengxianyu@cqc.com.cn Website: https://www.cqc.com.cn/
Approved By	Li Guozhen 
Work Carried Out By	Team Leader: Zheng Xianyu Team Member: Li Yanbin Chi Shuyang Technical Reviewer: Hong Dajian

Summary:

China Quality Certification Centre(CQC) has performed the verification of the emission reductions reported for the project activity “VCS Verification Report of Qingdao Longxin Wind Power Project Phase I” (VCS Project ID:969) for the monitoring period 28/09/2012-20/12/2017, to review and determine the monitored reductions in GHG emissions that have occurred as a result of the project activity.

These emission reductions are claimed as Verified Carbon Units (VCU) under the VCS Standard Version 4.3. The verification was performed on the basis of VCS Standard Version 4.3 for the VCS projects, as well as criteria given to provide for consistent project operations, monitoring and reporting. The verification was conducted by means of document review, follow-up interviews and site inspections, and the resolution of outstanding issues. The verification team identified 2CARs and no FAR is raised in this monitoring period. In CQC’s opinion, the GHG emission reductions reported for the project in the monitoring report(version 02 dated 30/08/2022) are fairly stated.

The Project has been registered as a CDM project on 28/09/2012 (UNFCCC registration reference number: 6697). The emission reductions of the project have not been issued as CERs.

CQC does not assume any responsibility towards the issuance and utilization of the VCUs hereby verified and certified. Request for issuance of VCUs shall be made by the project proponent to an approved VCS Program Registry based on the requirements set out under the most recent version of the VCS Program Guidelines clause on VCS Registration.

The verification of reported emission reductions is based on the information made available to CQC and the engagement conditions detailed in this report.

CQC cannot be held liable by any party for decisions made or not made based on this report. Hence, CQC is able to certify that the emission reductions from the “Qingdao Longxin Wind Power Project Phase I” during this monitoring period from 28/09/2012- 20/12/2017 amount to 472,697 tCO_2e.

1 INTRODUCTION

1.1 Objective

Verification is the periodic independent review and ex-post determination by an accredited verification body of the monitored reductions in GHG emissions that have occurred as a result of the registered VCS project activity during a defined verification period.

A verification statement is the written assurance by a verification body that, during a specific period in time, a project activity achieved the emission reductions as verified.

The objective of this verification was to verify and provide a verification statement of emission reductions reported for the "Qingdao Longxin Wind Power Project Phase I" for the period 28/09/2012- 20/12/2017.

1.2 Scope and Criteria

The scope of the verification is:

To verify that actual monitoring systems and procedures are in compliance with the monitoring systems and procedures described in the monitoring plan;

To evaluate the GHG emission reduction data and express a conclusion with a reasonable level of assurance about whether the reported GHG emissions reductiondata is free from material misstatement;

To verify that reported GHG emissions data is sufficiently supported by evidence.

The criteria of the verification are:

VCS Program Guide (version 4.2)[/39/]

VCS Standard (version 4.3)[/38/] and other relevant requirements defined by Verra;

The approved methodology ACM0002 (version 12.2.0)[/42/] applied by the project.

The verification shall ensure that reported emission reductions are complete and accurate

1.3 Level of Assurance

The verification report expresses a conclusion with a reasonable level of assurance about whether the reported GHG emissions reduction data is free from material misstatement. As per the para 3.9.1 of the VCS Standard Version 4.3, the project size categorization belongs to 'Project' as the expected annual emission reductions is 92,183 tCO_2e lower than 300,000 tCO_2e.Therefore, according to the requirement of para 4.1.8 (4) of VCS Standard Version 4.3 “The threshold for materiality with respect to the aggregate of errors, omissions and misrepresentations relative to the total reported GHG emission reductions and/or removals shall be five percent for projects and one percent for large projects.”, CQC applied a materiality threshold of 5% with respect to omission or misstatements concerning reported quantities of the project activity.

1.4 Summary Description of the Project

Qingdao Longxin Wind Power Project Phase I (hereinafter referred to as the Project) developed by China Resources Wind Power (Qingdao) Co., Ltd., involves construction and operation of a wind power project that is sited on Liyuan Town and Dianzi Town, Pingdu City, Shandong Province, P.R. China. The Project installs 24 wind turbines with capacity of 2000kW each and 1 wind turbine with capacity of 1800kW, providing a total installed capacity of 49.8MW to generate clean renewable electricity.

The electricity generated by the Project is supplied to the North China Power Grid (NCPG), displacing electricity generated by NCPG which is dominated by fossil fuel fired power plants. The estimated annual net electricity generation and GHG emission reductions in the first crediting period (from 08/11/2011 to 07/11/2021) are 99,026MWh and 92,183tCO_2e respectively.

The scenario existing prior to the start of the implementation of the project is: The same electricity output by the project activity would have otherwise been generated by the operation of NCPG connected power plants and by the addition of new generation sources. That is the same as the baseline scenario.

The construction of the Project started on 26/05/2011 and The Project was put into operation on 08/11/2011.

The project has been registered as VCS project with Ref. VCS 969 and VCUs of 82,302 tCO_2e have been issued for the monitoring period from 08/11/2011- 27/09/2012. The Project has been registered as a CDM project on 28/09/2012 (UNFCCC registration reference number: 6697). The emission reductions of the project have not been issued as CERs.

During this monitoring period from 28/09/2012 to 20/12/2017, the total emission reduction achieved is 472,697tCO_2e.

2 VERIFICATIONPROCESS

2.1 Method and Criteria

The verification was performed through means of the following three phases in accordance with the requirement of the registered VCS PD and monitoring plan contained in the registered VCS PD, the applied methodology, and the VCS Standard (version 4.3) and other relevant VCS requirements:

- A desk review of the monitoring report and all support documents;
- Follow-up interviews with project stakeholders and site inspection;
- The resolution of outstanding issues and the issuance of the verification report and statement.

The following sections outline each step in more detail.

The verification of the emission reductions has assessed all factors and issues that constitute the basis for emission reductions from the project. These include:

- The emission reduction calculations and the relevant data records;
- The calibration and maintenance records for the monitoring instruments;
- The management systems to support the project operation and monitoring.

2.2 Document Review

Based on the requirements of competency, experience and qualified sectoral scopes, CQC appointed a verification team in accordance with CQC's internal procedures.

Function	Name	Technical competence	Task Performance*
Team Leader	Zheng Xianyu	1.1, 1.2, 2.1	☒DR☒SV☒RP☐TR
Team Member	Chi shuyang	1.1, 1.2	☒DR☒SV☒RP☐TR
	Li Yanbin	1.1, 1.2	☒DR☒SV☒RP☐TR
Technical Reviewer	Hong Dajian	1.2, 2.1, 13.1	☒DR☐SV☐RP☒TR

*DR=Document review; SV=Site visit; RP=Reporting; TR=Technical review

During the desk review, CQC has applied standard auditing techniques to assess the quality of information provided. The following activities were performed:

- A review of the data and information presented to verify their completeness;

- A review of the monitoring plan and monitoring methodology, paying particular attention to the frequency of measurements, the quality of metering equipment including calibrationrequirements, and the quality assurance and quality control procedures; and an evaluation of data management and the quality assurance and quality control system in the context of their influence on the generation and reporting of emission reductions

2.3 Interviews

On 09/08/2022, CQC visited the project proponent China Resources Wind Power (Qingdao) Co., Ltd. to perform on-site assessment. The key personnel of the project were interviewed and. Main topics of the interview are summarized in the table below:

Interviewed personnel	Role	Organization	Subject
Mr. Ju Bin	Project Manager	China Resources Wind Power (Qingdao) Co., Ltd.	Operation of the project activity; Implementation of the monitor plan of the projectactivity; Datacollectionanddata achievement; Calibration of meters and equipment maintenance; Thecomplaintbylocal stakeholders; The stakeholder consultation during the operation of the project activity. Project's sustainable development contributions; The impact of the project activity; The complaint by local stakeholders; The stakeholder consultation during the operation of the project activity; Project's sustainable development contributions. Data collection and ER calculation.
Mr. ShangZitong	Staff	China Resources Wind Power (Qingdao) Co., Ltd.	
Mr. Pang Jianjian	Staff	China Resources Wind Power (Qingdao) Co., Ltd.	
Mr. Zhao Jie	Staff	China Resources Wind Power (Qingdao) Co., Ltd.	
Ms. Liu Yang	Project Manager	Juno Carbon Investment & Environment Technology (Beijing) Co.,Ltd.	
Ms. Ding Xue	Technical director	Juno Carbon Investment & Environment Technology (Beijing) Co.,Ltd.	

2.4 Site Inspections

During the on-site assessment, CQC has applied standard auditing techniques to assess the quality of information provided. The following aspects of the project activity have been verified:

- An assessment of the implementation and operation of the registered project activity is as per the registered VCS PD of the project activity;

- A review of information flows for generating, aggregating and reporting the monitoring parameters; and - Interviews with relevant personnel to determine whether the operational and data collection procedures are implemented in accordance with the monitoring plan;

- A cross-check between information provided in the monitoring report and data from other sources such as plant logbooks and the electricity receipts;

- A check of the monitoring equipment including calibration performance and observations of monitoring practices against the requirements of the registered VCS PD and the selected methodology;

- A review of calculations and assumptions made in determining the GHG data and emission reductions; and

- An identification that quality control and quality assurance procedures in place to prevent or identify and correct any errors or omissions in the reported monitoring parameters.

In addition, all parameters required by the monitoring methodology ACM0002 (version 12.2.0), and the management system were assessed during the site visit.

2.5 Resolution of Findings

The objective of this phase of the verification is to resolve issues related to the monitoring, implementation and operations of the registered project activity that could impair the capacity of the project activity to achieve emission removals or influence the monitoring and reporting of emission removals prior to CQC's positive conclusion on the GHG emission removals calculation.

Findings established during the verification can either be seen as a non-fulfilment of criteria ensuring the proper implementation of a project or where a risk to deliver high quality emission reductions is identified.

A Corrective Action Request (CAR) is raised, if one of the following situations occurs:

(a) Non-compliance with the monitoring plan or methodology are found in monitoring and reporting and has not been sufficiently documented by the project participants, or if the evidence provided to prove conformity is insufficient;

(b) Modifications to the implementation, operation and monitoring of the registered project activity has not been sufficiently documented by the project participants;

(c) Mistakes have been made in applying assumptions, data or calculations of emission reductions that will impact the quantity of emission reductions;

(d) Issues identified in a FAR during validation to be verified during verification or previous verification(s) have not been resolved by the project participants.

A Clarification Request (CL) is raised, if information is insufficient or not clear enough to determine whether the applicable VCS requirements have been met.

A Forward Action Request (FAR) is raised, for actions if the monitoring and reporting require attention and/or adjustment for the next verification period.

To guarantee the transparency of the verification process, the concerns raised are documented in more detail in Appendix A.

2 Corrective Action Requests (CARs) had been raised during the verification, presented in Appendix A. Taking into account this output, the Project participant took corrections and revised its Monitoring Report (VR). All CARs are successfully closed. (refer to Appendix A for further details).

No FAR and no other findings raised during the validation.

2.5.1 Forward Action Requests

A forward action request (FAR) is issued for actions if the monitoring and reporting require attention and/or adjustment for the next monitoring period.

CQC confirmed that there was no FAR identified in previous verification[/28/], and no FAR was raised during this verification.

2.6 Eligibility for Validation Activities

The project has been validated by TÜV Rheinland (China) Ltd. under the CDM rules and registered as CDM project on 28/09/2012, and was registered as VCS project under VCS standard version 3. The project has been registered as VCS project with Ref. VCS 969 and VCUs of 82,302tCO_2e have been issued for the monitoring period from 08/11/2011- 27/09/2012 by TÜV Rheinland (China) Ltd. The emission reductions of the projet have not been issued as CERS.

CQC was accredited in Sectoral Scope 1 on validation and verification and thus is eligible for verification activities on the proposed project. The monitoring period 28/9/2012-20/12/2017 is no more than consecutive 6 years. Thus, in compliance with the requirement for VVB stipulated in Section 4.1.20 of VCS standard version 4.3.

3 VALIDATION FINDINGS

3.1 Participation under Other GHG Programs

The project has been registered as CDM project and the reference number is 6697, the first CDM crediting period is from 28/09/2012 to 27/09/2019. The emission reductions of the project have not been issued as CERs.

The project has been registered as VCS project with Ref. VCS 969 and VCUs of 82,302tCO_2e have been issued for the monitoring period from 08/11/2011- 27/09/2012.

The project activity does not participated under other GHG programs.

3.2 Methodology Deviations

There is no methodology deviation applied during this monitoring period.

3.3 Project Description Deviations

In the registered VCS PD, the crediting period is described as from 08/11/2011 to 27/09/2012. A deviation is requested for the crediting period in the registered VCS PD. The project was registered under VCS Standard Version 3 and completed validation before 19/03/2020. Thus, it remains eligible to apply the crediting period requirements under VCS Version 3 which shall be a maximum of ten years and may be renewed at most twice, so the crediting period of the project should be updated from 08/11/2011 - 27/09/2012 to 08/11/2011-07/11/2021, and it has no impacts on the applicability, additionality or baseline of the project. There is no other project description deviation during this monitoring period.

3.4 Grouped Project

The project is not a grouped project.

4 VERIFICATION FINDINGS

This section summarizes the findings from the verification of the emission reductions reported for the "Qingdao Longxin Wind Power Project Phase I" for the monitoring period 28/09/2012-20/12/2017.

4.1 Project Implementation Status

Project Implementation in accordance with the registered project design document

The project is a wind power grid-connected plant and located at Liyuan Town and Dianzi Town, Pingdu City, Shandong Province, P.R.China. The geographical coordinates are verified by GPS system as from 119.8827°E to 119.9503°E, and from 36.8157°N to 37.8915°N (The central GPS coordinate is 119.91125°E, 36.8568°N).

This project installs 24 wind turbines with capacity of 2000 kW each and 1 wind turbines with capacity of 1800 kW which amount to a total installed capacity of 49.8MW. The estimated power output is 99,026MWh/year and the load factor is 22.70%. The Project started operation on 08/11/2011.

An 110kV substation is built at the project site, which connects the project to the Tangtian 220kV Substation which is about 6.7 km away from the project and belongs to the North China Power Grid. Then the power produced in the wind farm can be transmitted to the North China Power Grid.

Bidirectional meter M1 with accuracy 0.5S was installed on the Tangtian Substation to measure the total electricity supplied to the grid by the Project and Phase II project, meanwhile M1 is used to measure the total electricity imported from the grid by the Project and Phase II project. Meter M2 and M3 installed at the on-site substation recorded the electricity supplied by the Project and Phase II Project respectively.

Meter M4 is used to measure the electricity imported from the grid by the project and Phase II project via a spare 10kV back-up line.

During this monitoring period, the Project had been in normal operation, without special events such as overhaul or exchange of equipment. There were no events or situations which may impact the applicability of the methodology.

The monitoring system was implemented in line with the monitoring plan in the registered PD. The actual operation was conducted strictly in compliance with the description in the monitoring plan.

The actual implementation of the project during this verification period was verified in terms of nameplates of wind turbines and the equipment purchase contract. The details of theturbines with respect to their installation and capacity have been verified to be consistent withdescription indicated in the registered VCS PD.

The electricity generated by the Project is supplied to the North China Power Grid (NCPG), displacing part of electricity generated by NCPG which is dominated by fossil fuel fired power plants. According to the methodology ACM0002 (version 12.2.0), the baseline emissions are the electricity produced by the project multiplied by the emission factor of NCPG.

All the monitoring systemin operation period is consistent with the description in monitoring plan contained in the registered VCS PD. The control system at the power plant is automated and assures continuous operation, including monitoring on malfunction of equipment. By checking the daily operation and maintenance records[/7/] and via on-site visit, CQC can confirm that no serious malfunction happened and the plant was under a normal operation as expected in this monitoring period.

On-site training for the related procedures including, recording and reporting was verified to be in place[/6/] and their implementation was confirmed by interview with the key operators[/43/] and observing the operation.

CQC confirms that the project implementation is in accordance with the project description contained in registered VCS PD. Furthermore, through visual inspection and document review, it is confirmed that all physical features of the project activity including data collection systems and storage systems have been implemented in accordance with the monitoring plan.

Compliance of monitoring plan with monitoring methodology

CQC is able to confirm that the monitoring plan contained in the VCS PD is in accordance with the approved methodology applied by the project activity, i.e. ACM0002 (version 12.2.0).

Compliance of monitoring with the monitoring plan

The monitoring has been carried out in accordance with the monitoring plan contained in the VCS PD, CQC confirms that all parameters stated in the monitoring plan are monitored and reported appropriately. All parameters required to be monitored by the monitoring plan as per the monitoring methodology ACM0002 (version 12.2.0) and the management system were assessed during the site visit. The monitoring report lists each parameter required by the monitoring plan and the information flow (i.e. from data generation, recording, aggregation, calculation and reporting) for these parameters is provided. The information flow for each parameter in further verified in the following section.

Parameters fixed ex ante

“Data and parameters fixed ex ante” in the MR are checked against the registered VCS PD. The parameter $EF_{grid,CM,y}$ is the combined emission factor of the grid, which was determined ex-ante at the validation stage and has been fixed during the first crediting period. CQC confirms that the emission factor used in the monitoring report is in compliance with the VCS PD.

Parameters monitored

CQC conducted document review and performed on-site assessment with project stakeholders to:

- A review of information flows for generating, aggregating and reporting the monitoring parameters;

- Determine whether the operational and data collection procedures are implemented in accordance with the registered monitoring plan;

- A cross-check between information provided in the monitoring report and data from other sources such as plant logbooks and electricity receipts;

- An identification that quality control and quality assurance procedures in place to prevent or identify and correct any errors or omissions in the reported monitoring parameters

According to the monitoring plan, the parameters to be monitored is as below

$EG_{output,y}$ Electricity supplied to the grid by the Project and Phase II project

$EG_{imput,y}$ Electricity consumed from the grid by the Project and Phase II project

$EG_{another,y}$ Electricity supplied to the grid by the Phase II project

$EG_{im\text{-}spare,y}$ Electricity consumed by the Project and Phase II project from the grid the project through the backup line

Monitored parameters $EG_{output,y}$ and $EG_{imput,y}$

By site inspection and checking the monitoring plan contained in the registered VCS PD, CQC confirmed $EG_{output,y}$ and $EG_{imput,y}$ are continuously measured by meter M1. M1 is bi-directional and located at the high- voltage side of the on-site 35kV/110kV transformer station. The meter readings of electricity exports and imports were daily recorded, monthly aggregated and archived electronically.

The verification team had on-site checked the location of the meteragainst the diagram of power connection system [/4/] and found it to be consistent and installed in accordance with the approved monitoring plan. All the monitoring facilities and system have been verified by CQC during on-site visit.

By checking operation log [/7/] and via on-site visit, it is confirmed that M1 was working well during this monitoring period. Via the on-site interview and by checking the daily operation and maintenance records[/7/], monthly and daily reading records and electricity receipts[/9/] issued by grid company, it is confirmed by the verification team that the electricity is continuously measured by M1, daily recorded and monthly aggregated by trained staff of the project as agreed with the grid company at 24:00 on the aggregating, the last day of each month [/8/]. The electricity receipts[/9/] issued by the grid company have been used for verifying the records of $EG_{output,y}$ and $EG_{imput,y}$ measured by main meter M1.

Monitored parameter $EG_{another,y}$

By site interview and checking the monitoring plan contained in the registered VCS PD and previous verification reports, CQC confirmed $EG_{another,y}$ is continuously measured by meter M3, which is installed on the 110kv outline of the main transformer of Phase II project on site. The meter reading was daily recorded, monthly aggregated and archived electronically. By checking operation log [/7/] monthly and daily reading records [/8/] and via on-site visit, it is confirmed that M3 was working well during this monitoring period and the electricity is continuously measured by M3, daily recorded and monthly aggregated by trained staff of the project as agreed with the grid company at 24:00 on the aggregating, the last day of each month.

By site interview and checking the monitoring plan contained in the registered VCS PD and previous verification reports, CQC confirmed $EG_{im\text{-}spare,y}$ is continuously measured by meter M4, which is installed on the 10kv backup line on site. The meter reading was daily recorded, monthly aggregated and archived electronically. By checking operation log [/7/] monthly and daily reading records [/8/] and via on-site visit, it is confirmed that M4 was working well during this monitoring period and the electricity is continuously measured by M4, daily recorded and monthly aggregated by trained staff of the project as agreed with the grid company at 24:00 on the aggregating, the last day of each month.

As described above, the meters have been installed in accordance with VCS Program rules and meet all appropriate rules and requirements of VCS standard. CQC has on-site checked the location of the meters against the diagram of power connection system and found them to be consistent.

Data in the monthly reading records were used to the report, through a cross check with Electricity Receipts. The conservative values were used for the monitoring report and ERs calculation spread sheet, which has been verified by the verification team. Supporting references and data required to determine the quantity of net electricity generation supplied by the project is found to be complete and transparent.

CAR 01 was raised because of the monitoring period in the MR (from 28/09/2012 to 07/11/2021, which is more than six consecutive years) does not meet the requirements of rotation of validation/verification bodies in VCS-Standard_v4.3. The monitoring period has revised from 28/09/2012-07/11/2021 to 28/09/2012-20/12/2017. **CAR 01** was subsequently successfully closed.

CAR 02 was raised because of the information of the monitoring meters installed during the monitoring period is not provided in the MR and supporting documents. The information of the monitoring meters during this monitoring period have been added in the section 4.1 of the revised MR (V02, 30/08/2022). The main information are including the type, accuracy, serial number, calibration date, validity period and name of the calibration organization, and the meters' photo and the calibration reports covering this monitoring period have been submitted. **CAR 02** was subsequently successfully closed.

Refer to Appendix B for details.

Monitoring equipment and calibration

The documents review was carried out. Particular attention was paid to the frequency of measurements, the quality of the monitoring equipment including calibration performance and observations of monitoring practices against the requirements of the registered VCS PD and the methodology ACM0002(version 12.2.0) and corresponding tool(s), and the quality assurance and quality control procedures.

All monitoring meters have been calibrated annually as per the monitoring plan covering this monitoring period.

The calibration frequency of meters is annual, which is consistent with the monitoring plan. Based on the site visit and by checking the calibration reports, CQC confirms that:

- All meters have been installed in accordance with the monitoring plan;

- The meters' accuracy is in line with the requirement of the monitoring plan;

- The calibration frequency of the meters is annual, which is in line with the monitoring plan. And the calibrations are verified to be valid for the whole reporting period.

Data management and control

The quality assurance and quality control procedures have been addressed in the project management and monitoring manual[/5/], including the organization structure with the responsibilities, personnel competencies, monitoring procedures and monitoring management. By interview with the staff/43/ and check records [/7//8/] during on-site visit, it can be confirmed that the monitoring management system is implemented following the project management and monitoring manual.

All monitoring devices have been calibrated and maintained periodically to ensure the accuracy of measurement. Calibration records of instruments used in measurements were made available during the verification visit and found to be valid for the entire period of the verification. Competence and training records of in-plant personnel engaged in measurement of plant parameters were presented during verification and found to be in order.

As the above and document review, verification team considers that the project activity operated properly in the way complying with the implementation plan and monitoring plan contained in the VCS PD and the monitoring was performed in a transparent and comprehensive manner during this monitoring period.

The verification team has also checked other GHGs programs and forms of credit such as exchange platform of Chinese Certified Emission Reduction(CCER) projects, Gold Standard, EU ETS, IREC, China ETS and based on the interview with the project proponent, during this monitoring period, it is confirmed that except CDM and VCS scheme:

- No evidence showing that the project has participated or been rejected under any other GHG programs since validation or previous verification

- There is no observation that the project has received or sought any other emission trading program and form of environmental credit, or has become eligible to do so since validation or previous verification

The project is completely voluntary VCS project, not included in an emissions trading program or any other mechanism that includes GHG allowance trading. Although the national emission trading scheme has been launched since 16/07/2021, it only covers the high-emission and energy intensive industries that emit at least 26,000 tons of CO2e/year as per the regulation[/21/]including thermal power generation, petrochemical, chemical, building materials, iron and steel, etc. By checking the business license[/16]/of the project proponent, it is confirmed in business scope of renewable energy investment, thus is not included the mandatory emission control scheme and there is no emission cap enforced for the PP by further checking the enforced company list under China ETS in public information[/21/]. Moreover, it is confirmed by CQC the project is not registered as a CCER project in China, the emission reductions generated by the project activity are not eligible for transaction under China ETS as per the regulation[/20/]. Hence, it is confirmed that the emission reductions will not be double counted.

Via the on-site inspection, and through the interviews with the project proponent, local villagers and official from local environment bureau, and by checking the evidences provided by the project proponent, the verification team agrees on the following points regarding to the promotion of sustainability development by the project activity:

- SDG 7, Indicator 7.2.1 Renewable energy share in the total final energy consumption.
  The project provides clean and renewable energy through making use of wind power, displacing fossil fuel power in the gird NCPG. During this monitoring period, 507,789.778 MWh of net electricity generated by wind energy was delivered to the NCPG. It is verified by checking the daily and monthly reading records[/8/] and via on-site inspection. Meanwhile, by checking the approved VCS and CDM monitoring reports for the previous monitoring, the project has supplied 596,207.338 MWh renewable energy to NCPG during the first monitoring period and this monitoring period. And 1,980,520 MWh electricity from renewable source are expected to supply to NCPG over the project lifetime which contribute the SDGs 7. This contributes to increasing the share of clean energy consumption of China's National Plan on Implementation of 2030 Agenda for Sustainable Development (http://www.gov.cn/xinwen/2016-10/13/5118514/files/44cb945589874551a85d49841b568f18.pdf).

- SDG 8, Indicator 8.3.1 Proportion of informal employment in non agriculture employment, by sex.
  It is verified by interviewing with project proponent and staff and checking the staff roster[/22/], 22 people including 6 females were employed by the project owner for the operation,

monitoring and equipment maintenance of this project during this monitoring period. The project activity had provided temporary working opportunities during the construction period. From the operation start date, 22 people were employed including 6 females during the first VCS monitoring period and this monitoring period. This contributes to "Increase labor force participation rate through implementation rate through implementation of the classification policy. Vigorously enforce the law on promotion of employment" as stated in China's National Plan on Implementation of 2030 Agenda for Sustainable Development (http://www.gov.cn/xinwen/2016-10/13/5118514/files/44cb945589874551a85d49841b568f18.pdf).

- SDG 13, Indicator Tonnes of greenhouse gas emissions avoided or removed.
  As verified by on-site inspection, and via checking the emission reduction calculation sheet[/2/] and the daily and monthly reading records[/8/], 472,697tCO_2e GHG emission reductions are generated by the project activity during this monitoring period. And by checking the VCS and CDM monitoring and verification reports for the previous monitoring periods[/27/,] it is confirmed the cumulative emission reductions are 554,999 tCO_2e during the first VCS monitoring period and this monitoring period. And according to the registered PDD, the project was expected to prevent the release of 1,740,680 tCO_2e into the atmosphere during the project operation lifetime of 20 years. This contributes to achieve one of China's stated sustainable development priorities "Actively adapt to climate change and strengthen resistance capacity to climate risks in agriculture, forestry, water resources and other key fields, as well as cities, coastal regions and ecologically vulnerable areas".

In conclusion, Verification Team was able to confirm that the project implementation is in accordance with the project description contained in the VCS PD. All required equipments and procedures are available and implemented in an appropriate manner. All necessary monitoring instruments are installed and operated. The project is completely operational and the same has been confirmed on-site. Neither mistakes nor malfunction on main meters have been observed during this monitoring period.

4.2 Safeguards

4.2.1 No Net Harm

Via on-site inspection and checking the EIA summary and conclusion provided in the approved VCS PD, it is confirmed that the impact caused by the project activity on the surrounding ecosystem and residents, wastewater, noise, solid waste and atmosphere etc. is very little, there would be no net harm caused due to the project activity. Appropriate mitigation measures have been undertaken by the project proponent to avoid the potential impacts during the construction and operation. The EIA of the project are approved by the government.

Also, no potential environment or social economic matter was found during the site visit. It is verified by interviewing with project proponent, staff and local villagers and checking the staff roster and monthly payroll[/22/], the Explanation of the employment offered by the project [/23/] and national poverty standard[/24/], that the project has contributed to the local employment and improved income levels by providing job opportunities and offering permanent employees wages well above poverty income levels. As stated by the plant staff during the on-site interviews, they have gained knowledge and skills in the regular training organised by the project proponent, so it can be judged that the project has, to some extent, improved the marketability of the employees as well as the possibility of lifelong learning for them.

4.2.2 Local Stakeholder Consultation

The local stakeholder's meeting was held in Zhujiajing Village on Mar 2011. 49 participants attended the meeting including local residents, builders and members of the local authorities. The project owner introduced the proposed project, and then a survey was arranged through a one-page questionnaire, which was designed to be easily filled in. The opinions expressed by the stakeholders were recorded and are available on request.

The stakeholder meeting and the survey showed that the proposed project receives strong support from the local community. They all believe the proposed project will promote local economic development and agree with the project development and construction.

For continuous communication with local stakeholders, the project owner public its office telephone to local people. Through interviewing with staff from local environmental protection bureau and local residents during the site visit, it is confirmed by the verification team that during the implementation stage of this monitoring period, local authority has conducted spot checks on the implementation of the project periodically as per the request from the local governments' regulations, no negative comments and issues from the local stakeholders during this monitoring period were identified and the project passed all the periodic spot checks by local government.

All such conclusion has been verified through site visit and checking VCS PD.

4.3 AFOLU-Specific Safeguard

The project is not AFOLU project.

4.4 Accuracy of GHG Emission Reduction and Removal Calculations

CQC confirms that appropriate methods and formulae for calculating baseline emissions, project emissions and leakage have been followed, and the assumptions, emission factors and default values that are applied in the calculation have been justified.

According to the applied methodology, the emission reductions are determined as the difference between the baseline emissions, project emissions and leakage:

$ER_y = BE_y - PE_y - L_y$

Baseline emissions

Baseline emissions are determined as multiplying quantity of net electricity supplied to the grid by the project during year y (EG_y) by the validated ex-ante fixed grid emission factor ($EF_{grid,CM,y}$).

$BEy = EG_y \times EF_{grid,CM,y}$

Grid emission factor ($EF_{grid,CM,y}$)

$EF_{grid,CM,y}$ is the grid emission factor of the which has been verified ex-ante in the validation stage in the VCS PD as 0.9309 tCO_2e/MW

The net electricity supplied to the grid by the project (EG_y)

As per the Section 4.1 above, EG_y is determined as:

The verification team has checked the daily and monthly reading records, electricity receipts, Confirmation letter for electricity readings issued by the grid company and emission reduction calculation sheet, and confirmed the data and calculation applied are correct, complete and transparent. The reading records and EG_y calculation are summarized in Table 1 as follow：

Table 1 Net electricity supplied to the Grid by the project

Monitoring period		Total electricity supplied to the Grid by the Project and Phase II Project ($EG_{output,y}$) unit: MWh			Total electricity imported from the Grid by the project and Phase II project through the 110kV line ($EG_{import,y}$) unit: MWh			Electricity imported from the Grid by the project and Phase II project through a spare 10 kV line ($EG_{im-spare}$) unit: MWh			Electricity generated by the Phase II Project ($EG_{another,y}$) unit: MWh	Net electricity supplied to the grid by the project ($EG_{facility}$) unit: MWh
From	To	Data based on meter readings M1	Data based on sales receipt	Conservative value	Data based on meter readings M1(110kV)	Data based on sales receipts	Conservative values	Data based on meter readings M4(10kV)	Data based on sales receipts	Conservative values	Data based on meter readings M3	Calculated by $EG_{output,y}$-$EG_{import,y}$-$EG_{im-spare,y}$- $EG_{another,y}$
		A	B	C=Min (A, B)	D	E	F=Min (D, E)	G	H	I=Max (G, H)	J	J=C-F-I-J
28/09/2012	25/10/2012	15800.810	15800.810	15800.810	39.327	102.004	102.004	0.429	0.429	0.429	8682.080	7,016.297
26/10/2012	25/11/2012	21600.480	21600.480	21600.480	30.360	29.04	30.360	0.461	0.461	0.461	11698.720	9,870.939
26/11/2012	23/12/2012	21933.120	21933.120	21933.120	27.720	35.640	35.640	0.461	0.461	0.461	12515.360	9,381.659
24/12/2012	31/12/2012	4709.760	4709.760	4709.760	7.920	6.93	7.920	0.115	0.115	0.115	2442.880	2,258.845
Subtotal 2012				64044.170			175.924			1.466	35339.040	28,527.740
01/01/2013	25/01/2013	19315.560	19315.560	19315.560	23.760	20.790	23.760	0.346	0.346	0.346	9368.480	9,922.974
26/01/2013	25/02/2013	11820.600	11820.600	11820.600	151.800	149.160	151.800	0.461	0.461	0.461	7084.000	4,584.339
26/02/2013	26/03/2013	26550.480	26550.480	26550.480	15.840	18.480	18.480	0.461	0.461	0.461	14490.080	12,041.459
27/03/2013	24/04/2013	28005.120	28005.120	28005.120	6.600	10.560	10.560	0.461	0.461	0.461	14414.400	13,579.699
25/04/2013	25/05/2013	24845.040	24845.040	24845.040	15.840	14.520	15.840	0.461	0.461	0.461	13221.120	11,607.619
26/05/2013	24/06/2013	19561.080	19561.080	19561.080	21.120	0.000	21.120	0.461	0.461	0.461	10797.600	8,741.899
25/06/2013	25/07/2013	17169.240	17169.240	17169.240	33.000	35.640	35.640	0.461	0.461	0.461	9275.200	7,857.939
26/07/2013	25/08/2013	10152.120	10152.120	10152.120	42.240	44.880	44.880	0.461	0.461	0.461	5427.840	4,678.939
26/08/2013	24/09/2013	11993.520	11993.520	11993.520	56.760	62.040	62.040	2.297	2.297	2.297	6246.240	5,682.943
25/09/2013	25/10/2013	18540.720	18540.720	18540.720	73.920	64.680	73.920	0.461	0.461	0.461	9584.960	8,881.379
26/10/2013	24/11/2013	17376.480	17376.480	17376.480	80.520	73.920	80.520	0.461	0.461	0.461	8780.640	8,514.859
25/11/2013	25/12/2013	21795.840	21795.840	21795.840	43.560	59.400	59.400	0.461	0.461	0.461	11114.400	10,621.579
26/12/2013	31/12/2013	4819.320	4819.320	4819.320	1.320	7.128	7.128	0.092	0.092	0.092	2826.560	1,985.540
Subtotal 2013				231945.120			605.088			7.345	122631.520	108,701.167
01/01/2014	24/01/2014	11274.120	11274.200	11274.120	33.000	28.512	33.000	0.369	0.369	0.369	6052.640	5,188.111
25/01/2014	25/02/2014	17651.040	17651.040	17651.040	40.920	36.960	40.920	0.461	0.461	0.461	9597.280	8,012.379

26/02/2014	25/03/2014	19215.240	19215.240	19215.240	34.320	40.920	40.920	0.461	0.461	0.461	9347.360	9,826.499
26/03/2014	25/04/2014	16573.920	16573.920	16573.920	92.400	68.640	92.400	0.461	0.461	0.461	9285.760	7,195.299
26/04/2014	26/05/2014	28915.920	28915.920	28915.920	35.640	54.120	54.120	0.461	0.461	0.461	14567.520	14,293.819
27/05/2014	24/06/2014	16312.560	16312.560	16312.560	62.040	46.200	62.040	0.461	0.461	0.461	8050.240	8,199.819
25/06/2014	26/07/2014	13211.880	13211.880	13211.880	50.160	71.280	71.280	0.461	0.461	0.461	7143.840	5,996.299
27/07/2014	26/08/2014	7539.840	7539.840	7539.840	91.080	75.240	91.080	0.461	0.461	0.461	3706.560	3,741.739
27/08/2014	25/09/2014	4623.960	4623.960	4623.960	120.120	122.760	122.760	0.461	0.461	0.461	2455.200	2,045.539
26/09/2014	26/10/2014	16060.440	16060.440	16060.440	33.000	44.880	44.880	0.461	0.461	0.461	8608.160	7,406.939
27/10/2014	24/11/2014	14810.400	14810.400	14810.400	81.840	75.240	81.840	0.461	0.461	0.461	7080.480	7,647.619
25/11/2014	25/12/2014	27009.840	27009.840	27009.840	39.600	52.800	52.800	0.461	0.461	0.461	14078.240	12,878.339
26/12/2014	31/12/2014	3033.360	3033.360	3033.360	22.440	11.886	22.440	0.086	0.086	0.086	1561.120	1,449.714
Subtotal 2014				196232.520			810.480			5.526	101534.400	93882.113
01/01/2015	25/01/2015	15265.800	15265.800	15265.800	40.920	47.514	47.514	0.375	0.375	0.375	8210.400	7,007.511
26/01/2015	25/02/2015	13902.240	13902.240	13902.240	68.640	62.040	68.640	0.461	0.461	0.461	7332.160	6,500.979
26/02/2015	25/03/2015	18724.200	18724.200	18724.200	36.960	40.920	40.920	0.461	0.461	0.461	9241.760	9,441.059
26/03/2015	25/04/2015	26071.320	26071.320	26071.320	18.480	23.760	23.760	6.083	6.083	6.083	13759.680	12,281.797
26/04/2015	25/05/2015	21658.560	21658.560	21658.560	30.360	29.040	30.360	0.461	0.461	0.461	11098.560	10,529.179
26/05/2015	25/06/2015	18256.920	18256.920	18256.920	40.920	34.320	40.920	0.461	0.461	0.461	9771.520	8,444.019
26/06/2015	25/07/2015	10775.160	10775.160	10775.160	43.560	51.480	51.480	0.461	0.461	0.461	5624.960	5,098.259
26/07/2015	25/08/2015	8338.440	8338.440	8338.440	89.760	72.600	89.760	3.766	3.766	3.766	4241.600	4,003.314
26/08/2015	25/09/2015	7213.800	7213.800	7213.800	85.800	89.760	89.760	22.177	22.177	22.177	3991.680	3,110.183
26/09/2015	25/10/2015	15859.800	15859.800	15859.800	54.120	52.800	54.120	20.222	20.222	20.222	7835.520	7,949.938
26/10/2015	25/11/2015	17589.000	17589.000	17589.000	59.400	71.280	71.280	8.108	8.108	8.108	9570.880	7,938.732
26/11/2015	26/12/2015	13702.920	13702.920	13702.920	21.120	15.840	21.120	9.858	9.858	9.858	6834.080	6,837.862
27/12/2015	31/12/2015	2566.080	2566.080	2566.080	6.600	11.220	11.220	0.077	0.077	0.077	1092.960	1,461.823
Subtotal 2015				189924.240			640.854			72.971	98605.760	90604.655
01/01/2016	26/01/2016	18068.160	18068.160	18068.160	54.120	56.100	56.100	0.384	0.384	0.384	9292.800	8,718.876
27/01/2016	24/02/2016	17657.640	17657.64	17657.640	40.920	43.560	43.560	0.461	0.461	0.461	9109.760	8,503.859
25/02/2016	26/03/2016	18757.200	18757.20	18757.200	29.040	29.040	29.040	0.461	0.461	0.461	10035.520	8,692.179
27/03/2016	25/04/2016	23687.400	23687.40	23687.400	31.680	29.040	31.680	0.461	0.461	0.461	12242.560	11,412.699
26/04/2016	26/05/2016	23040.600	23040.60	23040.600	30.360	26.400	30.360	0.461	0.461	0.461	11792.000	11,217.779

27/05/2016	24/06/2016	14506.800	14506.80	14506.800	48.840	52.800	52.800	0.461	0.461	0.461	7935.840	6,517.699
25/06/2016	26/07/2016	17466.240	17466.24	17466.240	46.200	50.558	50.558	1.383	1.383	1.383	8986.560	8,427.739
27/07/2016	26/08/2016	7702.200	7702.20	7702.200	91.080	71.280	91.080	0.461	0.461	0.461	4341.920	3,268.739
27/08/2016	26/09/2016	13700.280	13700.28	13700.280	79.200	97.680	97.680	0.461	0.461	0.461	6825.280	6,776.859
27/09/2016	26/10/2016	12980.880	12980.88	12980.880	80.520	71.280	80.520	1.619	1.619	1.619	6696.800	6,201.941
27/10/2016	26/11/2016	17926.920	17926.92	17926.920	52.800	59.400	59.400	0.461	0.461	0.461	9238.240	8,628.819
27/11/2016	26/12/2016	15553.560	15553.56	15553.560	68.640	51.480	68.640	0.461	0.461	0.461	8377.600	7,106.859
27/12/2016	31/12/2016	3340.920	3340.920	3340.920	14.520	16.720	16.720	0.077	0.077	0.077	1344.640	1,979.483
Subtotal 2016				204388.800			708.138			7.612	106219.520	97453.530
01/01/2017	26/01/2017	10350.120	10350.120	10350.120	67.320	83.600	83.600	0.384	0.384	0.384	6691.520	3,574.616
27/01/2017	26/02/2017	24303.840	24303.840	24303.840	48.840	47.520	48.840	0.461	0.461	0.461	11281.600	12,972.939
27/02/2017	26/03/2017	14939.760	14939.760	14939.760	26.400	23.760	26.400	0.461	0.461	0.461	7978.080	6,934.819
27/03/2017	26/04/2017	17109.840	17109.840	17109.840	54.120	54.120	54.120	0.461	0.461	0.461	9074.560	7,980.699
27/04/2017	26/05/2017	23114.520	23114.520	23114.520	43.560	43.560	43.560	0.461	0.461	0.461	11932.800	11,137.699
27/05/2017	20/06/2017	14199.240	14199.240	14199.240	40.920	40.920	40.920	0.461	0.461	0.461	7606.720	6,551.139
21/06/2017	20/07/2017	13824.360	13824.360	13824.360	33.000	33.000	33.000	1.148	1.148	1.148	7307.027	6,483.185
21/07/2017	20/08/2017	11556.600	11556.600	11556.600	102.500	102.960	102.960	0.461	0.461	0.461	5781.600	5,671.579
21/08/2017	20/09/2017	6585.480	6585.480	6585.480	100.320	100.320	100.320	2.999	2.999	2.999	3375.680	3,106.481
21/09/2017	20/10/2017	13152.480	13152.480	13152.480	67.320	67.320	67.320	0.461	0.461	0.461	6716.160	6,368.539
21/10/2017	20/11/2017	20602.560	20602.560	20602.560	64.680	64.680	64.680	0.461	0.461	0.461	11200.640	9,336.779
21/11/2017	20/12/2017	19080.600	19080.600	19080.600	40.920	40.920	40.920	0.461	0.461	0.461	10537.120	8,502.099
Subtotal 2017				188819.400			706.640			8.680	99483.507	88620.573
Total				1075354.250			3647.124			103.600	563813.747	507789.778

The corresponding baseline emission reductions during this monitoring period is calculated as:

Monitoring period		Net electricity supplied to the grid by the project ($EG_{facility}$) unit: MWh	Emission Factor ($EF_{grid,CM,y}$) unit: tCO_2e/MWh	Baseline Emission (BE_y) unit: tCO_2e
From	To			
28/09/2012	31/12/2012	28,527.740	0.9309	26,556
01/01/2013	31/12/2013	108,701.167	0.9309	101,189
01/01/2014	31/12/2014	93,882.113	0.9309	87,394
01/01/2015	31/12/2015	90,604.655	0.9309	84,343
01/01/2016	31/12/2016	97,453.530	0.9309	90,719
01/01/2017	20/12/2017	88,620.573	0.9309	82,496
Total		**507,789.778**	**-**	**472,697**

Project emission

As statement in the registered VCS PD, for the wind power activities, the project emissions from the project is zero. Hence, PE_y during the monitoring period from the Project is zero.

Leakages

Leakage does not need to be accounted for this project as per the monitoring methodology ACM0002 (version 12.2.0).

Emission reduction

The emission reductions for this monitoring period were calculated as:

Monitoring period	GHG emission reductions or removals (tCO_2e)
28/09/2012-20/12/2017	**472,697**
Total ERs claimed (in 1910 days)	**472,697**

Comparison of actual emission reductions or net anthropogenic GHG removals by sinks with estimates in registered VCS-PD.

During the monitoring period, the actual emission reduction of 1910 days is 472,697tCO_2e,which is 0.02% lower than the estimated emission reduction of 482,382tCO_2e, which will not cause the over estimation of emission reductions. The deviation is within a reasonable range.

Therefore, CQC is able to confirm that the actual power supply and also emission reductions reported in this monitoring period are reasonable and appropriate. CQC verified the input data for calculating emission reductions and the calculating process, and confirmed the result were complete and transparent.

4.5 Quality of Evidence to Determine GHG Emission Reductions and Removals

All necessary documentations are collected, referenced and aggregated, which is easily accessible in hard-copy or electronic format. Measurements are performed by calibrated equipment, and the key data can also be cross-checked via other sources, such as records, receipts and inventory data. No assumptions are used that have any material influence on reported emission reductions.

CQC concludes that during this monitoring period, the evidences for determination of emission reductions are sufficient and reasonable, and the calculation of emission reductions is reliable.

4.6 Non-Permanence Risk Analysis

The project is not AFOLU project, and thus non-permanence risk analysis is not applicable for the project.

5 VERIFICATION CONCLUSION

CQC has performed the verification of the emission reductions that have been reported for the project activity "QINGDAO LONGXIN WIND POWER PROJECT PHASE I" in China (VCS Project ID: 969) for the period 28-September-2012 to 20-December-2017.

The verification is based on the baseline and monitoring methodology ACM0002 (version 12.2.0), the VCS PD. The verification consisted of the following three phases: i) desk review of the project design and the baseline and monitoring plan; ii) follow-up interviews with project stakeholders; iii) resolution of outstanding issues and the issuance of the final verification and certification report.

Our verification approach was based on the requirements as defined under the applicable VCS Standard Version 4.3 and relevant UNFCCC requirements. Our approach is risk-based, drawing on an understanding of the risks associated with reporting GHG emissions data and the controls in place to mitigate these. The verification can confirm that:

- the project is implemented and operated as per the registered VCS PD ;
- the monitoring plan is as per the applied methodology;
- the monitoring complies with the monitoring plan;
- the monitoring report and other supporting documents provided are complete and verifiable and in accordance with the applicable VCS Standard Version 4.3 and CDM requirements;
- the installed equipment being essential for generating emission reduction runs reliably and is calibrated appropriately;

- the monitoring system is in place and generates GHG emission reductions data;

- the GHG emission reductions are calculated without material misstatements.

In CQC's opinion the GHG emissions reductions of the "QINGDAO LONGXIN WIND POWER PROJECT PHASE I" for the period 28/09/2012-20/12/2017 are fairly stated in the monitoring report(version 02 dated 30/08/2022). The GHG emission reductions were calculated correctly on the basis of the approved methodology ACM0002 (version 12.2.0) and the monitoring plan contained in the registered VCS PD.

CQC can confirm that the GHG emission reductions are calculated without material misstatements. Based on the evidence and information that are considered necessary to guarantee that GHG emission reductions are appropriately calculated, CQC confirms the following statement:

Reporting period: 28/09/2012-20/12/2017

Verified GHG emission reductions and removals in the above verification period:

Year	Baseline emissions or removals(tCO_2e)	Project emissions or removals (tCO_2e)	Leakage emissions (tCO_2e)	Net GHG emission reductions or removals(tCO_2e)
28/09/2012-31/12/2012	26,556	0	0	26,556
01/01/2013-31/12/2013	101,189	0	0	101,189
01/01/2014—31/12/2014	87,394	0	0	87,394
01/01/2015—31/12/2015	84,343	0	0	84,343
01/01/2016—31/12/2016	90,719	0	0	90,719
01/01/2017—20/12/2017	82,496	0	0	82,496
Total	**472,697**	**0**	**0**	**472,697**

APPENDIX A: REFERENCE

Documentation used to verify the information provided by the project proponents

/1/	Juno Carbon Investment & Environmental Technology (Beijing) Co., Ltd.: VER/VCU Monitoring Report for Qingdao Longxin Wind Power Project Phase I, version 02dated 30/08/2022
/2/	Juno Carbon Investment & Environmental Technology (Beijing) Co., Ltd.: Emission reduction calculation spreadsheet for Qingdao Longxin Wind Power Project Phase I, version2.0dated06/09/2022
/3/	China Resources Wind Power (Qingdao) Co., Ltd.:Purchase Agreement for Qingdao Longxin Wind Power Project Phase I
/4/	China Resources Wind Power (Qingdao) Co., Ltd.： Diagram of power connection system
/5/	China Resources Wind Power (Qingdao) Co., Ltd.: VER monitoring manual and management procedure.
/6/	China Resources Wind Power (Qingdao) Co., Ltd.: Records of training for on-site staff: Records of training for on-site staff.
/7/	China Resources Wind Power (Qingdao) Co., Ltd.: Daily operation and maintenance records.
/8/	China Resources Wind Power (Qingdao) Co., Ltd.: Monthly and daily reading records Qingdao Longxin Wind Power Project Phase I from 28/09/2012-20/12/2017
/9/	State Grid Shandong Power Company: Monthly electricity receipts from28/09/2012-20/12/2017& Confirmation letter for electricity readings the period 28/09/2012-20/12/2017 issued by the grid company
/10/	Comment records
/11/	Contact information of PP posted on the bulletin board of village committee
/12/	Yearly questionnaires for local stakeholders
/13/	China Resources Wind Power (Qingdao) Co.: Registered CDM PDD

/14/	State Grid Shandong Electric Power Metering Center/ Shandong Institute of Metrology : Calibration certificates for meters M1,M2 ,M3 and M4 covering this monitoring period
/15/	Business license of China Resources Wind Power (Qingdao) Co., Ltd.
/16/	State Economic and Trade Commission: Technical administrative code of electric energy metering (DL/T 448-2000, DL/T 448-2016)
/17/	UNFCCC, http://cdm.unfccc.int
/18/	Gold Standard, http://www.goldstandard.org/
/19/	China CCER Exchange Info-platform, http://cdm.ccchina.org.cn/ccer.aspx
/20/	Measures for the Administration of Carbon Emission Trading, issued by Ministry of Ecology and Environment of China, dated 31/12/2020
/21/	Enforced company list in China cap & trade scheme, issued by Ministry of Ecology and Environment of China
/22/	China Resources Wind Power (Qingdao) Co., Ltd.: Staff roster and payroll in 2017
/23/	China Resources Wind Power (Qingdao) Co., Ltd.: the Explanation of the employment offered by the project.
/24/	National poverty standard in 2008 and 2016 https://www.gpbctv.com/jrrd/202104/159842.html?btwaf=54204711
/25/	TÜV Rheinland (China) Ltd. : VCS Validation Report for the project
/26/	VER/VCU Monitoring Report for the project from 08/11/2011- 27/09/2012
/27/	TÜV Rheinland (China) Ltd.: VCS Verification Report for the project from 08/11/2011- 27/09/2012
/28/	China Resources Wind Power (Qingdao) Co., Ltd.: Nameplates of the equipment
/29/	Stakeholder Consultation Opinion Response policy of Qingdao Longxin Wind Power Project Phase I

/30/	Feasibility Study Report of Qingdao Longxin Wind Power Project Phase I
/31/	Photo of grievance book to collect comments about project implementation from local stakeholders
/32/	China Resources Wind Power (Qingdao) Co., Ltd.: Construction completion report of the Project
/33/	China Resources Wind Power (Qingdao) Co., Ltd.: Wind Turbines Purchase Agreement, dated31/03/2007: Wind Turbines Purchase Agreement

Methodologies, tools and other guidance

/37/	Verified Carbon Standard: VCS Standard, version 4.3
/38/	Verified Carbon Standard: VCS Program Guide, version 4.1
/39/	Verified Carbon Standard: VCS Sectoral Scopes http://v-c-s.org/node/448
/40/	Verified Carbon Standard: Registration and Issuance Process, version 4.1
/41/	UNFCCC EB: Approved methodology, ACM0002 , version12.2.0

APPENDIX B: CORRECTIVE ACTION REQUESTS, CLARIFICATION REQUESTS AND FORWARD ACTION REQUESTS

Table 1: Corrective Action Requests

CAR ID	Corrective Action Request	Response by Project Proponent	Verification Team Assessment
CAR 01	The monitoring period in the MR(from 28/09/2012 to 07/11/2021, which is more than six consecutive years) does not meet the requirements of rotation of validation/verification bodies in VCS-Standard_v4.3.	The monitoring period has revised from 28/09/2012-07/11/2021 to 28/09/2012-20/12/2017.	OK. It has been revised and verified by CQC by checking updated MR. Therefore, CAR 01 is closed.
CAR 02	The information of the monitoring meters installed during the monitoring period is not provided in the MR and supporting documents.	The information of the monitoring meters during this monitoring period have been added in the section 4.1 of the revised MR (V02, 30/08/2022). The main information are including the type, accuracy, serial number, calibration date, validity period and name of the calibration organization, and the meters' photo and the calibration reports covering this monitoring period have been submitted.	OK. It has been revised and verified by CQC by checking updated MR. Therefore, CAR 01 is closed.

Table 2: Clarification Requests

CL ID	Clarification Request	Response by Project Proponent	Verification Team Assessment

NA	NA	NA	NA

Table 3: Forward Action Requests

FAR ID	Forward Action Request	Response by Project Proponent	Verification Team Assessment
NA	NA	NA	NA