



VERIFICATION REPORT FOR SOLITUDE 16MW SOLAR PV



Document Prepared By: Carbon Check (India) Private Limited,

Unit No.: 1701, Logix Office Tower, Plot No.: BW - 58, Sector - 32, NOIDA (Uttar Pradesh) - 201301, India, Phone: +91 120 4373114

<http://www.carboncheck.co.in>

Project Title	Solitude 16MW solar PV
Version	Version 03
Report ID	CC IPL1488/FVR

Report Title	Verification report for Solitude 16MW solar PV
Client	Voltas Yellow Ltd
Pages	41
Date of Issue	04 November 2022
Prepared By	Carbon Check (India) Private Ltd.
Contact	Unit No.: 1701, Logix Office Tower, Plot No.: BW - 58, Sector - 32, NOIDA (Uttar Pradesh) - 201301, India, Phone: +91 120 4373114 Registered address: 2071/38, 2nd Floor, Naiwala, Karol Bagh, New Delhi – 110005 projects@carboncheck.co.in www.carboncheck.co.in
Approved By	Vikash Kumar Singh, Compliance Officer
Work Carried Out By	Anubhav Dimri (Team Leader, Technical Expert) Rishi Kishore Raychoudhury (Team Member, Technical Expert and Local Expert) R Saranya (Trainee Assessor) Shivaji Chakraborty (Technical Reviewer)

Summary:

Voltas Yellow Ltd has appointed the validation/verification body Carbon Check (India) Private Ltd. to perform verification of the registered Project Activity (VCS PA Reference Number: 2308 / UN PA 10483) “Solitude 16 MW solar PV” in Mauritius (hereafter “project activity”) for the second monitoring period from 01 May 2020 to 31 December 2021.

The main purpose of this project activity is to generate electricity through renewable energy sources (solar photovoltaic). Voltas Yellow is the promoter and project proponent of the project activity. The project activity involves installations of 59,376 number of solar modules of CSUN Make (59,376 numbers of 275 W aggregating to 16.328 MWp) located in Solitude near the village of Triolet in the north of Mauritius, in the district of Pamplemousses. The electricity generated from the solar PV plant is sold to the national grid of the host country, Mauritius – Central Electricity Board (CEB) grid operated

by CEB. The project achieved emission reductions of 39,578 tCO₂e for the monitoring period by displacing net 39,926 MWh amount of electricity from the generation-mix of power plants connected to the national grid, which is mainly dominated by thermal/fossil fuel-based power plant.

The purpose of the verification is to review the monitoring results and verify that monitoring methodology was implemented according to monitoring plan and monitoring data, used to confirm the reductions in anthropogenic emissions by sources is sufficient, definitive and presented in a concise and transparent manner. In particular, monitoring plan, monitoring report and the project's compliance with relevant VCS, UNFCCC and Host Party criteria are verified in order to confirm that the project has been implemented in accordance with previously registered design and conservative assumptions, as documented.

The verification scope is defined as an independent and objective review of the monitoring report (MR). The MR is reviewed against the relevant criteria and guidance documents provided by VCS which include the following: VCS Program Guide (v4.2, dated 22/06/2022), VCS Standard (v4.3, dated 22/06/2022), Program Definitions (v4.2, dated 22/06/2022), Registration & Issuance Process (v4.2, dated 22/06/2022) and in line with the VCS Validation and Verification Manual (v3.2, dated 19/10/2016) applicable at the time in order to confirm that the emission reductions produced during the monitoring period are in accordance with the project activity as provided in the registered VCS PD/B04/. The CDM approved methodology ACM0002, Version 20.0 has been applied for the project activity.

The verification consisted of the following three phases: i) a desk review of the Monitoring Report ii) On Site Audit Assessment; iii) the resolution of outstanding issues and internal technical review followed by the issuance of the final verification report and opinion. In the course of the verification process 03 CAR ,07 CLs and 01 FARs were raised, all the CARs and CLs are closed now. The list of Clarification and Corrective Actions Requests (CL, CAR and FAR) is presented in this report.

CC IPL confirms that the project is implemented in accordance with the validated VCS-PD and the monitoring plan; and then, claimed emissions reductions are calculated without material misstatements.

CC IPL has performed the verification of the project activity Solitude 16 MW Solar PV on the basis of all issues and criteria of VCS Standard version 4.3 and VCS Program Guide version 4.2 for VCS projects and also on the criteria given to provide for consistent project operations, monitoring and reporting. Hence, in CC IPL's opinion the project correctly applies the baseline and monitoring methodology ACM0002, version 20.0 and meets the relevant UNFCCC requirements for the CDM Methodology, Voluntary Carbon Standard requirements and the relevant host country criteria.

Therefore, CC IPL is able to certify that the emissions reductions from the Solitude 16 MW Solar PV project during the period from 01 May 2020 to 31 December 2021 amount to 39,578 tCO₂e. The year-wise break up of verified emission reduction is as below:

Year	Baseline emissions or removals (tCO ₂ e)	Project emissions or removals (tCO ₂ e)	Leakage emissions (tCO ₂ e)	Net GHG emission reductions or removals (tCO ₂ e)

2020 (01/05/2020 to 31/12/2020)	15,754	0	0	15,754
2021 (01/01/2021 to 31/12/2021)	23,824	0	0	23,824
Total	39,578	0	0	39,578

1	Introduction	7
1.1	Objective	7
1.2	Scope and Criteria	7
1.3	Level of Assurance.....	9
1.4	Summary Description of the Project	9
2	Verification Process	9
2.1	Method and Criteria.....	9
2.2	Document Review	10
2.3	Interviews	11
2.4	Site Inspections.....	14
2.5	Resolution of Findings	15
2.5.1	Forward Action Requests	15
2.6	Eligibility for Validation Activities	16
3	Validation Findings	16
3.1	Participation under Other GHG Programs	17
3.2	Methodology Deviations.....	17
3.3	Project Description Deviations.....	17
3.4	Grouped Project	17
4	Verification Findings	17
4.1	Project Implementation Status	17
4.2	Safeguards	19
4.2.1	No Net Harm	19
4.2.2	Local Stakeholder Consultation	19
4.3	AFOLU-Specific Safeguards	19
4.4	Accuracy of GHG Emission Reduction and Removal Calculations	19
4.5	Quality of Evidence to Determine GHG Emission Reductions and Removals	22
4.6	Non-Permanence Risk Analysis.....	26
5	Verification conclusion	26
	APPENDIX 1: REFERENCES	27
	APPENDIX 2: ABBREVIATIONS	28

APPENDIX 3: COMPETENCY CERTIFICATE	30
APPENDIX 4: LIST OF FINDINGS	33

1 INTRODUCTION

1.1 Objective

Voltas Yellow Ltd (Project Proponent) has appointed the VVB, CCIPL for the verification service for the CDM registered project activity – Solitude 16 MW Solar PV located in in Solitude near the village of Triolet in the north of Mauritius, in the district of Pamplemousses (hereafter referred to as “project activity”) against the requirement of VCS Program and Green Yellow SAS (hereafter referred as other entity) is helping for the monitoring report.

Verification is the periodic independent review and ex post determination of both quantitative and qualitative information by a Validation and Verification Body (VVB) of the monitored reductions in GHG emissions that have occurred as a result of the VCS project activity during a defined monitoring period (monitoring period 2).

The purpose of verification is to review the monitoring results and verify that the monitoring methodology was implemented according to the monitoring plan and monitoring data and used to confirm the reductions in emissions is sufficient, definitive and presented in a concise and transparent manner. Carbon Check’s objective is to perform a thorough, independent assessment of the registered projects activities. In particular, the monitoring plan, monitoring report and the project’s compliance are verified against the relevant criteria and guidance documents provided by VCS. This allows for the confirmation that the project has been implemented in accordance with the VCS PD/B04/ and conservative assumptions, as documented. And, also to confirm if the monitoring plan is in compliance with the VCS PD/B04/ and approved monitoring methodology, ACM0002, version 20.0/B02/. The objective of this verification was to verify and certify emission reductions reported for the Solitude 16.328 MW Solar PV for the period 01/05/2020 to 31/12/2021.

1.2 Scope and Criteria

The verification of this project is based on the registered Project Description/B04/, the Monitoring Report of this monitoring period /02/, emission reduction calculation spread sheet /04/, supporting documents made available to the verifier and information collected through performing interviews and during the On-Site assessment. Furthermore, publicly available information was considered as far as available and required.

Carbon Check has employed a risk-based approach in the verification, focusing on the identification of significant risks and reliability of project monitoring and generation of emission reductions.

The verification is carried out based on the following requirements (latest available on VCS website at the time of verification), applicable for this project activity:

- VCS Program Guide (v4.2, dated 22/06/2022)
- VCS Standard (v4.3, dated 22/06/2022)
- Program Definitions (v4.2, dated 22/06/2022)
- Registration & Issuance Process (v4.2, dated 22/06/2022)
- VCS Validation and Verification Manual (v 3.2, dated 19/10/2016)
- CDM Methodology: ACM0002: Grid-connected electricity generation from renewable sources --- Version 20
- Other relevant rules, including the host country legislation

The scope of this verification, by independent checking of objective evidence, is as follows:

- To verify that the project is implemented as described in the project description
- To assess the project's compliance with other relevant rules including the host country legislation.
- To assess the implementation of the monitoring plan content as mentioned in the VCS-PD/B04/
- To confirm that the monitoring system is implemented and fully functional to generate voluntary emission reductions (VERs/VCUs) without any double counting and
- To establish that the data reported are accurate, complete, consistent, transparent and free of material error or omission by checking the monitoring records and the emissions reduction calculation /03/, /04/.
- To evaluate the GHG emission reduction data and express a conclusion with a reasonable level of assurance about whether the reported GHG emission reduction data is free from material misstatement.
- To verify that reported GHG emission data is sufficiently supported by evidence.

The verification shall ensure that the reported emission reductions are complete and accurate in order to be certified.

The method and criteria used for verification consisted of the following phases:

1. Completeness check and desk review:
2. Onsite audit assessment;

3. Resolution of outstanding issues and issuance of final verification report and applicable VCS Validation and Verification Deeds of Representation.

Carbon Check (India) Private Ltd. conducts all its work under strict rules to safeguard impartiality and ensure the independence of the verification team. The verification does not provide any consulting or recommendations for the client. However, stated requests for clarifications and/or corrective actions may provide input for improvement of the monitoring activities.

1.3 Level of Assurance

☒ Reasonable level of assurance

☐ Limited level of assurance

The level of assurance of the verification report falls under reasonable assurance engagements as selected by the Client. The verification team verified the complete monitoring data for all the parameters of the monitoring plan and confirms that the reported emission reductions are free from any type of material errors.

1.4 Summary Description of the Project

The project activity Solitude 16MW solar PV is a Greenfield project activity consisting of a 16 MW (16.328 MWp) solar photovoltaic power plant which involves generation of grid-connected renewable energy. The power plant is connected to the Central Electricity Board (CEB) grid of Mauritius. The project is located in Solitude near the village of Triolet in the north of Mauritius. The start date for the project is 19/12/2018, the date of commissioning on which the project activity is connected to the grid and begins generating GHG emission reductions.

The total emission reductions for the reported monitoring period 01/05/2020 to 31/12/2021 are 39,578 tCO₂e.

2 VERIFICATION PROCESS

2.1 Method and Criteria

The method and criteria used for verification:

The verification consists of the following three phases:

1. Completeness check and desk review of the validation report, monitoring plan, monitoring report, monitoring methodology, CDM PDD/VCS PD, applicable tools in particular attention to the frequency of measurements, quality of metering equipment's including calibration requirements, QA/QC procedures and other relevant documents.

2. On Site audit (including verification of monitoring plan, cross checking of technical description of plant equipment including Solar Modules, Inverters, Transformers etc. verification of details of electricity meters. follow-up interviews with project stakeholders, when deemed necessary). The on-site audit assignment includes the following:
- An assignment of implementation and operation of project activity with respect to validated CDM PDD/VCS PD;
 - Review of information flows for generating, aggregating and reporting the monitoring parameters;
 - Interview with relevant personals to determine whether the operational and data collection procedures are implemented and in accordance with monitoring plan of the validated CDM PDD/VCS PD;
 - Cross check of information and data provided in the monitoring report with plant SCADA system, inventories, purchase records or similar data sources;
 - Check of monitoring equipment's, calibration frequency and monitoring practice in-line with methodology and validated CDM PDD/VCS PD; Review of assumptions made in calculating the emission reduction;
 - Implementation of QA/QC procedure in-line with the validated CDM PDD/VCS PD and methodology requirement.

Resolution of outstanding issues and the issuance of the final Verification report and if applicable, the VCS Validation and Verification Deeds of Representation.

2.2 Document Review

The registered VCS PD/B04/, VCS MR /01/, /02/, emission reduction calculation spread sheet/03/, /04/ and supporting documents related to the project implementation, project design, monitoring and baseline were reviewed as per VCS version 04.2 standard requirements. The desk review included:

- A review of the data and information presented to verify completeness and consistency in accordance with VCS version 04 requirements/B01/;
- A review of the approved monitoring plan and monitoring methodology, paying particular attention to the frequency of measurements, quality of monitoring equipment (including calibration requirements) and the quality assurance and quality control (QA/QC) procedures;
- An evaluation of data management and the QA/QC system in the context of their influence on the generation and reporting of emission reductions.

Data input values were also checked from the records maintained by the project proponents. Results of calculations reported in the monitoring report were checked against data values as available from the project proponent in VER calculation sheet /03/, /04/.

These data values and other information related to project performance are available in the form of data records duly archived and maintained as per the quality assurance/quality control procedure specified as a part of monitoring plan in the registered VCS-PD/B04/.

Furthermore, the verification team used additional documentation by third parties like host-party legislation, technical reports referring to the project design or to the basic conditions and technical data.

2.3 Interviews

An on-site audit of the project activity was undertaken on 22/09/2022 to assess the implementation and operation of the project activity and to review evidence, and interview key personnel to confirm evidence associated with the data generation, aggregation, and calculation and reporting of the monitoring parameters. The remote audit assessment addressed:

- An assessment of the project implementation and operation as per the VCS PD/B04/ (including physical inspection to confirm physical existence and operation of project components);
- Review of information flows for generating, aggregating and reporting the monitoring parameters;
- Interviews with relevant personnel to confirm that the operational and data collection procedures are implemented in accordance with the monitoring plan in the monitoring report /01/, /02/.

The key personnel interviewed, and the main topics of the interviews are summarized in the table below:

	Date	Name	Organisation	Topic
/a/	22/09/2022	Ramchand Coonjul (Kiran)	GreenYellow Mauritius	• Project Design • Project Implementation and Operation status • Project start date and Project Location • Roles and responsibility, Project

				Implementation and Operation status, Qualification and Training, Roles and responsibility. - Grievance Mechanism and Local Stakeholder Consultation - Involved in Emissions Trading Programs and Other Binding Limits or Other Forms of Environmental Credit.
/b/	22/09/2022	Gopika Callychurn	GreenYellow Mauritius	- CER calculation and completeness of monitoring report, Electronic Monitoring system - Project implementation and operation, Project design, monitoring procedure, data and information flow, compliance of monitoring plan with monitoring methodology and approved CDM PDD/VCS-PD. - Project Implementation status - Monitoring and operating system

				• Quantification of emission reductions • Monitoring parameters • Emission factor for the grid • Roles and responsibility
/c/	22/09/2022	Josian Arlanda	GreenYellow Mauritius	• Project design • PV details • Monitoring plan • Monitoring procedures and monitoring equipment • Maintenance and operation plan • Data and information flow, Data input device, Roles and responsibility, Project implementation and operation, monitoring procedure.

2.4 Site Inspections

VVB has conducted an on-site visit for the verification of the project activity. During on-site visit the VVB has verified the monitoring plan with accordance to the registered VCS PD/MR and based on the desk review of documentation VVB can achieve a reasonable level of assurance, that is in conformance with the VCS rules.

Following points has been considered during the on-site visit:

- 1) An assessment of the implementation and operation of the project activity as per the registered VCS PD /B04/
- 2) A review of information aggregating and reporting of the monitoring parameters
- 3) Interviews with relevant personnel to confirm that the operational and data collection procedures are implemented in accordance with the MP (section 2.3 above)
- 4) A cross-check between the electricity sales information provided in the MR /01/ and data from other sources (section 2.3 above).
- 5) A check of the monitoring equipment including calibration performance, and observations of monitoring practices against the requirements of the VCS PD and the applied monitoring methodologies /B02/
- 6) A review of calculations and assumptions made in determining the GHG data and ERs /02/, and
- 7) An identification of QA/QC procedures in place to prevent, or identify and correct, any errors or omissions in the reported monitoring parameters
- 8) The duly calibration/testing of all metering equipment was checked.
- 9) The monitoring processes, routines and documentations were audited to check their proper application.
- 10) The monitoring data were checked completely.

The verification team carried out on-site interviews with representatives of PP to assess the information included in the project documentation and to gain additional information regarding the compliance of the project with the relevant criteria applicable for the VCS.

During the on-site audit assessment, all monitoring data with respect to accuracy to ensure the calculation of emission reductions was checked. All the procedures and records were found authenticated and properly maintained as per the requirements of the project.

The verification team has carried out interviews in order to assess the information included in the project documentation and to gain additional information regarding the compliance of the project with the relevant criteria applicable for the VCS.

2.5 Resolution of Findings

Material discrepancies identified in the course of the verification are addressed either as CARs, CLs or FARs. Corrective action requests (CAR) are issued, where:

- i. Mistakes have been made with a direct influence on project results requiring adjustments of the VERs/VCUs monitoring report;
- ii. Applicable methodological specific requirements have not been met.

A Clarification request (CL) may be used where additional information is needed to fully clarify an issue or where the information is not transparent enough to establish whether a requirement is met.

A forward action request (FAR) should be issued, where:

- i. The actual project monitoring and reporting practices requires attention and /or adjustment for the next consecutive verification period, or
- ii. An adjustment of the MP is recommended.

In the context of FARs, risks have been identified, which may endanger the delivery of high-quality emissions reductions in the future, i.e. by deviations from standard procedures as defined by the MP. As a consequence, such aspects should receive a special focus during the next consecutive verification. A FAR may originate from lack of data sustaining claimed emission reductions.

A total of 03 CARs, 07 CLs and 01 FARs was raised for the verification of the project activity and all are closed. The findings are provided in Appendix 4.

2.5.1 Forward Action Requests

Finding	FAR 01		
Classification	☐ CAR	☐ CL	☒ FAR
Description of finding (VVB)	PP shall conduct awareness program on the renewable energy and carbon credit to their maintenance team and this shall be checked at the time of next periodic verification.		
Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further	This comment has been duly noted.		

information for clarification as per finding)	
VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	In accordance with the forward action request, the PP shall conduct awareness program for the maintenance team. FAR01 shall be checked at the time of the next periodic verification.
Conclusion Tick the appropriate checkbox	☒ To be checked during the next periodic verification ☐ Outstanding finding (not closed) ☐ The finding is closed

2.6 Eligibility for Validation Activities

Validation/Verification body (VVB), Carbon Check (India) Private Ltd. holds accreditation for validation for the relevant sectoral scope 1 and is eligible for validation/verification for the project activity.

3 VALIDATION FINDINGS

3.1 Participation under Other GHG Programs

It has been confirmed through the description in PD /B04/, MR/02/ and through interviews (section 2.3) that the project activity is registered with CDM (UNPA 10483). PP is not claiming emission reductions for the same monitoring period in both the programs. PP has clarified that the monitoring report was webhosted with CDM, however, the issuance request has not been submitted for the same. PP has also provided a declaration/14/ to confirm that double counting does not take place during the monitoring period.

3.2 Methodology Deviations

Not Applicable.

3.3 Project Description Deviations

Not Applicable.

3.4 Grouped Project

Not Applicable.

4 VERIFICATION FINDINGS

4.1 Project Implementation Status

The project activity, “Solitude 16 MW solar PV” was registered as a CDM project activity with UNPA reference number 10483 with the application of methodology ACM0002 version 20. The project was subsequently registered with VCS ID 2308 applying the methodology ACM0002, version 20, “Grid-connected electricity generation from renewable sources” /B02/. The Project Proponent for the project activity is Voltas Yellow Ltd. VCS verification is being conducted with reference to the applied methodology ACM0002 version 20.

The project activity involves an installation of 59,376 number of solar modules of CSUN make (59,376 of 275 W aggregating to 16.328 MWp) /02/. The solar PV plant is located in the district of Pamplémousses, Mauritius. The site is in Solitude, which is near the village Triolet. Verification team confirmed from the registered VCS PD/B04/ and remote audit that the location of the project activity including the coordinates is same as mentioned in the registered VCS PD/B04/.

The project boundary includes the electricity generation equipment at the site and substation located at JINFEI operated by CEB (the national grid of the host country), Mauritius.

The ex-ante fixed grid emission factor of 0.9915 tCO₂/MWh has been used for the baseline emission calculation, which is line with the registered VCS PD and CDM PDD /B04/.

The registered VCS-PD/B04/ clearly describes the monitoring and responsibility of monitoring is with PP. During the remote audit, monitoring and reporting procedures were confirmed with the relevant staff and through the document review.

PP has also provided a declaration to confirm that double counting does not take place during the monitoring period /14/.

The monitoring plan is in accordance with the UNFCCC approved methodology ACM0002, version 20/B02/. All the data is collected and archived in accordance with the methodology and included in the monitoring plan. The monitoring has been carried out in accordance with the provision of monitoring plan, the verification team reviewed if:

- The monitoring of reductions in GHG emissions resulting from the proposed VCS project activity were implemented in accordance with the monitoring plan contained in the registered VCS-PD/B04/.
- The monitoring plan and the applied methodologies had been properly implemented and followed by the project participants.
- All parameters stated in the monitoring plan, the applied methodologies and relevant CDM and VCS requirements had been sufficiently monitored and updated.
- The responsibilities and authorities for monitoring and reporting were in accordance with the responsibilities and authorities stated in the monitoring plan.

The GHG emission reductions generated by the project activity are not included in an emissions trading program or any other mechanism that includes GHG allowance trading, this has been confirmed from the review of the PD/B04/ and confirmed during the remote audit. The project activity has not received or sought any other form of environmental credit, this has been confirmed from the review of the PD/B04/ and confirmed during the remote audit.

The sustainable development contribution of the project activity to the host country, Mauritius have been provided in the PD/B04/ and the contributions were confirmed with the PP during the remote audit. The main sustainable development contributions have been listed under Energy security and supply, Health, Employment opportunities and Technology transfer.

Overall, the project has been implemented in accordance with the registered VCS-PD/B04/.

4.2 Safeguards

4.2.1 No Net Harm

No negative environmental and social impacts have been identified by the project proponent for the project activity, thus there exists no net harm to the project activity. This was also confirmed through the review of the VCS PD/B04/, MR/02/ and confirmed during the remote audit.

4.2.2 Local Stakeholder Consultation

PP has confirmed that no comments have been received from the local stakeholders during the reported monitoring period. Local stakeholder consultation has been carried out for the project activity at the time of the project validation and found appropriate.

Verification team confirms that the local stakeholder consultation conducted meets the requirements as provided.

PP has also provided for a continuous grievance mechanism process for the project activity. The details for the project proponent and the environmental assessment practitioner have been provided for the continuous grievance mechanism. During the reported monitoring period (01 May 2020 to 31 December 2021), no LSC comments were received. PP has provided the Environmental and Social Report, 2021/15/ as *evidence* to confirm that no comments related to the project activity *have been received* during grievance process.

4.3 AFOLU-Specific Safeguards

Not Applicable.

4.4 Accuracy of GHG Emission Reduction and Removal Calculations

The total Emission Reductions for the project activity are calculated as:

Emission reductions = Baseline emission – Project emission – Leakage

Being a solar PV project, the project activity does not lead to any form of emission; Hence Project Emission (PE_y) =0.

Also, the leakage for the project activity is nil as per the registered CDM PDD, the VCS PD and the applied methodology. Hence Leakage (Ly) =0

So, Emission Reductions = Baseline Emissions

The Baseline Emissions (BE_y) are calculated as follows:

$$BE_y = EG_{PJ,y} \times EF_{grid,CM,y}$$

Where:

BE_y = Baseline emissions in year y (t CO₂/yr)

$EG_{PJ,y}$ = Quantity of net electricity generation that is produced and fed into the grid as a result of the implementation of the CDM project activity in year y (MWh/yr)

$EF_{grid,CM,y}$ = Combined margin CO₂ emission factor for grid connected power generation in year y calculated using the latest version of the “Tool to calculate the emission factor for an electricity system” (tCO₂/MWh)

Since the project activity consists in the installation of new grid-connected renewable power plant at site where no renewable power plant was operated prior to the implementation of the project activity, it verifies the case of Greenfield renewable energy power plant, option (a) whereby:

$$EG_{PJ,y} = EG_{facility,y}$$

Where:

$EG_{PJ,y}$ = Quantity of net electricity generation that is produced and fed into the grid as a result of the implementation of the CDM project activity in year y (MWh/yr)

$EG_{facility,y}$ = Quantity of net electricity generation supplied by the project plant/unit to the grid in year y (MWh/yr)

The verification team has determined whether the registered monitoring plan in the VCS PD and CDM PDD /B04/ has been properly implemented and followed by the PP and whether all parameters fixed ex-ante for emission reduction calculation are as per the registered PDD /B04/. The verification team's assessment of each data and parameter fixed ex-ante is provided below:

Parameter	Description	Value	Unit	Source	Assessment
$EF_{grid,CM,y}$	Combined margin CO ₂ emission factor for grid connected power generation in year y calculated using the latest version of the “Tool to calculate the emission factor for an electricity system”	0.9915	tCO ₂ e /MWh	Representatives of Ministry of Energy of Mauritius	The emission factor is fixed for the 1st renewable crediting period and shall be revised at the renewal of each crediting period. The value is consistent with registered CDM PDD and VCS PD/B04/ and fixed ex-ante for the project activity.
$EF_{grid,OM,y}$	Operating Margin CO ₂ emission factor for	1.0282	tCO ₂ e /MWh	IGES list of grid emission factors	The parameter is used for the ex-ante calculation of the emission factor for the project activity. The

	grid connected power generation in year y calculated using the latest version of the “Tool to calculate the emission factor for an electricity system”				emission factor is fixed for the 1st renewable crediting period and shall be revised at the renewal of each crediting period. The value is consistent with registered CDM PDD and VCS PD/B04/ and fixed ex-ante for the project activity.
EF _{grid,BM,y}	Build Margin CO2 emission factor for grid connected power generation in year y calculated using the latest version of the “Tool to calculate the emission factor for an electricity system”	0.8814	tCO2e /MWh	IGES list of grid emission factors	The parameter is used for the ex-ante calculation of the emission factor for the project activity. The emission factor is fixed for the 1st renewable crediting period and shall be revised at the renewal of each crediting period. The value is consistent with registered CDM PDD and VCS PD/B04/ and fixed ex-ante for the project activity.
The percentage share of total installed capacity of solar PV	The percentage share of total installed capacity of the solar PV in the total installed grid connected power generation capacity in	2.6	%	http://publicutilities.govmu.org	The parameter is used for additionality demonstration at ex-ante stage. The value is consistent with registered CDM PDD and VCS PD/B04/ and fixed ex-ante for the project activity.

	the host country.				
The total installed capacity of solar PV	The total installed capacity of the solar PV in the host country.	21.2	MW	http://publicutilities.govmu.org	The parameter is used for additionality demonstration at ex-ante stage. The value is consistent with registered CDM PDD and VCS PD/B04/ and fixed ex-ante for the project activity.

The values are consistent with the registered VCS PD/B04/ and defined fixed ex-ante during 1st renewable crediting period of the project activity. The fixed ex-ante data and parameter have been listed in the monitoring report/02/ and confirmed by the verification team as correct and consistent with that stated in the registered VCS PD/B04/. The verification team confirms that the MR/02/ and the ER calculation spreadsheet/04/ have considered the parameters fixed ex-ante correctly.

4.5 Quality of Evidence to Determine GHG Emission Reductions and Removals

CCIPL was able to confirm that the calculations are based on authentic data. The spreadsheets/04/ used to calculate the VCU calculations and all figures were tracked, cross checked with actual reported data from the CEB invoices and found to be consistent.

The quality of supporting evidence submitted to the VVB for verification is adequate and found to be verifiable. The transfer of carbon rights and other supporting documents related to quality and maintenance were checked by the verification team during the remote audit to confirm the authenticity of the documents and to check the correctness of the calculation.

When verifying the reported emission reductions, CCIPL ensured that there was a clear audit trail that contained the evidence and records that validate the stated figures. All source documents that form the basis for assumptions and other information underlying the GHG data were checked by the verification team.

When assessing the audit trails, CCIPL also examined:

1. Whether sufficient evidence was available, both in terms of frequency and in covering the full monitoring period
2. The source and nature of the evidence
3. If comparable information was available from sources other than that used in the monitoring report, CCIPL cross-checked the monitoring report against the other sources to confirm that the stated figures were correct.

CCIPL also assessed that the data collection system met the requirements of the monitoring plan as per the applied methodology.

Proper data management inclusive of data acquisition and aggregation, data management system is being followed for the project activity.

The monitoring personnel at site are well trained and follow reproducible routines. Thus, they are competent to carry out the relevant tasks with sufficient accuracy.

Monitored Parameters

Data / Parameter	Quantity of net electricity generation supplied by the project plant/unit to the grid in year y (EGfacility,y)		
Measuring frequency	Continuous measuring		
Recording frequency	At least Monthly recording		
Is measuring and reporting frequency in accordance with the monitoring plan and monitoring methodology? (Yes / No)	Yes		
Type of monitoring equipment	Bi-directional electricity Meters (installed at JINFEI substation). The configuration of the meters is as provided below: Main meter Make: EDM I Model: MK6E Accuracy class: 0.2S Serial number of main meter: 16538506 Backup meter Make: EDM I Model: MK6E Accuracy class: 0.2S Serial number of backup meter: 16538507		
Value(s) of monitored parameter	2020	2021	Total
	15,893	24,033	39,926
Is accuracy of the monitoring equipment as stated in the PDD?	Yes, the accuracy of the monitoring equipment is as stated in the VCS PD/B04/.		
Calibration frequency /interval	The state electricity regulator, CEB is responsible for the certification of CEB Meters through an accuracy test at least once every 4 (four) years thereafter or at		

	any time the readings of Net Energy from the CEB Meter and Seller Back-up Meter differ by an amount greater than 0.5%. The initial calibration/08/ conducted on 22/06/2020 is still valid during the monitoring period (valid upto 21/06/2024). CEB has also conducted inspection of the meters at least once after installation. The records for inspection/16/, dated 21/06/2021 have been provided to the verification team and the meters were found to be functioning correctly during the monitoring period.
Is the calibration interval in line with the monitoring plan of the PDD?	Yes, the QA/QC procedures from the registered CDM PDD and VCS PD/B04/ have been followed.
Company performing the calibration	The calibrations are performed by CEB (state regulator) prior to installation.
Did calibration confirm proper functioning of monitoring equipment? (Yes / No)	Yes, the calibrations confirmed proper functioning of the main meter and backup meter. The state electricity regulator, CEB is responsible for the certification of CEB Meters through an accuracy test at least once every 4 (four) years thereafter or at any time the readings of Net Energy from the CEB Meter and Seller Back-up Meter differ by an amount greater than 0.5%. The initial calibration/08/ conducted on 22/06/2020 is still valid during the monitoring period (valid upto 21/06/2024). CEB has also conducted inspection of the meters at least once after installation. The records for inspection/16/, dated 21/06/2021 have been provided to the verification team and the meters were found to be functioning correctly during the monitoring period.
Is(are) calibration(s) valid for the whole reporting period?	The state electricity regulator, CEB is responsible for the certification of CEB Meters through an accuracy test at least once every 4 (four) years thereafter or at any time the readings of Net Energy from the CEB Meter and Seller Back-up Meter differ by an amount greater than 0.5%. The initial calibration/08/ conducted on 22/06/2020 is still valid during the monitoring period (valid upto 21/06/2024). CEB has also conducted inspection of the meters at least once after installation. The records for inspection/16/, dated 21/06/2021 have been provided to the verification team and the meters were found to be functioning correctly during the monitoring period.
If applicable, has the reported data been crosschecked with other available data?	Yes, the reported data has been cross-checked with the electricity sales invoices/08/ in accordance with the QA/QC procedures provided in the section B.7.1 of the registered CDM-PDD and VCS PD/B04/.
How were the values in the monitoring report verified	The values in the monitoring report were verified through the comparison with the values in the ER

	sheet/04/ and the raw data provided therein, and cross checked with the electricity sales invoices/06/.
Does the data management (from monitoring equipment to emission reduction calculation) ensure correct transfer of data and reporting of emission reductions and are necessary QA/QC processes in place?	Yes, the data management ensures correct transfer of data and reporting of emission reductions and are necessary QA/QC processes in place.

The verification team can confirm that sufficient evidence is available for the whole monitoring period and the same is verifiable and that the data collection system meets the requirements of the monitoring plan and the applied methodology according to the assessment carried out during the remote audit and in the document review.

Verification team confirms that the quality of evidence to determine the GHG reductions and removals produced was found satisfactory. The detailed information flow with the roles and responsibilities of the individuals and the monitoring system have been provided in the VCS-MR/02/.

4.6 Non-Permanence Risk Analysis

Not applicable.

5 VERIFICATION CONCLUSION

Carbon Check (India) Private Limited has performed the verification of the grouped project activity “Solitude 16 MW solar PV” in Mauritius, with regards to the relevant requirements for VCS project activities.

The conclusions can be summarised as follows:

- The project is implemented and installed as planned and described in the registered CDM-PDD and VCS PD/B04/ and the project activity confirms with the verification criteria for project and their GHG emission reductions or removals set out in the VCS rules.
- The monitoring plan is in accordance with the applied approved methodology, i.e. ACM0002, version 20/B02/ and monitoring plan as sought out in the registered CDM PDD and VCS-PD/B04/.
- The monitoring system is in place and functional. The project has generated verifiable GHG emission reductions.

As the result of the verification of project activities, the verifier confirms that the GHG emission reductions are calculated without material misstatements in a conservative and appropriate manner. Carbon Check (India) Private Ltd. herewith confirms that the project has achieved emission reductions in the below mentioned reporting period as follows. The project complies with the verification criteria for projects and their GHG emissions reductions or removals set out in VCS rules.

Verification period: From 01-May-2020 to 31-December-2021

Verified GHG emission reductions and removals in the above verification period:

Year	Baseline emissions or removals (tCO ₂ e)	Project emissions or removals (tCO ₂ e)	Leakage emissions (tCO ₂ e)	Net GHG emission reductions or removals (tCO ₂ e)
2020	15,754	0	0	15,754
2021	23,824	0	0	23,824

Total	39,578	0	0	39,578
-------	--------	---	---	--------

APPENDIX 1: REFERENCES

S. No.	Document
/01/	Monitoring report version 1.1, dated 02/08/2022
/02/	Monitoring Report (final) version 1.4, dated 03/11/2022
/03/	ER spread sheet corresponding to /01/
/04/	ER spread sheet corresponding to /02/
/05/	Electricity generation records (for total hours and any downtimes)
/06/	Electricity Sales/ Purchase Invoices for the period 01/05/2020 to 31/12/2021
/07/	Electricity meter specifications (Main Meter, Backup Meters)
/08/	Electricity meters calibration certificates/ records
/09/	Photographs of all the electricity meters
/10/	Technical specifications from the manufacturer for: 1. Solar panels 2. Inverters 3. Transformer
/11/	Line diagram for metering location
/12/	Organisation Structure
/13/	Plant layout
/14/	Undertaking on double counting from the PP, dated 10/08/2022
/15/	Environmental and social report 2021
/16/	Electricity meters annual inspection record conducted by CEB for main meter and check meter: dated 21/06/2021
/B01/	1. VCS Standard, version 04.3 2. VCS Program Guide version 04.2 3. VCS Validation and Verification Manual, version 03.2 4. Registration and Issuance Process v4.2 5. VCS Program Definitions version 04.2
/B02/	Large Scale CDM Methodology ACM0002: Grid-connected electricity generation from renewable sources, Version 20.0
/B03/	1. VCS MR Template
/B04/	Registered CDM PDD (version 1.4 dated 02/05/2019 and the corresponding Validation Report VCS PD (version 1.2 dated 08/09/2020)

APPENDIX 2: ABBREVIATIONS

BAU	Business As Usual
-----	-------------------

CA	Corrective Action / Clarification Action
CER	Certified Emission Reduction
CAR	Corrective Action Request
CC IPL	Carbon Check (India) Private Ltd.
CDM	Clean Development Mechanism
CEB	Central Electricity Board
CER	Certified Emission Reduction
CL	Clarification Request
CO ₂	Carbon Dioxide
CO ₂ e	Carbon Dioxide Equivalent
CSUN	China Sunergy Co Ltd
DOE	Designated Operational Entities
DVR	Draft Validation Report
EB	CDM Executive Board
EF	Emission Factor
FA	Final Approval
FAR	Forward Action Request
FVR	Final validation Report
GHG	Greenhouse gas(es)
GWh	Giga Watt Hour
IPCC	Intergovernmental Panel on Climate Change
MW	Megawatts
MWh	Mega Watt Hour
OSV	On Site Visit
PV	Solar Photovoltaic
QC/QA	Quality control/ Quality assurance
TA	Technical Area
TR	Technical Review
UNFCCC	United Nations Framework Convention on Climate Change
VER	Verified Emission Reduction
VCS	Verified Carbon Standard
VCU	Verified Carbon Units
VVB	Validation / Verification Body

APPENDIX 3: COMPETENCY CERTIFICATE



Carbon

CHECK

Carbon Check (India) Private Ltd.

Mr. Anubhav Dimri


has been qualified as per CCIPL's internal qualification procedures, in accordance with requirements of Accreditation Standard (version 07.0):

For following functions:


Validator	☒	Team Leader	☒	Technical reviewer	☒
Verifier	☒	Technical Expert	☒	Local Assessor ¹	☒

In the following Technical Areas:

TA 1.1	☒	TA 4.1	☐	TA 9.1	☐	TA 13.1	☒
TA 1.2	☒	TA 5.1	☐	TA 9.2	☐	TA 13.2	☐
TA 3.1	☒	TA 5.2	☐	TA 10.1	☐	TA 14.1	☐



Mr. Vikash Kumar Singh
Compliance Officer



Mr. Amit Anand
CEO

Date of Approval
24/12/2021

Valid Till
23/12/2022

Revision History of the Document

01/03/2020 ²	Interim Revision for office address change
01/09/2020	Interim Revision for CCIPL logo change
24/12/2020	Annual Revision
24/12/2021	Annual Revision

¹ India, South Africa

² Please refer to previous version of competency certificates for the revision history.

CARBON CHECK (INDIA) PRIVATE LIMITED

CIN: U74930DL2012PTC232495

Regd. Off: 2071/38, 2nd Floor, Naiwala, Karol Bagh, New Delhi - 110005

Corporate off: Unit No. 1701, Logix City Centre Office Tower, Plot No. BW-58, Sector-32 Noida, Uttar Pradesh

Tel: +91 120 4373114 | URL: www.carboncheck.co.in | e-mail: info@carboncheck.co.in



Carbon Check (India) Private Ltd.

SHIVAJI CHAKRABORTY


has been qualified as per CCIPL's internal qualification procedures, in accordance with requirements of Accreditation Standard (version 07.0):

For following functions:

Validator	☐	Team Leader	☒	Technical reviewer	☒
Verifier	☐	Technical Expert	☒	Local Assessor ¹	☒

In the following Technical Areas:

TA 1.1	☒	TA 4.1	☐	TA 9.1	☐	TA 13.1	☐
TA 1.2	☒	TA 5.1	☐	TA 9.2	☐	TA 13.2	☐
TA 3.1	☒	TA 5.2	☐	TA 10.1	☐	TA 14.1	☐



Mr. Vikash Kumar Singh
Compliance Officer

Date of Approval
24/12/2021



Mr. Amit Anand
CEO

Valid Till
23/12/2022

Revision History of the Document

01/03/2020 ²	Interim Revision for office address change
01/09/2020	Interim Revision for CCIPL logo change
24/12/2020	Annual Revision
24/12/2021	Annual Revision

¹ India.

² Please refer to previous version of competency certificates for the revision history.

CARBON CHECK (INDIA) PRIVATE LIMITED

CIN: U74930DL2012PTC232495

Regd. Off: 2071/38, 2nd Floor, Naiwala, Karol Bagh, New Delhi - 110005

Corporate off: Unit No. 1701, Logix City Centre Office Tower, Plot No. BW-58, Sector-32 Noida, Uttar Pradesh

Tel: +91 120 4373 114 | URL: www.carboncheck.co.in | e-mail: info@carboncheck.co.in



Carbon Check (India) Private Ltd.

Mr. Rishi K Raychoudhury


has been qualified as per CCIPL's internal qualification procedures, in accordance with requirements of Accreditation Standard (version 07.0):


For following functions:

Validator ☐ Team Leader ☐ Technical reviewer ☐
 Verifier ☐ Technical Expert ☒ Local Assessor¹ ☒

In the following Technical Areas:

TA 1.1 ☐ TA 4.1 ☐ TA 9.1 ☐ TA 13.1 ☐
 TA 1.2 ☒ TA 5.1 ☐ TA 9.2 ☐ TA 13.2 ☐
 TA 3.1 ☐ TA 5.2 ☐ TA 10.1 ☐ TA 14.1 ☐


 Mr. Vikash Kumar Singh
 Compliance Officer


 Mr. Amit Anand
 CEO

Date of Approval
 17/08/2022

Valid Till
 23/12/2022

Revision History of the Document

01/03/2020 ²	Interim Revision for office address change
01/09/2020	Interim Revision for CCIPL logo change
24/12/2020	Annual Revision
24/12/2021	Annual Revision
17/08/2022	Initial Joining

¹ India

² Please refer to previous version of competency certificates for the revision history.

CARBON CHECK (INDIA) PRIVATE LIMITED
 CIN: U74930DL2012PTC232495

Regd. Off: 2071/38, 2nd Floor, Nalwala, Karol Bagh, New Delhi - 110005

Corporate off: Unit No. 1701, Logix City Centre Office Tower, Plot No. BW-58, Sector-32 Noida, Uttar Pradesh
 Tel: +91 120 4373114 | URL: www.carboncheck.co.in | e-mail: info@carboncheck.co.in

APPENDIX 4: LIST OF FINDINGS

TABLE 1: CORRECTIVE ACTION REQUESTS (CARs) AND CLARIFICATION REQUESTS (CLs)

Finding	CL 01		
Classification	☐ CAR	☒ CL	☐ FAR
Description of finding (VVB)	The EGfacility,y mentioned in the section 4.2 of the MR2 version 1.1 is not in line with the actual EGfacility,y calculated and crosschecked during the on-site assessment. Please clarify.		
Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	The latter was a misread. This human error has been modified during on-site visit.		
VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	VVB has assessed that the value of the parameter EGfacility,y has been modified in accordance with the values observed during the onsite visit. CL01 is closed.		
Conclusion Tick the appropriate checkbox	☐ To be checked during the next periodic verification ☐ Outstanding finding (not closed) ☒ The finding is closed		

Finding	CL 02		
Classification	☐ CAR	☒ CL	☐ FAR
Description of finding (VVB)	The Baseline Emission and the Emission Reduction calculated in the section 5 of the MR2, version 1.1 is not in line with the actual Baseline Emission and Emission Reduction calculated during the on-site assessment. Please provide clarification on the difference in the values.		
Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	The BE & ER calculation initially consisted of decimals due to the combined margin CO2 emission factor. A conservative round down approach has thus been applied by the PP to obtain an accurate estimate of BE and ER values following the audit.		

VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	The applicable parameters are ex-ante parameters and the values for such parameters may not be changed. CL02 remains open.
Corrective Action or clarification #2 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	The ex-ante parameter used in the calculation have not been changed. However, results obtained by using ex-ante parameters have been rounded. H3

Finding	CL 03		
Classification	☐ CAR	☒ CL	☐ FAR
Description of finding (VVB)	In the 3rd paragraph of the section 4.3 of the MR2, version 1.1 it is mentioned that the “net electricity generation supplied by the project plant to the grid is reliably monitored through calibrated electricity meters and cross reliably monitored through calibrated electricity meters and cross-checked with sales records as part of checked with sales records as part of quality assurance/quality control measures on top of CEB diligence.”. PP shall explain the process of cross		

	checking of electricity generation data in accordance with the requirements of Tool 05 , version 03 for the parameter.
Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	More information on the cross-checking of electricity generation has been added in the MR. In accordance with tool 05, latest inspection & calibration certificates of meters have been provided.
VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	PP has provided the information on the cross-checking of electricity generation in the section 4.3 of the MR. Furthermore, PP shall also provide the QA/QC procedures for the monitoring parameter EGfacility,y in accordance with the section B.7.1 of the registered PDD. CL03 remains open.
Corrective Action or clarification #2 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	Additional information on the QA/QC procedures have been provided.
VVB Assessment #2 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	VVB has assessed that the PP has provided the QA/QC procedures for the monitoring parameter EGfacility,y in the section 4.2 of the MR2, version 1.2. Thus, CL03 is closed.
Conclusion Tick the appropriate checkbox	☐ To be checked during the next periodic verification ☐ Outstanding finding (not closed) ☒ The finding is closed

Finding	CL 04
Classification	☐ CAR ☒ CL ☐ FAR
Description of finding (VVB)	1. The total electricity export for the month of November 2020 does not match with the sales invoice of CEB provided. 2. Emission reduction calculation spreadsheet has not been provided to the verification team.
Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	1. The latter was a human error and has already been modified. 2. The ERs probably did not get uploaded in the online compressed file link but was re-sent to the lead assessor onsite.

VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	1. VVB has assessed that the total electricity export for the month of November 2020 matches with the sales invoice of CEB provided. CL04.1 is closed. 2. VVB confirms that the Emission Reduction Calculation spreadsheet has been received by the verification team. CL04.2 is closed.
Conclusion Tick the appropriate checkbox	☐ To be checked during the next periodic verification ☐ Outstanding finding (not closed) ☒ The finding is closed

Finding	CL 05		
Classification	☐ CAR	☒ CL	☐ FAR
Description of finding (VVB)	PP has not provided the justification related to the efficient performance of instrument and devices during the monitoring period.		
Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	Same will be sent via mail alongside this document.		
VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	VVB has assessed that the PP has provided the documents related to the performance of instrument and devices during the monitoring period. Thus, CL05 is closed.		
Conclusion Tick the appropriate checkbox	☐ To be checked during the next periodic verification ☐ Outstanding finding (not closed) ☒ The finding is closed		

Finding	CL 06		
Classification	☐ CAR	☒ CL	☐ FAR
Description of finding (VVB)	PP should provide evidence for grievance resolution of local stakeholder during the monitoring period.		

Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	No stakeholders' grievances were received during the monitoring period.
VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	PP shall provide the grievance mechanism process for the VCS project activity and the means of communication of grievance with the PP. If any document has been used to register the grievances, a copy of the document shall be provided to the verification team. CL06 remains open.
Corrective Action or clarification #2 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	We prepare two official environmental reports on a bi-annual basis which are also transferred to the stakeholders. This tool allows them to raise their queries, if any. A log sheet is also available on site whereby visitors/stakeholders are encouraged to register their remarks/grievances. A copy of the environmental report and log sheet will be sent as supporting documents.
VVB Assessment #2 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	VVB confirms that the copy of the environmental report and log sheet has been received by the verification team. The local stakeholder grievance process has also been explained by the PP. However, the grievance process has not been outlined in the section 2.2 of the MR. CL06 remains open.
Corrective Action or clarification #3 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	The clarification as above has been added in section 2.2 of MR.
VVB Assessment #3 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	PP has revised the section 2.2 of the MR to provide the details of the grievance process. PP has also confirmed that no comments have been received from the local stakeholders. CL06 is closed.
Conclusion Tick the appropriate checkbox	☐ To be checked during the next periodic verification ☐ Outstanding finding (not closed) ☒ The finding is closed

Finding	CL 07		
Classification	☐ CAR	☒ CL	☐ FAR

Description of finding (VVB)	In section B.7.1 of the PDD, it is stated that “CEB shall inspect each CEB Meter upon installation and at least once every year thereafter.” PP has provided the inspection records for 2020 only. PP shall also provide the inspection records for 2021 for both main and check meter.
Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	Same will be sent via mail alongside this document.
VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	VVB has assessed that the PP has provided the inspection records for 2021 for both main and check meters. After the initial installation of the meters, only one annual inspection carried out in 2021 is applicable to the project activity. Thus, CL07 is closed.
Conclusion Tick the appropriate checkbox	☐ To be checked during the next periodic verification ☐ Outstanding finding (not closed) ☒ The finding is closed

Finding	CAR 01		
Classification	☒ CAR	☐ CL	☐ FAR
Description of finding (VVB)	In section 4.2 of the MR2 version 1.1, the EGexport and EGimport are not included as monitoring parameters.		
Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	The two parameters have been included as monitoring parameters following the on-site visit.		
VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	VVB has assessed that the EGexport and EGimport parameters are included. PP shall clarify if the parameters are listed in the registered PDD. PP shall provide the parameters in accordance with the registered PDD and the monitoring methodology, ACM0002. CAR01 remains open.		
Corrective Action or clarification #2 (PP shall write a detailed and clear corrective action or further	The EGexport and EGimport parameters were added in the PD but are not listed as monitoring parameters in the registered PDD. They have therefore been excluded from the MR.		

information for clarification as per finding)	
VVB Assessment #2 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	VVB has assessed that the EG _{export} and EG _{import} parameters are not listed as monitoring parameters in the registered PDD. So, VVB confirms that these parameters are excluded from the MR2, version 1.2. Thus, CAR01 is closed.
Conclusion Tick the appropriate checkbox	☐ To be checked during the next periodic verification ☐ Outstanding finding (not closed) ☒ The finding is closed

Finding	CAR 02		
Classification	☒ CAR	☐ CL	☐ FAR
Description of finding (VVB)	PP does not mention about the cross-checking procedure of electricity generation in the monitoring report.		
Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	Same has been included in the MR following the on-site visit.		
VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	VVB has assessed that PP has mentioned clearly about the cross-checking procedure of electricity generation in the monitoring report. PP shall also provide the evidence of the cross-check conducted during the monitoring period to the verification team. CAR02 remains open.		
Corrective Action or clarification #2 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	Supporting documents will be sent alongside this document.		
VVB Assessment #2 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and	VVB confirms that the generation records are cross checked with the electricity invoices by the PP. The evidence in the form of monthly cross-check performed by Green Yellow and CEB representatives has been provided to the verification team. Thus, CAR02 is closed.		

VVB assessments (#2, #3, etc.) shall be added.	
Conclusion Tick the appropriate checkbox	☐ To be checked during the next periodic verification ☐ Outstanding finding (not closed) ☒ The finding is closed

Finding	CAR 03		
Classification	☒ CAR	☐ CL	☐ FAR
Description of finding (VVB)	- Ex-ante parameters 'The percentage share of total installed capacity of solar PV' and 'The total installed capacity of solar PV' are not reported in the section 4.1 of the MR as per the registered PDD. - The value of the ex-ante parameters EFgrid,OM,y and EFgrid,BM,y provided in the section 4.1 of the MR are not consistent with the PDD.		
Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	- The listed ex-ante parameters have been added in the MR. - The values of the two listed ex-ante parameters are actually the same: 1.0282 and 0.8814 respectively. They had only been represented correct to 3 decimal places in the previous version of the MR.		
VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	- VVB has assessed that the section 4.1 of the MR as per the registered PDD, the Ex-ante parameters 'The percentage share of total installed capacity of solar PV' and 'The total installed capacity of solar PV' are mentioned clearly. Thus, CAR03.1 is closed. - The value of the ex-ante parameters provided in the version 1.2 of the MR are not consistent with the registered PDD. The values of ex-ante parameters may not be changed in the monitoring report without project description deviation. CAR03.2 remains open.		
Corrective Action or clarification #2 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	The value of the ex-ante parameters have been corrected according to the registered PDD.		

VVB Assessment #2 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	VVB has assessed that the value of the ex-ante parameters have been corrected according to the registered PDD in the section 4.1 of the MR2, version 1.2. Thus, CAR03 is closed.
Conclusion Tick the appropriate checkbox	☐ To be checked during the next periodic verification ☐ Outstanding finding (not closed) ☒ The finding is closed

TABLE 2: FORWARD ACTION REQUESTS

Finding	FAR 01		
Classification	☐ CAR	☐ CL	☒ FAR
Description of finding (VVB)	PP shall conduct awareness program on the renewable energy and carbon credit to their maintenance team and this shall be checked at the time of next periodic verification.		
Corrective Action or clarification #1 (PP shall write a detailed and clear corrective action or further information for clarification as per finding)	This comment has been duly noted.		
VVB Assessment #1 The assessment shall encompass all open issues in the finding. In case of non-closure, additional corrective action and VVB assessments (#2, #3, etc.) shall be added.	In accordance with the forward action request, the PP shall conduct awareness program for the maintenance team. FAR01 shall be checked at the time of the next periodic verification.		
Conclusion Tick the appropriate checkbox	☒ To be checked during the next periodic verification ☐ Outstanding finding (not closed) ☐ The finding is closed		