

TRAINING DOCUMENT · SKILLCLOUD ACADEMY

All names, data, and circumstances are fictional. For educational use only.

AGENT VISUAL INSPECTION DISCLOSURE (AVID)

Reference: C.A.R. Form AVID · Completed by Listing Agent

1. GENERAL INFORMATION & SCOPE

Inspection Date:	September 29, 2025 (10:30 AM – 11:45 AM)
Property Address:	4827 Rolando Blvd, San Diego, CA 92115
Inspecting Agent:	Sofia Reyes (DRE #02156789) · Berkshire Hathaway HomeServices
Weather Conditions:	Clear, dry, ambient temperature approx. 74°F

2. SPECIFIC ROOM-BY-ROOM VISUAL OBSERVATIONS

(Visual inspection only of reasonably and normally accessible areas pursuant to CA Civil Code §2079):

Area InspectedVisual Observations Noted **Exterior / Grounds / Driveway** Concrete driveway shows longitudinal surface settlement cracking. Mature front yard landscaping in good manicured condition. Exterior paint on wood fascias and eaves shows sun fading and early paint flaking on west/south exposures. **Garage (Detached 2-Car)** Detached garage interior dry. Some minor wood framing dust/frass noticed near south interior framing baseplate (recommend professional termite inspection). Automatic door operates normally. **Living Room & Dining Area** Original oak hardwood flooring in good condition with minor surface scratches near hallway entry. Chandelier hanging above dining table (noted as excluded item on RLA). **Kitchen** Updated cabinetry and quartz countertops clean and sound. Range, hood, and dishwasher clean. No active leaks observed beneath sink cabinet. **Hallway & Guest Bath** Sink basin faucet drained slowly during visual run test. Grout in shower enclosure intact. **Bedrooms (3) & Master Bath** All windows open and latch. Master bathroom shower tile intact. No visible stains on bedroom ceilings.

3. AGENT SIGNATURE

Sofia Reyes
Sofia Reyes, Realtor® · BHHS California Properties · Date:
09/29/2025

4827 Rolando Blvd, San Diego, CA 92115 · Escrow #CTT-2025-07421
TRAINING DOCUMENT · SKILLCLOUD ACADEMY