

TRAINING DOCUMENT · SKILLCLOUD ACADEMY

All names, data, and circumstances are fictional. For educational use only.

BUYER'S REQUEST FOR REPAIR NO. 1 (C.A.R. FORM RR)

Presented by: Marcus Lee on behalf of Jason & Michelle Brooks · Date: October 18, 2025

TRANSACTION REFERENCE

Property Address:	4827 Rolando Blvd, San Diego, CA 92115
Buyer(s):	Jason Brooks and Michelle Brooks
Seller(s):	Daniel Herrera and Carmen Herrera
Contingency Deadline:	Day 17 Investigation Contingency expires October 20, 2025

BUYER'S REPAIR & CREDIT REQUESTS

Pursuant to Section 11 of the Purchase Agreement, Buyer requests that Seller agree to the following items prior to Close of Escrow:

Item #Defect / Finding ReferenceRepair / Credit RequestedEstimate 1. **Foundation Specialist Report:** 18-inch crack on south wall stem. Credit buyer to complete recommended epoxy injection seal by Pacific Foundation Engineering. \$2,200.00 2. **Atlas Pest Control Report #WDO-2025-4128:** Section 1 active subterranean termites in detached garage. Complete full perimeter subterranean termite treatment with clear Section 1 completion notice. \$1,850.00 3. **Precision Home Inspection:** HVAC heating/AC unit is 64 years old, past useful life. Replace HVAC furnace and condensing unit with new modern 3-ton 16-SEER system or provide closing credit. \$8,500.00 TOTAL BUYER REQUEST: \$12,550.00

BUYER SIGNATURES

<i>Jason Brooks</i>	<i>Michelle Brooks</i>
Buyer: Jason Brooks · Date: 10/18/2025	Buyer: Michelle Brooks · Date: 10/18/2025