

WOOD DESTROYING ORGANISM INSPECTION REPORT

Atlas Pest Control, Inc. | CA SPCB License #PR-8827 | Report #WDO-2025-4128

Inspection Date: October 14, 2025 | Inspector: Carlos Vega, License #OPR-12847

Property: 4827 Rolando Blvd, San Diego, CA 92115 | APN: 470-362-18-00

1. SCOPE OF INSPECTION

This inspection covers the main dwelling, attached garage, and accessible substructure (crawl space). Inaccessible areas are excluded per the Structural Pest Control Board regulations.

2. FINDINGS — SECTION 1 (Active Infestation / Infection)

Finding 1: Evidence of active drywood termite infestation in the attic area. Termite pellets (frass) observed along roof framing members in the northeast quadrant of the attic. Estimated infestation area: approximately 120 square feet of attic framing.

Recommendation: Localized chemical treatment of affected attic framing. Estimated cost: **\$1,850**.

3. FINDINGS — SECTION 2 (Conditions Likely to Lead to Infestation)

Finding 2: No Section 2 conditions noted at time of inspection.

4. AREAS NOT INSPECTED

The following areas were not inspected and are excluded from this report: areas concealed by stored items in garage, areas behind walls, under flooring, and any areas not visible or accessible at the time of inspection.

5. SUMMARY

Section	Finding	Est. Cost
Section 1 (Active)	Drywood termite — attic framing	\$1,850
Section 2 (Conditions)	None	\$0

Carlos Vega

10/14/2025

Inspector (Carlos Vega, OPR-12847)

Date

Maria Gutierrez

10/14/2025

Listing Agent (Maria Gutierrez)

Date