



**Cal OES**  
GOVERNOR'S OFFICE  
OF EMERGENCY SERVICES

## DEBRIS REMOVAL FINAL SIGN OFF

### DRR 21048 WILDFIRE INCIDENT

SITE ADDRESS: 4978 EDGEWOOD CIRCLE, GRIZZLY FLATS, CA APN: 041-522-005

COUNTY: EL DORADO

Debris Removal Complete ☒ Yes ☐ No  
Confirmation Sampling Approved ☒ Yes ☐ No  
Erosion Control Complete ☒ Yes ☐ Waived  
Erosion Control Level/BMP ☐ 1 ☒ 2 ☐ 3 (Please attach drawing for Level 3)  
Tree Removal Complete ☒ Yes ☐ No ☐ N/A – No Trees  
FINAL APPROVAL DATE: 12/11/2021

#### Property Notes:

- Septic tank location marked, does appear to have damage.
- Propane tank location marked does appear to have fire damage.
- No water well located on property.
- Retaining wall left in place to prevent erosion of native soil. The property owner should consult a license civil or structural engineer to determine the proper course of action to rebuild any concrete structure left by the IMT.
- Parcel appears to be free of debris. All cleanup goals achieved.

Joe Quen

Print Name

Cal Recycle/Cal OES or State Designee

County/City Representative



Photo Comments

Items the homeowner asked for us to leave.



#### Photo Comments

Look into the writer of the property from down below.





Photo Comments



Photo Comments



Photo Comments





Photo Comments

Septic system.



Photo Comments

Walls.





Photo Comments

Wall septic to the right propane tank in back a photo.



Photo Comments



Photo Comments





Photo Comments

Driveway.



Photo Comments



Photo Comments

Front of the property.