

NasQuest Resources Sdn Bhd

Technical Inspection Division

ROV Selected Anode Report (SANI)

SOW Report No: SOW-2026-001

Structure:	Bekok-A	Vessel:	Sapura Achiever
Job Pack:	ROV Inspection Campaign 2026	Insp. Date Range:	01 Jun 2026 to 02 Jun 2026

Item No.	QID	Elevation (m)	Depletion (%)	Anode CP (mV)	Anode Type	Anomaly	Dive No.	Findings
1	BAN004	-12.5	15%	-1050 -1101 -1080	ALUMINUM	No	ROV-01	Anode BAN004 Close Visual Inspection Top Stub: -1101 mV Bottom Stub: -1080 mV
2	BAN005	-15.0	25%	-1020 -980	ALUMINUM	Yes	ROV-01	Anode BAN005 shows signs of depletion. Mid Stub: -980 mV [Reference: ANOM-2026-001] Rectified: Replaced anode

PREPARED BY	REVIEWED BY	APPROVED BY
Name: Date: Signature:	Name: Date: Signature:	Name: Date: Signature: