FINAL INSPECTION DATASHEET
BODP-A

PROJECT & ASSET SPECIFICATIONS

CLIENT:	NasQuest Resources Sdn Bhd
CONTRACTOR:	NasQuest Resources Sdn Bhd
VESSEL:	MEO RESOLUTION
FIELD / LOCATION:	BOKOR FIELD
JOBPACK:	UIMC2026/SKA/PLAT01
SOW REPORT NUMBER:	AM26-016-01
INSPECTION DATE RANGE:	24 Aug 2026 – 31 Aug 2026
REVISION:	0
ISSUED DATE:	2026-10-22

DOCUMENT CONTROL & ENDORSEMENTS

PREPARED BY	REVIEWED BY	APPROVED BY
Name: Inspection Lead	Name: Senior QA Engineer	Name: Technical Director
Position: _____	Position: _____	Position: _____
Date: 2026-10-22	Date: 2026-10-22	Date: 2026-10-22

Generated By: OFFSHOREPRO Version 1.0 (NasQuest Resources Sdn Bhd)

TABLE OF CONTENTS

Document Sections & Page Navigation

Total Document Pages: 15

SECTION / REPORT TEMPLATE	PAGE NO.
STRUCTURE DETAILS	**Page 3**
Defect Criteria Report	**Page 4**
INSPECTION SUMMARY	**Page 5**
Inspection Summary by Graph	**Page 6**
GENERAL VISUAL INSPECTION	**Page 7**
General Visual Inspection Report (ROV)	**Page 8**
CATHODIC PROTECTION SURVEY	**Page 9**
Cathodic Protection Survey Report (ROV)	**Page 10**
BASE LEVEL SURVEY	**Page 11**
Scour Survey Report (ROV)	**Page 12**
FLOODED MEMBER DETECTION SURVEY	**Page 13**
FMD Survey Report (ROV)	**Page 14**

Interactive Document Navigation: Click on any section title, sub-report, or page number to jump directly to that page.

STRUCTURE DETAILS

Nasquest Resources Sdn Bhd
Subsea Inspection & Asset Integrity
Defect Criteria Specification Report
Report No: AM26-016-01

DC-001 - PTS-2023 (Ver. 1)

Effective: 25/01/2026

Structure Group	Defect Type	Condition	Priority	Alert Message
ANODE WASTAGE (AW) (AW)				
All Structure Groups	Anode Not Working	> 75%	PRIORITY 2	Anode not working
CATHODIC POTENTIAL (CP) (CP)				
Primary, Conductor, Pile	Cathodic Potential Over Protected	< -1150 mV	PRIORITY 1	CP unprotected
Primary, Pile, Conductor	Cathodic Potential Over Protected	> -650 mV	PRIORITY 1	CP over protected
Primary, Pile, Conductor	Cathodic Potential Unprotected	> -799 mV	PRIORITY 2	CP over protected
Secondary, Anode, Boat Landing, Clamps, Guides	Cathodic Potential Unprotected	> -649 mV	PRIORITY 2	CP over protected
Anode, Boat Landing, Clamps, Guides, Secondary	Cathodic Potential Unprotected	< -1150 mV	PRIORITY 2	Cp unprotected
Secondary, Anode, Clamps, Guides, Boat Landing	Cathodic Potential Over Protected	> -799 mV	PRIORITY 3	CP over protected
DEBRIS (DB) (DB)				
All Structure Groups	Debris Metallic In Contact	== Debris Metallic	PRIORITY 1	Metallic Item in contact
All Structure Groups	Debris Non Metallic In Contact	== Debris Non Metallic	OBSERVATION	Debries observation
All Structure Groups	Debris Metallic In Contact	== Debris Metallic	OBSERVATION	Debris Observation
LACK OF INTEGRITY (LI) (LI)				
Primary	Lack Of Integrity - Member Flooded	== Flooded	PRIORITY 1	Flooded Member
Secondary	Lack Of Integrity - Member Flooded	== Flooded	PRIORITY 2	Flooded Member
SCOUR (SC) (SC)				
All Structure Groups	Scour Depth Limit	> 900 mm	PRIORITY 1	Scour depth exceeded

Marine Growth Inspection (MGI)

Profile: 2026 Field Profile

Description: Field campaign limits

Segment	From Elevation / Reference Level	Max Allowable Thickness	Application Rule
1	MSL (0.00m)	**80 mm**	From surface level downwards to next segment
2	1/3 WD (Water Depth)	**80 mm**	Interpolated depth segment limit
3	Mudline (Seabed Level)	**25 mm**	From this elevation downwards to Mudline

PREPARED BY	REVIEWED BY	APPROVED BY
Name: Position: Date:	Name: Position: Date:	Name: Position: Date:

INSPECTION SUMMARY

Nasquest Resources Sdn Bhd

Subsea Inspection & Asset Integrity

Inspection Summary

Report No: AM26-016-01

Field Name: BOKOR FIELD | **Structure Name:** BODP-A | **Jobpack Name:** UIMC2026/SKA/PLAT01 | **Inspection Date:** --

TOTAL QIDs	COMPLETED	INCOMPLETE	TOTAL ANOMALIES	COMPLETION RATE
--	--	--	--	-- %
Unique in approved jobpack	Verified completed QIDs	Outstanding / restricted	Unique anomaly IDs	No scope QIDs defined

ROV TASK COVERAGE

Tasks: 100% Done (200/200)

TASK LEVEL PROGRESS: 200 Completed (100%) • 0 Incomplete (0%) • 200 Total Tasks

General Visual Inspection (GVI)	180/180 QIDs	100%
Scour Survey Inspection	8/8 QIDs	100%
Splash Zone Inspection (SZI)	8/8 QIDs	100%
Water Depth Measurement	4/4 QIDs	100%

Completed Tasks / QIDs Remaining / Incomplete Tasks

ANOMALY DISTRIBUTION

Priority donut & defect ranking

0 TOTAL

P1: 0 (0%) P2: 0 (0%)

P3: 0 (0%) Obs: 0 (0%)

Rectified Anomalies: 0

DEFECT CRITERIA RANKING

	COUNT (%)
Anode wastage (AW)	0 (0%)
Cathodic potential (CP)	0 (0%)
Debris (DB)	0 (0%)
Lack of integrity (LI)	0 (0%)
Physical damage (PD)	0 (0%)
Scour (SC)	0 (0%)
Variation to spec (VS)	0 (0%)

MARINE GROWTH (MGI)

Coverage

Hard Soft Total: 189 QIDs

0-20% 20-40% 40-60% 60-80% 80-100%

ANODE CONDITION

Depletion

Type: -- Total: 1

0-25%	0
26-50%	0
50-75%	0
76-100%	0
Not Evaluated	0

Anode Health: 0% (<50% dep.)

SCOUR SURVEY

Integrity & depth

Faces Survey	Piles Survey	Exposed Piles	Min Depth	Max Depth
4/4	4	0	None	300 mm

0 300 (Max) 800 (Limit) 1200 mm

Safety: Normal (<800mm)

PREPARED BY

Name: . . . . . .

Date:

Signature:

REVIEWED BY

Name: . . . . . .

Date:

Signature:

APPROVED BY

Name: . . . . . .

Date:

Signature:

GENERAL VISUAL INSPECTION

Nasquest Resources Sdn Bhd
Subsea Inspection & Asset Integrity
General Visual Inspection Report (ROV)
Report No: AM26-016-01

Structure:	BODP-A	**Vessel:**	N/A
Job Pack:	UIMC2026/SKA/PLAT01	**Insp. Date Range:**	N/A

No.	Component QID	Elevation (m)	Dive No.	Tape No.	CP (mV)	Findings
1	N/A	-15.5	D01	T01	—	No significant findings
2	N/A	-25	D02	T02	—	No significant findings

PREPARED BY	REVIEWED BY	APPROVED BY
Name:	Name:	Name:
Date:	Date:	Date:
Signature:	Signature:	Signature:

CATHODIC PROTECTION SURVEY

Nasquest Resources Sdn Bhd

Subsea Inspection & Asset Integrity

Cathodic Protection Survey Report (ROV)

Report No: AM26-016-01

Structure:	BODP-A	**Vessel:**	N/A
Job Pack:	UIMC2026/SKA/PLAT01	**Insp. Date Range:**	N/A

No.	Component QID	Elevation (m)	Dive No.	Tape No.	CP (mV)	Findings
-	-	-	-	-	-	No observations recorded for this scope.

PREPARED BY	REVIEWED BY	APPROVED BY
Name:	Name:	Name:
Date:	Date:	Date:
Signature:	Signature:	Signature:

BASE LEVEL SURVEY

Nasquest Resources Sdn Bhd
Subsea Inspection & Asset Integrity
Scour Survey Report (ROV)
Report No: AM26-016-01

Structure:	BODP-A	**Vessel:**	N/A
Job Pack:	UIMC2026/SKA/PLAT01	**Insp. Date Range:**	N/A

No.	Component QID	Elevation (m)	Dive No.	Tape No.	Findings
GENERAL / UNASSIGNED FACE					
1	N/A	-72.00 m	D03	T04	No significant findings
2	N/A	-72.20 m	D03	T04	No significant findings

PREPARED BY	REVIEWED BY	APPROVED BY
Name:	Name:	Name:
Date:	Date:	Date:
Signature:	Signature:	Signature:

FLOODED MEMBER DETECTION SURVEY

Nasquest Resources Sdn Bhd
Subsea Inspection & Asset Integrity
FMD Survey Report (ROV)
Report No: AM26-016-01

Structure:	BODP-A	**Vessel:**	N/A
Job Pack:	UIMC2026/SKA/PLAT01	**Insp. Date Range:**	N/A

Component QID	Elevation (m)	Dive No.	Tape No.	Status	Density Value	Findings
N/A	-45.00 m	N/A	T05	**Not Flooded**	-	No significant findings
N/A	-55.00 m	N/A	T05	**Not Flooded**	-	No significant findings

PREPARED BY	REVIEWED BY	APPROVED BY
Name:	Name:	Name:
Date:	Date:	Date:
Signature:	Signature:	Signature:

END OF REPORT