



Transaction Report						
PlantId	Plant	Registration	CompletionStatus	Defect Id	Defect Status	Defect Type
36	LV016 - 2BC 8MV 2017 Toyota Hilux Dual Cab GUN125R Ute	2BC8MV	Completed on time	108	Closed	Remark
62	CRE036 Volvo EC530EL Excavator	N\A	Not yet completed no expected date	132	Closed	Breakdown
				141	Closed	Breakdown
70	CRE027 CAT D6 LPG Bulldozer	N\A	Not yet completed no expected date	105	Closed	Breakdown
79	CRE018 Volvo EC300	N\A	Not yet completed no expected date	190	Closed	Breakdown
97	CRE341 Articulated Dump Truck CAT745	N\A	Not yet completed no expected date	111	Closed	Remark
108	CRE051 Volvo EC350DL Excavator	N\A	Completed on time	109	Closed	Breakdown
139	CRE505 Dump Truck - Articulated	N\A	Completed on time	106	Closed	Breakdown
140	CRE507 Dump Truck, Cat 745	N\A	Not yet completed no expected date	110	Closed	Remark
141	CRE508 CAT745 Dump Truck	N\A	Not yet completed no expected date	147	Closed	Breakdown
166	EX01 Cloudcon Test Excavator	N\A	Not yet completed no expected date	80	Closed	Breakdown
				81	Closed	Breakdown
				155	Closed	Breakdown
227	CRE578 Padfoot Single Drum 19.0t	N\A	Not yet completed no expected date	118	Closed	Breakdown
273	CRE623 Excavator 336 (20T)	N\A	Not yet completed no expected date	103	Closed	Breakdown
302	CRE652 Excavator CAT330 Next Gen	N\A	Not yet completed no expected date	168	Closed	Breakdown