

document_id: INS-PRG-ETP601-001 title: Effluent Treatment Tank ETP-601 Records Review document_type: inspection_report synthetic: true generated_for: Pragyan Plant Intelligence Hackathon Prototype revision: "1.0" effective_or_event_date: 2025-08-05 owner_role: ETP Operator related_asset_tags: [ETP-601] related_drawing_ids: [PCP-PID-005] confidentiality: Internal Demo review_status: Draft for Human Review

Inspection Details

Field	Value
Inspection ID	INS-PRG-ETP601-001
Asset tag	ETP-601
Asset type	Effluent treatment tank
Drawing ID	PCP-PID-005
Inspector role	ETP Operator

Scope

Review the fictional document index and asset context for ETP-601.

Observations

The P&ID reference is available. A fictional handover record contains an incomplete source-location field and is marked for evidence review. No treatment performance or environmental conclusion is recorded.

Finding and Follow-Up

Severity: Low

Recommended follow-up: Complete the source-location metadata before using the handover record as verified evidence.

Review Status

Draft for Human Review. This is a synthetic inspection scenario, not a confirmed plant finding.