CUT Maintanance

Estate & Infrastructure

Staff number

Password

Sign Up

Already have an account? Login

Accounts and roles are created by a system administrator

CUT Maintanance

Estate & Infrastructure

Staff number

Password

Login

My jobs

Thabo Dlamini - 3 open, 1 overdue

All | New | Active | Overdue

Burst pipe in the bathroom

Kovsie Res - Block B - Room 214

Assigned | Overdue-Today 14:00

Light not working in corridor

Concordia Res - Ground floor

Accepted | Due Tomorrow 10:00

Broken window latch

Ithuteng Res - Room 108

In Progress | Due Fri 12:00

My Jobs | History

< My jobs

MC-2026-0142

Plumbing - High priority

Burst pipe in bathroom

Water leaking from the basin pipe onto the floor. Photo attached.



Location **Kovsie Res - Block B - Room 214**

Reported by **HCM T.Mokoena**

Deadline **Overdue** **Today 14:00**

- **Assigned**
- Accepted
- In Progress
- Completed
- Verified

Accepted job

Declined and tell supervisor

< Back

Update progress

MC-2026-0142 - Burst pipe in bathroom

Status

In Progress

Notes

e.g.Isolated water supply, replacing pipe section

Photo(optional)

Take or choose a photo

Save updates

< Back

Mark as completed

MC-2026-0142 - Burst pipe in bathroom

What was done

In Progress

Photo of finished work

Take or choose a photo

Time spent

Under 1 hour

After you submit,the House Committe Member is asked to confirm the problem is resolved

Submit as completed

Job submitted

MC-2026-0142



Waiting for verification

The complaint has been notified. If they report it as not resolved, the job returns to your list as reopened

Back to my jobs

History

Jobs you have finished

Block shower drain

MC-2026-0120-Kovsie Res - Block A

Verified

Door hinge repair

MC-2026-0115 - Concordia Res -Room 12

Awaiting verification