REQUEST FOR QUOTATION

From: Valtara Cement, Procurement Department

To: Nordwind Turbine Services, Bid Desk

Dear Sir or Madam,

We kindly request a quotation for inspection work on a NW-G50 air-cooled generator (generator) at our Valtara Kiln Plant.

Scope of work. Rotor inspection with retaining ring test and electrical testing of the stator winding.

Operating hours at last outage: approx. 18,000 h.

Unit serial number: SN-24371.

Planned outage window: 06 Feb 2027 to 06 Apr 2027.

Please submit your quotation by **07 March 2027**.

Kind regards,
Joaquin Reinholt
Senior Buyer, Valtara Cement
Tel: +49 30 5550 2489
E-mail: joaquin.reinholt@valtara-procurement.example

Synthetic document. Not a real request.