

Public Risk Screen

SENTINEL-1A · NORAD 39634

DECISION AUTHORITY: SCREENING_ONLY · MODE: PUBLIC_SCREEN
This is a public-data screen. It is not an underwriting determination and must not be used to bind coverage.

OPERATOR / TYPE	REGIME
ESA / earth_observation	SSO
NEXT HUMAN ACTION	GENERATED
request_cdm	2026-08-12T00:00:00+00:00

A usable Conjunction Data Message with positive-semidefinite covariance is required before collision probability can be computed.

COLLISION PROBABILITY

Pc = NULL
Pc is NULL because no buyer-supplied CDM was provided. Public SOCRATES/CelesTrak columns are not a computed collision probability.

EVIDENCE LEDGER

Class	Status	Why it matters
Operator telemetry	missing	Power, thermal, attitude, command, and anomaly telemetry are required before underwriting conclusions.
Calibrated imagery	missing	Imagery needs range, scale, calibration, and image-quality metadata before physical damage dimensions are defensible.
Camera and range metadata	missing	Focal length, sensor pitch, GSD/range, pose, illumination, and scale reference are missing or incomplete.
Spacecraft geometry	missing	Mass, projected area, subsystem geometry, materials, and exposed components are required for exposure modeling.
Shielding and materials	missing	Shielding depth and material stackups are required for MMOD/radiation vulnerability estimates.
Covariance/CDM quality	missing	Conjunction conclusions require state covariance, CDM quality, hard-body radius, and uncertainty realism.
Operator anomaly logs	missing	Private anomaly, maintenance, and operations logs are required to connect public observations to spacecraft health.
Actuarial priors	missing	Validated fleet loss priors, policy context, and claims history are required for loss probability and financial exposure.

BLOCKED CLAIMS

- financial_exposure_without_policy_or_operator_financials
- physical_damage_dimensions_without_calibrated_imagery
- power_impact_without_telemetry_or_measurement_chain
- total_loss_probability_without_actuarial_model
- underwriting_recommendation_without_private_evidence

VISUAL FINDINGS (UNCALIBRATED)

- **solar_cell_cracking** (MODERATE): Visible light-colored radial patterns and discoloration on the solar array panel surface, localized at the position indicated by the red arrow. Morphology is consistent with localized cover glass fracturing or potential impact-induced substrate damage. Exact dimensions cannot be determined without range/GSD metadata.

SUMMARY

Public Risk Screen result; screening-only authority. This pack lists what public evidence shows, what is missing, and what a human should request next. It is not an underwriting or bind decision.

REPRODUCIBILITY

input_hash dd617beecc073f275223abe7680e0d60cd344ca3d0311a4d95228d2926d32c35
software_sha 330df6552d116ea447dc5f24790de1b9a882026f
generated_at 2026-08-12T00:00:00+00:00

Public Risk Screen result; screening-only authority. This pack lists what public evidence shows, what is missing, and what a human should request next. It is not an underwriting or bind decision. Do not treat this document as a quote, binder, or official inspection certificate. Public catalog conjunction columns are not a computed collision probability.