Site Visit Call Report

Call Report No: CRN-011 | Date: 10 Mar 2026 09:45

1. CUSTOMER INFORMATION

Call Report No.	CRN-011
Customer Name	Juma Mustafa
Customer Type	Salaried
Brief Profile	Customer want a house
IBPS No.	09931
Customer Number	11993
Project Name	Kikapu Shopping Stall

2. SITE VISIT DETAILS

Visit Date & Time	23 Feb 2026 16:35
Person Met at Site	Fundi Joseph
Exact Location	Green House
House Located Along	Green Valley Houses
Site PIN	445-7890
Security Details	LR. No 6789
Plot/LR No.	6789

3. FINANCIAL SUMMARY

BQ Amount	KES 45,000,000.00
Construction Loan Amount	KES 35,000,000.00
Customer Contribution	KES 9,999,997.00
Drawn Funds (D1)	KES 14,000,000.00

Drawn Funds (D2)	KES 11,000,000.00
Subtotal Drawn	KES 2,500,000.00

4. PROJECT PROGRESS

Works Complete	Slab is complete, flooring is already done
Works Ongoing	Construction of windows and doors
Materials Found on Site	Metal panels for the windows and doors
Defects Noted on Site	No defects
Drawdown Request No.	Dd 1221
Drawdown KES Amount	KES 10,000,000.00

Site Visit Objectives:

1. Almost Done
2. Everything looks good so far
3. 17 bags of cement, ballast, timber and tools

5. DOCUMENTS SUBMITTED

QS Valuation	Yes
Interim Certificate	Yes
Instruction Letter	Yes
Progress Report	Yes
Invoice	No

6. SIGN-OFF

Prepared By	Shallot Damary
Signature	ShallotD
Date	25 Feb 2026

' **Approved By: QS Officer**

Date: -

7. PROGRESS PHOTOS



Photo 1



Photo 2



Photo 3



Photo 4

8. MATERIALS ON SITE



Photo 1



Photo 2



Photo 3



Photo 4

9. DEFECTS NOTED



Photo 1



Photo 2



Photo 3



Photo 4