

Site Visit Call Report

Call Report No: CRN-034 | Status: **Rework**

1. CUSTOMER INFORMATION

Name of the customer:	Tsavo Constructors Ltd
Salaried/Consultancy/Business:	Business
Project Name:	Kisumu Business Complex
Date & time of site visit:	2026-03-16T11:23
Designation/name of person met:	Sir Charles Kamunya
Amounts Breakdown	
BQ amount:	KES 75,000,000.00
Construction loan amount:	KES 73,000,000.00
Customer's contribution:	KES 12,000,000.00
Drawdown Funds to Date:	
Drawdown 1:	23,000,000.00
Drawdown 2:	25,000,000.00
Sub-total:	KES 23,000,000.00
Undrawn funds to date:	KES 25,000,000.00

2. ADDITIONAL INFORMATION

Brief profile of the customer:	Company building a business complex
Details of the Site	
Exact location:	Spring Valley
House located along:	Spring Valley - Lower Kabete Road
Site Pin:	LR. 2021

Security details:	LR. 2021
Plot/LR No.:	LR 2021

3. PROJECT INFORMATION

Site Visit Objectives	
Objective 1: Progress	Done
Objective 2: Defects	Done
Objective 3: Materials	Done
Works Complete:	Flooring done. First to third floor done
Works Ongoing:	Fourth floor ongoing
Materials Found on Site:	Cement, ballast, bricks, sand
Defects Noted on Site:	None
Drawdown Request No.:	xxx
Drawdown KES Amount:	KES 32,000,000.00

4. DOCUMENTS SUBMITTED

QS Valuation	Yes
Interim Certificate	Yes
Customer Instruction Letter	Yes
Contractor's Progress Report	Yes
Contractor's Invoice	Yes




5. SIGN-OFF

Prepared By:	Michael Mwai
Signature:	M.Mwai
Date of Preparation:	17/03/2026

Authorised by:

Designation:

PROGRESS PHOTOS



MATERIALS ON SITE



DEFECTS NOTED ON SITE

