Site Visit Call Report

Call Report No: CRN-019 | Status: **Draft**

1. CUSTOMER INFORMATION

Name of the customer:	Steve Rodgers
Salaried/Consultancy/Business:	Salaried
Project Name:	Cold Pottery
Date & time of site visit:	2026-03-09T08:54
Designation/name of person met:	Joseph Mwende
Amounts Breakdown	
BQ amount:	KES 79,000,000.00
Construction loan amount:	KES 78,000,000.00
Customer's contribution:	KES 8,000,000.00
Drawdown Funds to Date:	
Drawdown 1:	25,000,000.00
Drawdown 2:	30,000,000.00
Sub-total:	**KES 55,000,000.00**
Undrawn funds to date:	**KES 23,000,000.00**

2. ADDITIONAL INFORMATION

Brief profile of the customer:	Customer wants funds for building a home
Details of the Site	
Exact location:	Makongeni
House located along:	Thika-Makongeni Rd
Site Pin:	23234

Security details:	23432
Plot/LR No.:	LR. 23432

3. PROJECT INFORMATION

Site Visit Objectives	
Objective 1: Progress	Done
Objective 2: Defects	Done
Objective 3: Materials	Yes
Works Complete:	Walls and floors
Works Ongoing:	Roofing
Materials Found on Site:	cement and sand
Defects Noted on Site:	None
Drawdown Request No.:	xxx
Drawdown KES Amount:	KES 15,000,000.00

4. DOCUMENTS SUBMITTED

QS Valuation	Yes
Interim Certificate	Yes
Customer Instruction Letter	Yes
Contractor's Progress Report	No
Contractor's Invoice	No

5. SIGN-OFF

Prepared By:	Shallot Damary
Signature:	Shallot
Date of Preparation:	04/03/2026

Authorised by:	Designation:

PROGRESS PHOTOS

MATERIALS ON SITE

DEFECTS NOTED ON SITE