

Site Visit Call Report

Call Report No: CRN-073 | Status: **Approved**

1. CUSTOMER INFORMATION

Name of the customer:	Jeniffer Chebet
Salaried/Consultancy/Business:	Business
Project Name:	Wabera Office Complex
Date & time of site visit:	6 May 2026, 12:27
Designation/name of the person met at the site:	Jeniffer Chebet
Amounts Breakdown	
BQ amount:	KES 25,600,000.00
Construction loan amount:	KES 25,600,000.00
Customer's contribution:	KES 5,000,000.00
Drawn Funds to Date:	
	D1: KES. 5,600,000.00
	D2: KES. 9,700,000.00
	D3: KES. 2,500,000.00
	Sub-total: KES. 17,800,000.00
Undrawn funds to date:	KES 7,800,000.00

2. ADDITIONAL INFORMATION

Brief profile of the customer/facility (Construction/Buy & Build/Equity Release):

Customer requesting funds to expand the business complex

Details of the Site

Exact location:	Wabera, Kabete
House located along:	Wabera Street
Site Pin:	—
Security details:	LR No: 1564
Plot / LR No.	1564

3. PROJECT INFORMATION

Site Visit Objectives	
Objective 1: Confirm progress on site and level of work done Foundation done Ground floor done First floor done	
Objective 2: Confirm status of the building including taking note of any visible defects None	
Objective 3: Take note of materials stored on site Sand Bricks Cement	
Works Complete	Foundation done Ground floor done First floor done
Works Ongoing	Second Floor done Tiles installation
Materials Found on Site	Cement Sand Ballast
Defects Noted on Site	None
Drawdown Request No.	xxxx
Drawdown KES Amount	KES 5,000,000.00

4. DOCUMENTS SUBMITTED


Document	Submitted
QS Valuation	Yes
Interim Certificate	Yes
Customer Instruction Letter	Yes
Contractor's Progress Report	No
Contractor's Invoice	No

5. SIGN-OFF

Prepared By	Shallot Damary
Signature	Shallot Damary
Date of Preparation	6 May 2026, 03:00

Authorised by:	Designation:
Joy Wambui	Quantity Surveyor

PROGRESS PHOTOS



MATERIALS ON SITE

