Site Visit Call Report

Call Report No: CRN-003 | Date: 09 Mar 2026 15:03

1. CUSTOMER INFORMATION

Call Report No.	CRN-003
Customer Name	Safari Cement
Customer Type	Business
Brief Profile	Company that makes cement requires funds to expand their factory and two storage warehouses
IBPS No.	111234
Customer Number	02456
Project Name	Lisa Homes

2. SITE VISIT DETAILS

Visit Date & Time	02 Mar 2026 17:11
Person Met at Site	Daniel Mwai Mwangi
Exact Location	By Pass
House Located Along	By Pass Junction
Site PIN	8989
Security Details	8989
Plot/LR No.	8989

3. FINANCIAL SUMMARY

BQ Amount	KES 150,000,000.00
Construction Loan Amount	KES 150,000,000.00
Customer Contribution	KES 10,000,000.00

Drawn Funds (D1)	KES 7,500,000.00
Drawn Funds (D2)	KES 25,000,000.00
Subtotal Drawn	KES 32,499,999.00

4. PROJECT PROGRESS

Works Complete	done
Works Ongoing	done
Materials Found on Site	done
Defects Noted on Site	none
Drawdown Request No.	8989
Drawdown KES Amount	KES 45,000,000.00

Site Visit Objectives:

1. done
2. done
3. done

5. DOCUMENTS SUBMITTED

QS Valuation	Yes
Interim Certificate	Yes
Instruction Letter	Yes
Progress Report	No
Invoice	No

6. SIGN-OFF

Prepared By	Shallot Damary
Signature	Shallot
Date	02 Mar 2026

' Approved By: QS Officer

Date: -

7. PROGRESS PHOTOS



Photo 1

8. MATERIALS ON SITE



Photo 1

9. DEFECTS NOTED



Photo 1