

Site Visit Call Report

Call Report No: CRN-011 | Status: **Approved**

1. CUSTOMER INFORMATION

Name of the customer:	Juma Mustafa
Salaried/Consultancy/Business:	Salaried
Project Name:	Kikapu Shopping Stall
Date & time of site visit:	2026-02-23T16:35
Designation/name of person met:	Fundi Joseph
Amounts Breakdown	
BQ amount:	KES 45,000,000.00
Construction loan amount:	KES 35,000,000.00
Customer's contribution:	KES 9,999,997.00
Drawdown Funds to Date:	
Sub-total:	KES 2,500,000.00
Undrawn funds to date:	KES 10,000,000.00

2. ADDITIONAL INFORMATION

Brief profile of the customer:	Customer want a house
Details of the Site	
Exact location:	Green House
House located along:	Green Valley Houses
Site Pin:	445-7890
Security details:	LR. No 6789
Plot/LR No.:	6789

3. PROJECT INFORMATION

Site Visit Objectives	
Objective 1: Progress	Almost Done
Objective 2: Defects	Everything looks good so far
Objective 3: Materials	17 bags of cement, ballast, timber and tools
Works Complete:	Slab is complete, flooring is already done
Works Ongoing:	Construction of windows and doors
Materials Found on Site:	Metal panels for the windows and doors
Defects Noted on Site:	No defects
Drawdown Request No.:	Dd 1221
Drawdown KES Amount:	KES 10,000,000.00

4. DOCUMENTS SUBMITTED

QS Valuation	Yes
Interim Certificate	Yes
Customer Instruction Letter	Yes
Contractor's Progress Report	Yes
Contractor's Invoice	No





5. SIGN-OFF





Prepared By:	Shallot Damary
Signature:	ShallotD
Date of Preparation:	25/02/2026

Authorised by:

Designation:

PROGRESS PHOTOS



MATERIALS ON SITE

DEFECTS NOTED ON SITE

