

Site Visit Call Report

Call Report No: CRN-037 | Status: **Draft**

1. CUSTOMER INFORMATION

Name of the customer:	Stephen Kipchoge Ruto
Salaried/Consultancy/Business:	Salaried
Project Name:	Farm House Construction
Date & time of site visit:	2026-03-25T08:39
Designation/name of person met:	Clients' Wife
Amounts Breakdown	
BQ amount:	KES 16,500,000.00
Construction loan amount:	KES 13,000,000.00
Customer's contribution:	KES 1,200,000.00
Drawdown Funds to Date:	
Drawdown 1:	5,600,000.00
Drawdown 2:	3,200,000.00
Drawdown 3:	2,000,000.00
Sub-total:	KES 11,300,000.00
Undrawn funds to date:	KES 2,200,000.00

2. ADDITIONAL INFORMATION

Brief profile of the customer:	Customer wants to build a mansion
Details of the Site	
Exact location:	Kilifi
House located along:	Bamburu Road

Site Pin:	XXXXX
Security details:	87907
Plot/LR No.:	87907

3. PROJECT INFORMATION

Site Visit Objectives	
Objective 1: Progress	Done
Objective 2: Defects	Done
Objective 3: Materials	Done
Works Complete:	Foundation Flooring Walls
Works Ongoing:	Roofing Surrounding compound
Materials Found on Site:	Sand Cement Wheelbarrow
Defects Noted on Site:	None
Drawdown Request No.:	xx
Drawdown KES Amount:	KES 1,750,000.00



4. DOCUMENTS SUBMITTED

QS Valuation	Yes
Interim Certificate	Yes
Customer Instruction Letter	Yes
Contractor's Progress Report	No
Contractor's Invoice	No



5. SIGN-OFF

Prepared By:	Shallot Damary
Signature:	Shallot
Date of Preparation:	25/03/2026

Authorised by:	Designation:

PROGRESS PHOTOS

MATERIALS ON SITE



DEFECTS NOTED ON SITE

