

Site Visit Call Report

Call Report No: CRN-052 | Status: **Approved**

1. CUSTOMER INFORMATION

Name of the customer:	Daniel Mutua Mwanzia
Salaried/Consultancy/Business:	Salaried
Project Name:	Residential Home
Date & time of site visit:	2026-04-17T17:46
Designation/name of person met:	Fundi Joseph
Amounts Breakdown	
BQ amount:	KES 7,000,000.00
Construction loan amount:	KES 7,000,000.00
Customer's contribution:	KES 1,500,000.00
Drawdown Funds to Date:	
Drawdown 1:	2,500,000.00
Drawdown 2:	1,500,000.00
Sub-total:	KES 2,500,000.00
Undrawn funds to date:	KES 3,000,000.00

2. ADDITIONAL INFORMATION

Brief profile of the customer:	Customer wants to build a home
Details of the Site	
Exact location:	Mwea - Kirinyaga Road
House located along:	Along Mwea Rice Factory
Site Pin:	-1.2852332987899602, 36.821636037346295

Security details:	12121
Plot/LR No.:	12121

3. PROJECT INFORMATION

Site Visit Objectives	
Objective 1: Progress	Foundation and ground walls complete
Objective 2: Defects	None
Objective 3: Materials	Cement, Sand, Ballast
Works Complete:	Foundation Flooring Walls
Works Ongoing:	First floor walls Door and windows installation
Materials Found on Site:	Cement, Ballast, sand, water
Defects Noted on Site:	None
Drawdown Request No.:	xxxx
Drawdown KES Amount:	KES 1,500,000.00

4. DOCUMENTS SUBMITTED

QS Valuation	Yes
Interim Certificate	Yes
Customer Instruction Letter	Yes
Contractor's Progress Report	No
Contractor's Invoice	No

5. SIGN-OFF

Prepared By:	Michael Mwai
Signature:	Michael Mwai

Date of Preparation:	17/04/2026
----------------------	------------

Authorised by:	Designation:

PROGRESS PHOTOS

MATERIALS ON SITE