

Site Visit Call Report

Call Report No: CRN-070 | Status: **QS Review**

1. CUSTOMER INFORMATION

Name of the customer:	Alex Njuguna Mumo
Salaried/Consultancy/Business:	Business
Project Name:	Home Build
Date & time of site visit:	2026-05-05T12:07
Designation/name of person met:	Wife of the customer
Amounts Breakdown	
BQ amount:	KES 7,800,000.00
Construction loan amount:	KES 7,800,000.00
Customer's contribution:	KES 800,000.00
Drawdown Funds to Date:	
Drawdown 1:	1,500,000.00
Sub-total:	KES 1,500,000.00
Undrawn funds to date:	KES 6,300,000.00

2. ADDITIONAL INFORMATION

Brief profile of the customer:	Customer wants to build a home mansio
Details of the Site	
Exact location:	Kikuyu
House located along:	Along Kikuyu Market
Site Pin:	None
Security details:	2323

Plot/LR No.:	None
--------------	------

3. PROJECT INFORMATION

Site Visit Objectives	
Objective 1: Progress	Flooring done
Objective 2: Defects	None
Objective 3: Materials	cement, bricks, sand, ballast
Works Complete:	First Floor
Works Ongoing:	Second floor
Materials Found on Site:	Cement, bricks, sand, ballast
Defects Noted on Site:	None
Drawdown Request No.:	xxx
Drawdown KES Amount:	KES 2,300,000.00

4. DOCUMENTS SUBMITTED

QS Valuation	Yes
Interim Certificate	Yes
Customer Instruction Letter	Yes
Contractor's Progress Report	No
Contractor's Invoice	No

5. SIGN-OFF

Prepared By:	Shallot Damary
Signature:	Shallot Damary
Date of Preparation:	05/05/2026

Authorised by:

Designation:

PROGRESS PHOTOS

MATERIALS ON SITE