

Site Visit Call Report

Call Report No: CRN-087 | Status: **Draft**

1. CUSTOMER INFORMATION

Name of the customer:	Francis Mwita Mwangi
Salaried/Consultancy/Business:	Salaried
Project Name:	Residential Construction
Date & time of site visit:	4 Jun 2026, 10:21
Designation/name of the person met at the site:	Clients' wife
Amounts Breakdown	
BQ amount:	KES 29,800,000.00
Construction loan amount:	KES 19,700,000.00
Customer's contribution:	KES 1,080,000.00
Drawn Funds to Date:	
	D1: KES. 0.00
	Sub-total: KES. 0.00
Undrawn funds to date:	KES 0.00

2. ADDITIONAL INFORMATION

Brief profile of the customer/facility (Construction/Buy & Build/Equity Release):	
Proposed residential construction	
Details of the Site	
Exact location:	Highpoint, Juja
House located along:	Thika Superhighway
Site Pin:	-1.28534328, 36.82174904
Security details:	2733
Plot / LR No.	2733

3. PROJECT INFORMATION

Site Visit Objectives	
Objective 1: Confirm progress on site and level of work done	
Done	
Objective 2: Confirm status of the building including taking note of any visible defects	
Done	
Objective 3: Take note of materials stored on site	
Done	
Works Complete	External render work Internal plaster work Wardrobe plinth work
Works Ongoing	None
Materials Found on Site	Crown Paint
Defects Noted on Site	None
Drawdown Request No.	xxx
Drawdown KES Amount	KES 245,000.00

4. DOCUMENTS SUBMITTED

Document	Submitted
QS Valuation	Yes
Interim Certificate	Yes
Customer Instruction Letter	Yes
Contractor's Progress Report	No
Contractor's Invoice	No


5. SIGN-OFF

Prepared By	Shallot Damary
Signature	S.D
Date of Preparation	3 Jun 2026, 03:00

Document Status:

This is an unofficial draft report

PROGRESS PHOTOS



MATERIALS ON SITE

